

Remove the jumper.
Force to pins 2 and 5.
Sense to pins 3 and 4.
Set 3.3 V, limit 50 mA.