Ethernet In Stepdown **Ethernet Out USB** Out J1 CRJ032-1-TH TX+ TX-RX-J2 U1]+24V / CRJ032-1-TH OUT-USB_A_2.0 D+ GND1 GND TX-GND GND1 TX+