

Visual vehicle inspection report

Findings at the time of inspection. See the overview for priorities and next steps.

VEHICLE		REPORT REFERENCE	
2021 Sample Touring Sedan		PPI-DEMO-2026-002 / v1	
VIN	ODOMETER	INSPECTION DATE	
SAMPLE - NO REAL VIN	48,210 mi	Sep 22, 2026	

✓ Checked

⚠ Monitor

⚠ Service recommended

🔴 Urgent

❓ Unknown / not inspected

N/A = not applicable. A missing or unavailable check is never marked as checked.

TIRES & WHEELS

Four corners. Measured values and visible condition.

Placard reference: 225/50R17 | F/R 34 psi cold

FRONT LEFT 🔴 Urgent		FRONT RIGHT ✓ Checked	
Tread	5/32 in 4.0 mm	Tread	6/32 in 4.8 mm
Pressure	34 psi (cold)	Pressure	34 psi (cold)
Tire size	225/50R17	Tire size	225/50R17
Load / speed / DOT	98 / V / 0224	Load / speed / DOT	98 / V / 0224
Cracking	None	Cracking	None
Uneven wear	Even	Uneven wear	Even
Tire / rim damage	Object / rash	Tire / rim damage	None / none
Placard fitment	Matches placard	Placard fitment	Matches placard
REAR LEFT ⚠ Service*		REAR RIGHT ✓ Checked	
Tread	Unavailable	Tread	6/32 in 4.8 mm
Pressure	Unavailable	Pressure	34 psi (cold)
Tire size	215/50R17	Tire size	225/50R17
Load / speed / DOT	98 / V / 0519	Load / speed / DOT	98 / V / 0224
Cracking	Significant	Cracking	None
Uneven wear	Mild uneven	Uneven wear	Even
Tire / rim damage	None / none	Tire / rim damage	None / none
Placard fitment	Differs from placard	Placard fitment	Matches placard

* Partial: tread or pressure unavailable; see the tire entries and overview.

BODY DAMAGE MAP

FRONT

1

2

⚠ 1 Left front fender

Shallow dent; finish intact.

⚠ 2 Right front door

Surface scratch; no bare metal.

Vehicle left/right is viewed from the driver's seat. Bumpers outside this scope.

INSPECTOR CERTIFICATION

☒ I certify that the observations and answers in this inspection are accurate to the best of my knowledge and ability.

Alex Morgan | Self-inspector (fictional)

Sep 22, 2026 11:10 ET | Sample only

Inspection overview

Condition, context and practical next steps, organized by inspection category.

VEHICLE 2021 Sample Touring Sedan		REPORT REFERENCE PPI-DEMO-2026-002 / v1	
VIN SAMPLE - NO REAL VIN	ODOMETER 48,210 mi	INSPECTION DATE Sep 22, 2026	

OBSERVATIONS / SIGNIFICANCE / NEXT STEPS

PRIORITY ACTIONS

Replace the front-left tire: a foreign object is confirmed. Rear-left cracking warrants replacement; its tread and pressure remain unmeasured.

TIRES

A foreign object is confirmed in the front-left tire. Rear-left cracking is significant; its tread was not measured.

Replace front-left tire. Rear-left replacement recommended; verify fitment.

WHEELS

Cosmetic curb rash was recorded on the front-left rim. No structural damage was reported on the visible surfaces.

Cosmetic repair is optional. Investigate any new vibration or air loss.

BODY DAMAGE

Left front fender dent [B1] and right front door scratch [B2]. The mapped damage is cosmetic.

Use map markers 1 and 2 to locate recorded damage.

FITMENT

Rear-left tire size differs from the confirmed rear placard specification. No approved alternative was documented.

Fit the specified tire or verify an approved alternative.

UNAVAILABLE MEASUREMENTS

The self-inspector could not measure rear-left tread or pressure. The other three tire readings were recorded.

Measure before relying on that tire condition assessment.

INSPECTION SCOPE

This inspection covers tires, wheels and in-scope cosmetic body areas. Mechanical systems and bumpers are outside scope.

Choose Complete Inspection for the broader checklist.

SCOPE & EVIDENCE

Self-inspection. Rear-left tread and pressure were unavailable; no measurement was inferred from a photo. Brakes, engine, interior, road test and bumpers are outside the Dents & Tires scope.

Full findings and uploaded photos are available through the optional evidence appendix.