

Full findings & photo evidence

2021 Sample Touring Sedan

PPI-DEMO-2026-001 / v1 | Sep 22, 2026 | Jordan Lee | Technician (fictional)

Complete finding record

 T1 | Front-left tire - foreign object

A foreign object was confirmed in the tread. Replacement is required under this report program policy, whether or not the tire retains pressure. Measured tread: 5/32 in (3.96875 mm before display rounding). Pressure: 34 psi, cold. Rim: cosmetic curb rash. Evidence E01.

 T2 | Rear-left tire - cracking and fitment

Significant visible cracking was confirmed. Replacement is recommended. Installed size 215/50R17 differs from the confirmed 225/50R17 rear placard reference; verify fitment before replacement. Tread: 3/32 in (2.38125 mm). DOT: 0519. Mild uneven wear suggests a follow-up alignment/pressure review; it does not establish suspension failure. Evidence E02.

 B1 | Left front fender - damage marker 1

Shallow dent with intact finish, recorded as cosmetic damage. Consider cosmetic repair if desired. Evidence E03.

 B2 | Right front door - damage marker 2

Surface scratch without exposed metal. Cosmetic repair is optional. No photo was supplied in this fictional example.

 C01 | Identity / title / history

Recorded checks in this group had no reported concern. This fictional fixture is for layout review only.

 C02 | Paint / body

See B1 and B2 for complete recorded body observations.

 C03 | Windshield

Recorded checks in this group had no reported concern. This fictional fixture is for layout review only.

 C04 | Lamps / lenses

Recorded checks in this group had no reported concern. This fictional fixture is for layout review only.

 C05 | Seats / upholstery

Recorded checks in this group had no reported concern. This fictional fixture is for layout review only.

 C06 | Carpet / mats

Recorded checks in this group had no reported concern. This fictional fixture is for layout review only.

Full findings & photo evidence

2021 Sample Touring Sedan

PPI-DEMO-2026-001 / v1 | Sep 22, 2026 | Jordan Lee | Technician (fictional)

Complete finding record

✔ C07 | Interior odors

Recorded checks in this group had no reported concern. This fictional fixture is for layout review only.

✔ C08 | Windows / locks

Recorded checks in this group had no reported concern. This fictional fixture is for layout review only.

✔ C09 | Climate controls

Recorded checks in this group had no reported concern. This fictional fixture is for layout review only.

✔ C10 | Other electrical

Recorded checks in this group had no reported concern. This fictional fixture is for layout review only.

✔ C11 | Starting / transmission

Recorded checks in this group had no reported concern. This fictional fixture is for layout review only.

✔ C12 | Road-test braking

Recorded checks in this group had no reported concern. This fictional fixture is for layout review only.

✔ C13 | Road vibration / noise

Recorded checks in this group had no reported concern. This fictional fixture is for layout review only.

✔ C14 | Warning lamps

Recorded checks in this group had no reported concern. This fictional fixture is for layout review only.

✔ C15 | Diagnostic scan

Recorded checks in this group had no reported concern. This fictional fixture is for layout review only.

✔ C16 | Engine-bay leaks

Recorded checks in this group had no reported concern. This fictional fixture is for layout review only.

✔ C17 | Idle / engine

Recorded checks in this group had no reported concern. This fictional fixture is for layout review only.

Full findings & photo evidence

2021 Sample Touring Sedan

PPI-DEMO-2026-001 / v1 | Sep 22, 2026 | Jordan Lee | Technician (fictional)

Complete finding record

✔ C18 | Drive belt

Recorded checks in this group had no reported concern. This fictional fixture is for layout review only.

✔ C19 | Battery terminals

Recorded checks in this group had no reported concern. This fictional fixture is for layout review only.

❓ C20 | Fluids

Oil, coolant and brake-fluid observations completed; transmission fluid unavailable. No green status is assigned to the unavailable observation.

✔ C21 | Pad estimate / rotors

Pad life estimated at 50-75%; visible rotors appeared normal. Optional pad-thickness measurement was not performed. This completed row covers the reported estimate and visible rotor observation only.

✔ C22 | Steering / tracking

Recorded checks in this group had no reported concern. This fictional fixture is for layout review only.

✔ C23 | Suspension / ride

Recorded checks in this group had no reported concern. This fictional fixture is for layout review only.

❓ C24 | Underbody

Full underbody access was unavailable. A complete underside check remains outstanding.

✔ C25 | Modifications

Recorded checks in this group had no reported concern. This fictional fixture is for layout review only.

✔ Front Right tire - recorded measurements

Tread 6/32 in (4.7625 mm), cold pressure 34 psi, tire size 225/50R17, load index 98, speed rating V, DOT 0224. No visible cracking, uneven wear, tire damage or wheel damage recorded; size matches the confirmed reference.

✔ Rear Right tire - recorded measurements

Tread 6/32 in (4.7625 mm), cold pressure 34 psi, tire size 225/50R17, load index 98, speed rating V, DOT 0224. No visible cracking, uneven wear, tire damage or wheel damage recorded; size matches the confirmed reference.

Full findings & photo evidence

2021 Sample Touring Sedan

PPI-DEMO-2026-001 / v1 | Sep 22, 2026 | Jordan Lee | Technician (fictional)

Photo evidence record

E01 | Front-left tire - foreign object

T1 | tires.front_left.damage | tread close-up

PHOTO PLACEMENT EXAMPLE

No actual inspection photo supplied
The uploaded image fills this area without cropping.

CAPTION / FINDING CONTEXT

In a completed inspection, this page displays the original uploaded close-up associated with the confirmed foreign object. A retained-pressure observation does not change the report policy: replacement is required.

Evidence state: layout placeholder; no actual photo

Full findings & photo evidence

2021 Sample Touring Sedan

PPI-DEMO-2026-001 / v1 | Sep 22, 2026 | Jordan Lee | Technician (fictional)

Photo evidence record

E02 | Rear-left tire - cracking and marking

T2 | tires.rear_left.cracking / size | sidewall view

PHOTO PLACEMENT EXAMPLE

No actual inspection photo supplied
The uploaded image fills this area without cropping.

CAPTION / FINDING CONTEXT

This slot demonstrates a sidewall evidence record. The inspector confirms visible cracking, size and DOT markings separately. The original image is retained even if extraction fails.

Evidence state: layout placeholder; no actual photo

Full findings & photo evidence

2021 Sample Touring Sedan

PPI-DEMO-2026-001 / v1 | Sep 22, 2026 | Jordan Lee | Technician (fictional)

Photo evidence record

E03 | Left front fender - shallow dent

B1 | body.left_front_fender.condition | context view

PHOTO PLACEMENT EXAMPLE

No actual inspection photo supplied
The uploaded image fills this area without cropping.

CAPTION / FINDING CONTEXT

This context image is associated with damage-map marker 1. Every uploaded photo receives a manifest entry, including additional views not selected by a model.

Evidence state: layout placeholder; no actual photo