```
"Ethernet1/1": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 1000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
    "in_discard": 0,
    "in_errors": 0,
    "in_if_down_drop": 0,
    "in_ignored": 0,
    "in_jumbo_packets": 0,
    "in_mac_pause_frames": 0,
    "in_multicast_pkts": 0,
    "in_no_buffer": 0,
    "in_octets": 0,
    "in_overrun": 0,
    "in_oversize_frame": 0,
    "in_pkts": 0,
    "in_runts": 0,
    "in_short_frame": 0,
    "in_storm_suppression_packets": 0,
```

{

"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {
"in_rate": 0,
"in_rate_bps": 0,
"in_rate_pkts": 0,
"in_rate_pps": 0,

"in_underrun": 0,

```
"load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
    "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"description": "VPC Peer Link",
"duplex_mode": "full",
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 4,
"last_link_flapped": "02:41:34",
"link_state": "up",
```

```
"mac_address": "5254.000d.e744",
  "medium": "broadcast",
  "mtu": 9216,
  "oper_status": "up",
  "phys_address": "5254.000d.e744",
  "port_channel": {
    "port_channel_int": "Port-channel1",
    "port_channel_member": true
  "port_mode": "trunk",
  "port_speed": "1000",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/10": {
  "admin_state": "down",
  "auto_mdix": "off",
  "bandwidth": 10000000,
   "beacon": "off",
   "counters": {
     "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
```

"in_discard": 0,
"in_errors": 0,
"in_if_down_drop": 0,
"in_ignored": 0,
"in_jumbo_packets": 0,
"in_mac_pause_frames": 0,
"in_multicast_pkts": 0,
"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,

```
"out_errors": 0,
  "out_jumbo_packets": 0,
  "out_late_collision": 0,
  "out_lost_carrier": 0,
  "out_mac_pause_frames": 0,
  "out_multicast_pkts": 0,
  "out_no_carrier": 0,
  "out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
    "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
```

```
"description": "to",
"efficient_ethernet": "n/a",
"enabled": false,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 1,
"last_link_flapped": "02:41:51",
"link_state": "down",
"mac_address": "5254.000d.e74d",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e74d",
"port_channel": {
  "port_channel_member": false
},
"port_mode": "access",
"reliability": "255/255",
"rxload": "1/255",
"switchport_monitor": "off",
```

```
"txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/100": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
     "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
     "in_no_buffer": 0,
     "in_octets": 0,
     "in_overrun": 0,
     "in_oversize_frame": 0,
     "in_pkts": 0,
     "in_runts": 0,
     "in_short_frame": 0,
```

"in_underrun": 0,	
"in_unicast_pkts": 0,	
"in_unknown_protos": 0,	
"in_watchdog": 0,	
"in_with_dribble": 0,	
"last_clear": "never",	
"out_babble": 0,	
"out_broadcast_pkts": 0,	
"out_collision": 0,	
"out_deferred": 0,	
"out_discard": 0,	
"out_errors": 0,	
"out_jumbo_packets": 0,	
"out_late_collision": 0,	
"out_lost_carrier": 0,	
"out_mac_pause_frames": 0,	
"out_multicast_pkts": 0,	
"out_no_carrier": 0,	
"out_octets": 0,	
"out_pkts": 0,	
"out_unicast_pkts": 0,	
"rate": {	
"in_rate": 0,	
"in_rate_bps": 0,	
"in_rate_pkts": 0,	

"in_storm_suppression_packets": 0,

```
"in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e7a7",
```

```
"mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e7a7",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/101": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
    "in_discard": 0,
    "in_errors": 0,
    "in_if_down_drop": 0,
```

"medium": "broadcast",

"in_ignored": 0,
"in_jumbo_packets": 0,
"in_mac_pause_frames": 0,
"in_multicast_pkts": 0,
"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,

```
"out_lost_carrier": 0,
  "out_mac_pause_frames": 0,
  "out_multicast_pkts": 0,
  "out_no_carrier": 0,
  "out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
```

```
"encapsulation": "arpa"
  },
  "ethertype": "0x8100",
  "flow_control": {
    "receive": false,
     "send": false
  },
  "interface_reset": 0,
   "last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e7a8",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e7a8",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
   "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/102": {
```

"admin_state": "up",	
"auto_mdix": "off",	
"bandwidth": 10000000,	
"beacon": "off",	
"counters": {	
"in_bad_etype_drop": 0,	
"in_broadcast_pkts": 0,	
"in_crc_errors": 0,	
"in_discard": 0,	
"in_errors": 0,	
"in_if_down_drop": 0,	
"in_ignored": 0,	
"in_jumbo_packets": 0,	
"in_mac_pause_frames": 0,	
"in_multicast_pkts": 0,	
"in_no_buffer": 0,	
"in_octets": 0,	
"in_overrun": 0,	
"in_oversize_frame": 0,	
"in_pkts": 0,	
"in_runts": 0,	
"in_short_frame": 0,	
"in_storm_suppression_packets": 0,	
"in_underrun": 0,	
"in_unicast_pkts": 0,	
"in_unknown_protos": 0,	

in_with_dribble*: 0,
last_clear": "never",
out_babble*: 0,
out_broadcast_pkts": 0,
out_collision": 0,
out_deferred": 0,
out_discard": 0,
out_errors": 0,
out_jumbo_packets": 0,
out_late_collision": 0,
out_lost_carrier": 0,
out_mac_pause_frames": 0,
out_multicast_pkts*: 0,
out_no_carrier": 0,
out_octets": 0,
out_pkts": 0,
out_unicast_pkts": 0,
rate": {
"in_rate": 0,
"in_rate_bps": 0,
"in_rate_pkts": 0,
"in_rate_pps": 0,
"load_interval": 300,
"out_rate": 0,
"out_rate_bps": 0,

"in_watchdog": 0,

```
"out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e7a9",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e7a9",
```

```
"port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport\_monitor": "off",\\
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/103": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
```

"port_channel": {

"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0, "out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,

```
"out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
```

```
"receive": false,
    "send": false
  },
  "interface_reset": 0,
  "last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e7aa",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e7aa",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/104": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
```

"counters": {		
"in_bad_etype_drop": 0,		
"in_broadcast_pkts": 0,		
"in_crc_errors": 0,		
"in_discard": 0,		
"in_errors": 0,		
"in_if_down_drop": 0,		
"in_ignored": 0,		
"in_jumbo_packets": 0,		
"in_mac_pause_frames": 0,		
"in_multicast_pkts": 0,		
"in_no_buffer": 0,		
"in_octets": 0,		
"in_overrun": 0,		
"in_oversize_frame": 0,		
"in_pkts": 0,		
"in_runts": 0,		
"in_short_frame": 0,		
"in_storm_suppression_packets": 0,		
"in_underrun": 0,		
"in_unicast_pkts": 0,		
"in_unknown_protos": 0,		
"in_watchdog": 0,		
"in_with_dribble": 0,		
"last_clear": "never",		
"out_babble": 0,		

```
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {
  "in_rate": 0,
  "in_rate_bps": 0,
  "in_rate_pkts": 0,
  "in_rate_pps": 0,
  "load_interval": 300,
  "out_rate": 0,
  "out_rate_bps": 0,
  "out_rate_pkts": 0,
  "out_rate_pps": 0
},
"rx": true,
```

"out_broadcast_pkts": 0,

```
"tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e7ab",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e7ab",
"port_channel": {
  "port_channel_member": false
},
"port_mode": "access",
```

```
"reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/105": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
   "counters": {
     "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
     "in_no_buffer": 0,
     "in_octets": 0,
     "in_overrun": 0,
     "in_oversize_frame": 0,
```

"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {

```
"in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
"interface_reset": 0,
```

},

```
"last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e7ac",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e7ac",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/106": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
```

"in_discard": 0,
"in_errors": 0,
"in_if_down_drop": 0,
"in_ignored": 0,
"in_jumbo_packets": 0,
"in_mac_pause_frames": 0,
"in_multicast_pkts": 0,
"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,

```
"out_errors": 0,
  "out_jumbo_packets": 0,
  "out_late_collision": 0,
  "out_lost_carrier": 0,
  "out_mac_pause_frames": 0,
  "out_multicast_pkts": 0,
  "out_no_carrier": 0,
  "out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
    "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
```

```
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e7ad",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e7ad",
"port_channel": {
  "port_channel_member": false
},
"port_mode": "access",
"reliability": "255/255",
"rxload": "1/255",
"switchport_monitor": "off",
"txload": "1/255",
```

```
},
"Ethernet1/107": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
     "in_no_buffer": 0,
     "in_octets": 0,
     "in_overrun": 0,
     "in_oversize_frame": 0,
     "in_pkts": 0,
     "in_runts": 0,
     "in_short_frame": 0,
     "in_storm_suppression_packets": 0,
```

"types": "100/1000/10000 Ethernet"

"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {
"in_rate": 0,
"in_rate_bps": 0,
"in_rate_pkts": 0,
"in_rate_pps": 0,

"in_underrun": 0,

```
"load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
    "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e7ae",
"medium": "broadcast",
```

```
"oper_status": "down",
  "phys_address": "5254.000d.e7ae",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/108": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
    "in_discard": 0,
    "in_errors": 0,
    "in_if_down_drop": 0,
    "in_ignored": 0,
```

"mtu": 1500,

"in_jumbo_packets": 0,
"in_mac_pause_frames": 0,
"in_multicast_pkts": 0,
"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,

```
"out_multicast_pkts": 0,
  "out_no_carrier": 0,
  "out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
    "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
```

"out_mac_pause_frames": 0,

```
},
  "ethertype": "0x8100",
  "flow_control": {
    "receive": false,
    "send": false
  },
  "interface_reset": 0,
  "last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e7af",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e7af",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/109": {
  "admin_state": "up",
```

"auto_mdix": "off",
"bandwidth": 10000000,
"beacon": "off",
"counters": {
"in_bad_etype_drop": 0,
"in_broadcast_pkts": 0,
"in_crc_errors": 0,
"in_discard": 0,
"in_errors": 0,
"in_if_down_drop": 0,
"in_ignored": 0,
"in_jumbo_packets": 0,
"in_mac_pause_frames": 0,
"in_multicast_pkts": 0,
"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0, "in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,

"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0, "out_unicast_pkts": 0,
"rate": {
"in_rate": 0,
"in_rate_bps": 0,
"in_rate_pkts": 0,
"in_rate_pps": 0,
"load_interval": 300,
"out_rate": 0,
"out_rate_bps": 0,
"out_rate_pkts": 0,

```
"out_rate_pps": 0
  },
  "rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e7b0",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e7b0",
"port_channel": {
```

```
"port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/11": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 1000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
    "in_discard": 0,
    "in_errors": 0,
    "in_if_down_drop": 0,
    "in_ignored": 0,
    "in_jumbo_packets": 0,
    "in_mac_pause_frames": 0,
    "in_multicast_pkts": 0,
    "in_no_buffer": 0,
```

in_overrun": 0,
in_oversize_frame": 0,
in_pkts": 0,
in_runts": 0,
in_short_frame": 0,
in_storm_suppression_packets": 0,
in_underrun": 0,
in_unicast_pkts": 0,
in_unknown_protos": 0,
in_watchdog": 0,
in_with_dribble*: 0,
last_clear": "never",
out_babble*: 0,
out_broadcast_pkts": 0,
out_collision": 0,
out_deferred": 0,
out_discard": 0,
out_errors": 0,
out_jumbo_packets": 0,
out_late_collision": 0,
out_lost_carrier": 0,
out_mac_pause_frames": 0,
out_multicast_pkts*: 0,
out_no_carrier": 0,
out_octets": 0,

"in_octets": 0,

```
"out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"description": "Link to inside-host01",
"duplex_mode": "full",
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
```

```
"flow_control": {
    "receive": false,
    "send": false
  },
  "interface_reset": 2,
  "last_link_flapped": "02:41:51",
  "link_state": "up",
  "mac_address": "5254.000d.e74e",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "up",
  "phys_address": "5254.000d.e74e",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "port_speed": "1000",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/110": {
  "admin_state": "up",
  "auto_mdix": "off",
```

"bandwidth": 10000000,
"beacon": "off",
"counters": {
"in_bad_etype_drop": 0,
"in_broadcast_pkts": 0,
"in_crc_errors": 0,
"in_discard": 0,
"in_errors": 0,
"in_if_down_drop": 0,
"in_ignored": 0,
"in_jumbo_packets": 0,
"in_mac_pause_frames": 0,
"in_multicast_pkts": 0,
"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0, "in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,

out_babble*: 0,
out_broadcast_pkts": 0,
out_collision": 0,
out_deferred": 0,
out_discard": 0,
out_errors*: 0,
out_jumbo_packets": 0,
out_late_collision*: 0,
out_lost_carrier": 0,
out_mac_pause_frames": 0,
out_multicast_pkts*: 0,
out_no_carrier": 0,
out_octets": 0,
out_pkts*: 0,
out_unicast_pkts*: 0,
rate": {
"in_rate": 0,
"in_rate_bps": 0,
"in_rate_pkts": 0,
"in_rate_pps": 0,
"load_interval": 300,
"out_rate": 0,
"out_rate_bps": 0,
"out_rate_pkts": 0,
"out_rate_pps": 0

"last_clear": "never",

```
},
  "rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e7b1",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e7b1",
"port_channel": {
  "port_channel_member": false
```

```
},
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport\_monitor" : "off",\\
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/111": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
     "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
     "in_no_buffer": 0,
     "in_octets": 0,
```

"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,

"in_overrun": 0,

```
"out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
```

```
"interface_reset": 0,
  "last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e7b2",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e7b2",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/112": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
```

in_crc_errors": 0,	
in_discard": 0,	
in_errors*: 0,	
in_if_down_drop": 0,	
in_ignored": 0,	
in_jumbo_packets": 0,	
in_mac_pause_frames": 0,	
in_multicast_pkts*: 0,	
in_no_buffer": 0,	
in_octets": 0,	
in_overrun": 0,	
in_oversize_frame": 0,	
in_pkts": 0,	
in_runts": 0,	
in_short_frame": 0,	
in_storm_suppression_packets": 0,	
in_underrun": 0,	
in_unicast_pkts": 0,	
in_unknown_protos": 0,	
in_watchdog": 0,	
in_with_dribble": 0,	
last_clear": "never",	
but_babble": 0,	
out_broadcast_pkts": 0,	
out_collision": 0,	

"in_broadcast_pkts": 0,

```
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {
  "in_rate": 0,
  "in_rate_bps": 0,
  "in_rate_pkts": 0,
  "in_rate_pps": 0,
  "load_interval": 300,
  "out_rate": 0,
  "out_rate_bps": 0,
  "out_rate_pkts": 0,
  "out_rate_pps": 0
},
"rx": true,
"tx": true
```

```
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e7b3",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e7b3",
"port_channel": {
  "port_channel_member": false
},
"port_mode": "access",
"reliability": "255/255",
"rxload": "1/255",
```

```
"switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/113": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
     "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
     "in_no_buffer": 0,
     "in_octets": 0,
     "in_overrun": 0,
     "in_oversize_frame": 0,
     "in_pkts": 0,
     "in_runts": 0,
```

"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {
"in_rate": 0,
"in_rate_bps": 0,

"in_short_frame": 0,

```
"in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
```

```
"medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e7b4",
  "port_channel": {
    "port_channel_member": false
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/114": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
    "in_discard": 0,
    "in_errors": 0,
```

"mac_address": "5254.000d.e7b4",

in_ignored": 0,
in_jumbo_packets": 0,
in_mac_pause_frames": 0,
in_multicast_pkts": 0,
in_no_buffer": 0,
in_octets": 0,
in_overrun": 0,
in_oversize_frame": 0,
in_pkts": 0,
in_runts": 0,
in_short_frame": 0,
in_storm_suppression_packets": 0,
in_underrun": 0,
in_unicast_pkts": 0,
in_unknown_protos": 0,
in_watchdog": 0,
in_with_dribble": 0,
last_clear": "never",
out_babble": 0,
out_broadcast_pkts": 0,
out_collision": 0,
out_deferred": 0,
out_discard": 0,
out_errors": 0,
out_jumbo_packets*: 0,

"in_if_down_drop": 0,

```
"out_late_collision": 0,
  "out_lost_carrier": 0,
  "out_mac_pause_frames": 0,
  "out_multicast_pkts": 0,
  "out_no_carrier": 0,
  "out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
```

```
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e7b5",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e7b5",
"port_channel": {
  "port_channel_member": false
"port_mode": "access",
"reliability": "255/255",
"rxload": "1/255",
"switchport_monitor": "off",
"txload": "1/255",
"types": "100/1000/10000 Ethernet"
```

"Ethernet1/115": {	
"admin_state": "up",	
"auto_mdix": "off",	
"bandwidth": 10000000,	
"beacon": "off",	
"counters": {	
"in_bad_etype_drop": 0,	
"in_broadcast_pkts": 0,	
"in_crc_errors": 0,	
"in_discard": 0,	
"in_errors": 0,	
"in_if_down_drop": 0,	
"in_ignored": 0,	
"in_jumbo_packets": 0,	
"in_mac_pause_frames": 0,	
"in_multicast_pkts": 0,	
"in_no_buffer": 0,	
"in_octets": 0,	
"in_overrun": 0,	
"in_oversize_frame": 0,	
"in_pkts": 0,	
"in_runts": 0,	
"in_short_frame": 0,	
"in_storm_suppression_packets": 0,	
"in_underrun": 0,	

"in_unicast_pkts": 0,

"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {
"in_rate": 0,
"in_rate_bps": 0,
"in_rate_pkts": 0,
"in_rate_pps": 0,
"load_interval": 300,
"out_rate": 0,

"in_unknown_protos": 0,

```
"out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e7b6",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
```

```
"phys_address": "5254.000d.e7b6",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/116": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
```

"in_multicast_pkts": 0,
"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,

```
"out_no_carrier": 0,
  "out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
```

```
"flow_control": {
    "receive": false,
    "send": false
  },
  "interface_reset": 0,
  "last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e7b7",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e7b7",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/117": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
```

"beacon": "off",	
"counters": {	
"in_bad_etype_drop": 0,	
"in_broadcast_pkts": 0,	
"in_crc_errors": 0,	
"in_discard": 0,	
"in_errors": 0,	
"in_if_down_drop": 0,	
"in_ignored": 0,	
"in_jumbo_packets": 0,	
"in_mac_pause_frames": 0,	
"in_multicast_pkts": 0,	
"in_no_buffer": 0,	
"in_octets": 0,	
"in_overrun": 0,	
"in_oversize_frame": 0,	
"in_pkts": 0,	
"in_runts": 0,	
"in_short_frame": 0,	
"in_storm_suppression_packets": 0,	
"in_underrun": 0,	
"in_unicast_pkts": 0,	
"in_unknown_protos": 0,	
"in_watchdog": 0,	
"in_with_dribble": 0,	
"last_clear": "never",	

```
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {
  "in_rate": 0,
  "in_rate_bps": 0,
  "in_rate_pkts": 0,
  "in_rate_pps": 0,
   "load_interval": 300,
  "out_rate": 0,
  "out_rate_bps": 0,
  "out_rate_pkts": 0,
  "out_rate_pps": 0
},
```

"out_babble": 0,

```
"rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e7b8",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e7b8",
"port_channel": {
  "port_channel_member": false
},
```

```
"port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/118": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
     "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
     "in_no_buffer": 0,
     "in_octets": 0,
     "in_overrun": 0,
```

"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,

"in_oversize_frame": 0,

```
"rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
```

},

```
"last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e7b9",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e7b9",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/119": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in\_bad\_etype\_drop" \colon 0,
    "in_broadcast_pkts": 0,
```

"interface_reset": 0,

m_oto_onoto . v,
"in_discard": 0,
"in_errors": 0,
"in_if_down_drop": 0,
"in_ignored": 0,
"in_jumbo_packets": 0,
"in_mac_pause_frames": 0,
"in_multicast_pkts": 0,
"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,

```
"out_errors": 0,
  "out_jumbo_packets": 0,
  "out_late_collision": 0,
  "out_lost_carrier": 0,
  "out_mac_pause_frames": 0,
  "out_multicast_pkts": 0,
  "out_no_carrier": 0,
  "out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
```

"out_discard": 0,

```
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e7ba",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e7ba",
"port_channel": {
  "port_channel_member": false
},
"port_mode": "access",
"reliability": "255/255",
"rxload": "1/255",
"switchport_monitor": "off",
```

```
"txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/12": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
     "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
     "in_no_buffer": 0,
     "in_octets": 0,
     "in_overrun": 0,
     "in_oversize_frame": 0,
     "in_pkts": 0,
     "in_runts": 0,
     "in_short_frame": 0,
```

"in_underrun": 0,	
"in_unicast_pkts": 0,	
"in_unknown_protos": 0,	
"in_watchdog": 0,	
"in_with_dribble": 0,	
"last_clear": "never",	
"out_babble": 0,	
"out_broadcast_pkts": 0,	
"out_collision": 0,	
"out_deferred": 0,	
"out_discard": 0,	
"out_errors": 0,	
"out_jumbo_packets": 0,	
"out_late_collision": 0,	
"out_lost_carrier": 0,	
"out_mac_pause_frames": 0,	
"out_multicast_pkts": 0,	
"out_no_carrier": 0,	
"out_octets": 0,	
"out_pkts": 0,	
"out_unicast_pkts": 0,	
"rate": {	
"in_rate": 0,	
"in_rate_bps": 0,	
"in_rate_pkts": 0,	

"in_storm_suppression_packets": 0,

```
"in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e74f",
```

```
"mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e74f",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/120": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
    "in_discard": 0,
    "in_errors": 0,
    "in_if_down_drop": 0,
```

"medium": "broadcast",

"in_ignored": 0,
"in_jumbo_packets": 0,
"in_mac_pause_frames": 0,
"in_multicast_pkts": 0,
"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,

```
"out_lost_carrier": 0,
  "out_mac_pause_frames": 0,
  "out_multicast_pkts": 0,
  "out_no_carrier": 0,
  "out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
```

```
"encapsulation": "arpa"
  },
  "ethertype": "0x8100",
  "flow_control": {
    "receive": false,
     "send": false
  },
  "interface_reset": 0,
   "last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e7bb",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e7bb",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
   "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/121": {
```

"admin_state": "up",	
"auto_mdix": "off",	
"bandwidth": 10000000,	
"beacon": "off",	
"counters": {	
"in_bad_etype_drop": 0,	
"in_broadcast_pkts": 0,	
"in_crc_errors": 0,	
"in_discard": 0,	
"in_errors": 0,	
"in_if_down_drop": 0,	
"in_ignored": 0,	
"in_jumbo_packets": 0,	
"in_mac_pause_frames": 0,	
"in_multicast_pkts": 0,	
"in_no_buffer": 0,	
"in_octets": 0,	
"in_overrun": 0,	
"in_oversize_frame": 0,	
"in_pkts": 0,	
"in_runts": 0,	
"in_short_frame": 0,	
"in_storm_suppression_packets": 0,	
"in_underrun": 0,	
"in_unicast_pkts": 0,	
"in_unknown_protos": 0,	

in_with_dribble*: 0,
last_clear": "never",
out_babble*: 0,
out_broadcast_pkts": 0,
out_collision": 0,
out_deferred": 0,
out_discard": 0,
out_errors": 0,
out_jumbo_packets": 0,
out_late_collision": 0,
out_lost_carrier": 0,
out_mac_pause_frames": 0,
out_multicast_pkts*: 0,
out_no_carrier": 0,
out_octets": 0,
out_pkts": 0,
out_unicast_pkts": 0,
rate": {
"in_rate": 0,
"in_rate_bps": 0,
"in_rate_pkts": 0,
"in_rate_pps": 0,
"load_interval": 300,
"out_rate": 0,
"out_rate_bps": 0,

"in_watchdog": 0,

```
"out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e7bc",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e7bc",
```

```
"port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport\_monitor": "off",\\
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/122": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
    "in_discard": 0,
    "in_errors": 0,
    "in_if_down_drop": 0,
    "in_ignored": 0,
    "in_jumbo_packets": 0,
    "in_mac_pause_frames": 0,
    "in_multicast_pkts": 0,
```

"port_channel": {

"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0, "out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,

```
"out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
```

```
"receive": false,
    "send": false
  },
  "interface_reset": 0,
  "last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e7bd",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e7bd",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/123": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
```

"counters": {		
"in_bad_etype_drop": 0,		
"in_broadcast_pkts": 0,		
"in_crc_errors": 0,		
"in_discard": 0,		
"in_errors": 0,		
"in_if_down_drop": 0,		
"in_ignored": 0,		
"in_jumbo_packets": 0,		
"in_mac_pause_frames": 0,		
"in_multicast_pkts": 0,		
"in_no_buffer": 0,		
"in_octets": 0,		
"in_overrun": 0,		
"in_oversize_frame": 0,		
"in_pkts": 0,		
"in_runts": 0,		
"in_short_frame": 0,		
"in_storm_suppression_packets": 0,		
"in_underrun": 0,		
"in_unicast_pkts": 0,		
"in_unknown_protos": 0,		
"in_watchdog": 0,		
"in_with_dribble": 0,		
"last_clear": "never",		
"out_babble": 0,		

```
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {
  "in_rate": 0,
  "in_rate_bps": 0,
  "in_rate_pkts": 0,
  "in_rate_pps": 0,
  "load_interval": 300,
  "out_rate": 0,
  "out_rate_bps": 0,
  "out_rate_pkts": 0,
  "out_rate_pps": 0
},
"rx": true,
```

"out_broadcast_pkts": 0,

```
"tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e7be",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e7be",
"port_channel": {
  "port_channel_member": false
},
"port_mode": "access",
```

```
"reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/124": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
   "counters": {
     "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
     "in_no_buffer": 0,
     "in_octets": 0,
     "in_overrun": 0,
     "in_oversize_frame": 0,
```

"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {

```
"in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
"interface_reset": 0,
```

},

```
"last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e7bf",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e7bf",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/125": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
```

"in_discard": 0,
"in_errors": 0,
"in_if_down_drop": 0,
"in_ignored": 0,
"in_jumbo_packets": 0,
"in_mac_pause_frames": 0,
"in_multicast_pkts": 0,
"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,

```
"out_errors": 0,
  "out_jumbo_packets": 0,
  "out_late_collision": 0,
  "out_lost_carrier": 0,
  "out_mac_pause_frames": 0,
  "out_multicast_pkts": 0,
  "out_no_carrier": 0,
  "out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
    "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
```

```
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e7c0",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e7c0",
"port_channel": {
  "port_channel_member": false
},
"port_mode": "access",
"reliability": "255/255",
"rxload": "1/255",
"switchport_monitor": "off",
"txload": "1/255",
```

```
},
"Ethernet1/126": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
     "in_no_buffer": 0,
     "in_octets": 0,
     "in_overrun": 0,
     "in_oversize_frame": 0,
     "in_pkts": 0,
     "in_runts": 0,
     "in_short_frame": 0,
     "in_storm_suppression_packets": 0,
```

"types": "100/1000/10000 Ethernet"

"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {
"in_rate": 0,
"in_rate_bps": 0,
"in_rate_pkts": 0,
"in_rate_pps": 0,

"in_underrun": 0,

```
"load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
    "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e7c1",
"medium": "broadcast",
```

```
"oper_status": "down",
  "phys_address": "5254.000d.e7c1",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/127": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
    "in_discard": 0,
    "in_errors": 0,
    "in_if_down_drop": 0,
    "in_ignored": 0,
```

"mtu": 1500,

"in_jumbo_packets": 0,
"in_mac_pause_frames": 0,
"in_multicast_pkts": 0,
"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,

```
"out_multicast_pkts": 0,
  "out_no_carrier": 0,
  "out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
    "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
```

"out_mac_pause_frames": 0,

```
},
  "ethertype": "0x8100",
  "flow_control": {
    "receive": false,
    "send": false
  },
  "interface_reset": 0,
  "last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e7c2",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e7c2",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/128": {
  "admin_state": "up",
```

"auto_mdix": "off",
"bandwidth": 10000000,
"beacon": "off",
"counters": {
"in_bad_etype_drop": 0,
"in_broadcast_pkts": 0,
"in_crc_errors": 0,
"in_discard": 0,
"in_errors": 0,
"in_if_down_drop": 0,
"in_ignored": 0,
"in_jumbo_packets": 0,
"in_mac_pause_frames": 0,
"in_multicast_pkts": 0,
"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0, "in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,

"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0, "out_unicast_pkts": 0,
"rate": {
"in_rate": 0,
"in_rate_bps": 0,
"in_rate_pkts": 0,
"in_rate_pps": 0,
"load_interval": 300,
"out_rate": 0,
"out_rate_bps": 0,
"out_rate_pkts": 0,

```
"out_rate_pps": 0
  },
  "rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e7c3",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e7c3",
"port_channel": {
```

```
"port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/13": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
    "in_discard": 0,
    "in_errors": 0,
    "in_if_down_drop": 0,
    "in_ignored": 0,
    "in_jumbo_packets": 0,
    "in_mac_pause_frames": 0,
    "in_multicast_pkts": 0,
    "in_no_buffer": 0,
```

in_overrun": 0,
in_oversize_frame": 0,
in_pkts": 0,
in_runts": 0,
in_short_frame": 0,
in_storm_suppression_packets": 0,
in_underrun": 0,
in_unicast_pkts": 0,
in_unknown_protos": 0,
in_watchdog": 0,
in_with_dribble*: 0,
last_clear": "never",
out_babble*: 0,
out_broadcast_pkts": 0,
out_collision": 0,
out_deferred": 0,
out_discard": 0,
out_errors": 0,
out_jumbo_packets": 0,
out_late_collision": 0,
out_lost_carrier": 0,
out_mac_pause_frames": 0,
out_multicast_pkts*: 0,
out_no_carrier": 0,
out_octets": 0,

"in_octets": 0,

```
"out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
```

```
"send": false
  },
  "interface_reset": 0,
  "last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e750",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e750",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport\_monitor" : "off",\\
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/14": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
```

"in_bad_etype_drop": 0,
"in_broadcast_pkts": 0,
"in_crc_errors": 0,
"in_discard": 0,
"in_errors": 0,
"in_if_down_drop": 0,
"in_ignored": 0,
"in_jumbo_packets": 0,
"in_mac_pause_frames": 0,
"in_multicast_pkts": 0,
"in_no_buffer": 0, "in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,

```
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {
  "in_rate": 0,
  "in_rate_bps": 0,
  "in_rate_pkts": 0,
  "in_rate_pps": 0,
  "load_interval": 300,
  "out_rate": 0,
  "out_rate_bps": 0,
  "out_rate_pkts": 0,
  "out_rate_pps": 0
},
"rx": true,
"tx": true
```

```
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e751",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e751",
"port_channel": {
  "port_channel_member": false
},
"port_mode": "access",
"reliability": "255/255",
```

```
"rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/15": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
   "counters": {
     "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in\_if\_down\_drop" \colon 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
     "in_no_buffer": 0,
     "in_octets": 0,
     "in_overrun": 0,
     "in_oversize_frame": 0,
     "in_pkts": 0,
```

"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {
"in_rate": 0,

"in_runts": 0,

```
"in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  "rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
"interface_reset": 0,
"last_link_flapped": "never",
```

```
"link_state": "down",
  "mac_address": "5254.000d.e752",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e752",
  "port_channel": {
    "port_channel_member": false
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/16": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
    "in_discard": 0,
```

"in_if_down_drop": 0,
"in_ignored": 0,
"in_jumbo_packets": 0,
"in_mac_pause_frames": 0,
"in_multicast_pkts": 0,
"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,

"in_errors": 0,

```
"out_jumbo_packets": 0,
  "out_late_collision": 0,
  "out_lost_carrier": 0,
  "out_mac_pause_frames": 0,
  "out_multicast_pkts": 0,
  "out_no_carrier": 0,
  "out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
```

"efficient_ethernet": "n/a",

```
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e753",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e753",
"port_channel": {
  "port_channel_member": false
},
"port_mode": "access",
"reliability": "255/255",
"rxload": "1/255",
"switchport_monitor": "off",
"txload": "1/255",
"types": "100/1000/10000 Ethernet"
```

```
"Ethernet1/17": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
    "in_discard": 0,
    "in_errors": 0,
    "in_if_down_drop": 0,
    "in_ignored": 0,
    "in_jumbo_packets": 0,
    "in_mac_pause_frames": 0,
    "in_multicast_pkts": 0,
    "in_no_buffer": 0,
    "in_octets": 0,
    "in_overrun": 0,
    "in_oversize_frame": 0,
    "in_pkts": 0,
    "in_runts": 0,
    "in_short_frame": 0,
    "in\_storm\_suppression\_packets": 0,
```

"in_underrun": 0,

"in_unkr	own_protos": 0,
"in_watc	hdog": 0,
"in_with	dribble": 0,
"last_cle	ar": "never",
"out_bat	bble*: 0,
"out_bro	adcast_pkts": 0,
"out_col	ision": 0,
"out_def	erred": 0,
"out_dis	card": 0,
"out_erro	ors": 0,
"out_jum	bo_packets": 0,
"out_late	e_collision": 0,
"out_los	c_carrier": 0,
"out_ma	c_pause_frames": 0,
"out_mu	ticast_pkts": 0,
"out_no_	carrier": 0,
"out_oct	ets": 0,
"out_pkt	s": 0,
"out_uni	cast_pkts": 0,
"rate": {	
"in_ra	": 0,
"in_ra	te_bps": 0,
"in_ra	te_pkts": 0,
"in_ra	te_pps": 0,
"load_	interval": 300,

"in_unicast_pkts": 0,

```
"out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e754",
"medium": "broadcast",
"mtu": 1500,
```

```
"oper_status": "down",
  "phys_address": "5254.000d.e754",
  "port_channel": {
    "port_channel_member": false
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/18": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
```

"in_multicast_pkts": 0,
"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,

"in_mac_pause_frames": 0,

```
"out_multicast_pkts": 0,
  "out_no_carrier": 0,
  "out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
    "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
```

```
"ethertype": "0x8100",
  "flow_control": {
    "receive": false,
    "send": false
  "interface_reset": 0,
  "last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e755",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e755",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/19": {
  "admin_state": "up",
  "auto_mdix": "off",
```

"bandwidth": 10000000,	
"beacon": "off",	
"counters": {	
"in_bad_etype_drop": 0,	
"in_broadcast_pkts": 0,	
"in_crc_errors": 0,	
"in_discard": 0,	
"in_errors": 0,	
"in_if_down_drop": 0,	
"in_ignored": 0,	
"in_jumbo_packets": 0,	
"in_mac_pause_frames": 0,	
"in_multicast_pkts": 0,	
"in_no_buffer": 0,	
"in_octets": 0,	
"in_overrun": 0,	
"in_oversize_frame": 0,	
"in_pkts": 0,	
"in_runts": 0, "in_short_frame": 0,	
"in_storm_suppression_packets": 0,	
"in_underrun": 0,	
"in_unicast_pkts": 0,	
"in_unknown_protos": 0,	
"in_watchdog": 0,	
"in_with_dribble": 0,	

out_babble*: 0,
out_broadcast_pkts": 0,
out_collision": 0,
out_deferred": 0,
out_discard": 0,
out_errors*: 0,
out_jumbo_packets": 0,
out_late_collision*: 0,
out_lost_carrier": 0,
out_mac_pause_frames": 0,
out_multicast_pkts*: 0,
out_no_carrier": 0,
out_octets": 0,
out_pkts*: 0,
out_unicast_pkts*: 0,
rate": {
"in_rate": 0,
"in_rate_bps": 0,
"in_rate_pkts": 0,
"in_rate_pps": 0,
"load_interval": 300,
"out_rate": 0,
"out_rate_bps": 0,
"out_rate_pkts": 0,
"out_rate_pps": 0

"last_clear": "never",

```
},
  "rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e756",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e756",
"port_channel": {
  "port_channel_member": false
```

```
},
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport\_monitor" : "off",\\
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/2": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 1000000,
  "beacon": "off",
  "counters": {
     "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
     "in_no_buffer": 0,
     "in_octets": 0,
```

"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,

"in_overrun": 0,

```
"out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"description": "VPC Peer Link",
"duplex_mode": "full",
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
```

```
"send": false
  },
  "interface_reset": 4,
  "last_link_flapped": "02:41:35",
  "link_state": "up",
  "mac_address": "5254.000d.e745",
  "medium": "broadcast",
  "mtu": 9216,
  "oper_status": "up",
  "phys_address": "5254.000d.e745",
  "port_channel": {
    "port_channel_int": "Port-channel1",
    "port_channel_member": true
  },
  "port_mode": "trunk",
  "port_speed": "1000",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/20": {
  "admin_state": "up",
  "auto_mdix": "off",
```

"receive": false,

"bandwidth": 10000000,	
"beacon": "off",	
"counters": {	
"in_bad_etype_drop": 0,	
"in_broadcast_pkts": 0,	
"in_crc_errors": 0,	
"in_discard": 0,	
"in_errors": 0,	
"in_if_down_drop": 0,	
"in_ignored": 0,	
"in_jumbo_packets": 0,	
"in_mac_pause_frames": 0,	
"in_multicast_pkts": 0,	
"in_no_buffer": 0,	
"in_octets": 0,	
"in_overrun": 0,	
"in_oversize_frame": 0,	
"in_pkts": 0,	
"in_runts": 0, "in_short_frame": 0,	
"in_storm_suppression_packets": 0,	
"in_underrun": 0,	
"in_unicast_pkts": 0,	
"in_unknown_protos": 0,	
"in_watchdog": 0,	
"in_with_dribble": 0,	

out_babble*: 0,
out_broadcast_pkts": 0,
out_collision": 0,
out_deferred": 0,
out_discard": 0,
out_errors*: 0,
out_jumbo_packets": 0,
out_late_collision*: 0,
out_lost_carrier": 0,
out_mac_pause_frames*: 0,
out_multicast_pkts*: 0,
out_no_carrier": 0,
out_octets": 0,
out_pkts*: 0,
out_unicast_pkts*: 0,
rate": {
"in_rate": 0,
"in_rate_bps": 0,
"in_rate_pkts": 0,
"in_rate_pps": 0,
"load_interval": 300,
"out_rate": 0,
"out_rate_bps": 0,
"out_rate_pkts": 0,
"out_rate_pps": 0

"last_clear": "never",

```
},
  "rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e757",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e757",
"port_channel": {
  "port_channel_member": false
```

```
},
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport\_monitor" : "off",\\
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/21": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
     "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
     "in_no_buffer": 0,
     "in_octets": 0,
```

"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,

"in_overrun": 0,

```
"out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
```

```
"interface_reset": 0,
  "last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e758",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e758",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/22": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
```

in_crc_errors": 0,	
in_discard": 0,	
in_errors*: 0,	
in_if_down_drop": 0,	
in_ignored": 0,	
in_jumbo_packets": 0,	
in_mac_pause_frames": 0,	
in_multicast_pkts*: 0,	
in_no_buffer": 0,	
in_octets": 0,	
in_overrun": 0,	
in_oversize_frame": 0,	
in_pkts": 0,	
in_runts": 0,	
in_short_frame": 0,	
in_storm_suppression_packets": 0,	
in_underrun": 0,	
in_unicast_pkts": 0,	
in_unknown_protos": 0,	
in_watchdog": 0,	
in_with_dribble": 0,	
last_clear": "never",	
but_babble": 0,	
out_broadcast_pkts": 0,	
out_collision": 0,	

"in_broadcast_pkts": 0,

```
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {
  "in_rate": 0,
  "in_rate_bps": 0,
  "in_rate_pkts": 0,
  "in_rate_pps": 0,
  "load_interval": 300,
  "out_rate": 0,
  "out_rate_bps": 0,
  "out_rate_pkts": 0,
  "out_rate_pps": 0
},
"rx": true,
"tx": true
```

```
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e759",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e759",
"port_channel": {
  "port_channel_member": false
},
"port_mode": "access",
"reliability": "255/255",
"rxload": "1/255",
```

```
"switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/23": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
    "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
     "in_no_buffer": 0,
     "in_octets": 0,
     "in_overrun": 0,
     "in_oversize_frame": 0,
     "in_pkts": 0,
     "in_runts": 0,
```

"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {
"in_rate": 0,
"in_rate_bps": 0,

"in_short_frame": 0,

```
"in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
```

```
"medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e75a",
  "port_channel": {
    "port_channel_member": false
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/24": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
    "in_discard": 0,
    "in_errors": 0,
```

"mac_address": "5254.000d.e75a",

in_ignored": 0,
in_jumbo_packets": 0,
in_mac_pause_frames": 0,
in_multicast_pkts": 0,
in_no_buffer": 0,
in_octets": 0,
in_overrun": 0,
in_oversize_frame": 0,
in_pkts": 0,
in_runts": 0,
in_short_frame": 0,
in_storm_suppression_packets": 0,
in_underrun": 0,
in_unicast_pkts": 0,
in_unknown_protos": 0,
in_watchdog": 0,
in_with_dribble": 0,
last_clear": "never",
out_babble": 0,
out_broadcast_pkts": 0,
out_collision": 0,
out_deferred": 0,
out_discard": 0,
out_errors": 0,
out_jumbo_packets*: 0,

"in_if_down_drop": 0,

```
"out_late_collision": 0,
  "out_lost_carrier": 0,
  "out_mac_pause_frames": 0,
  "out_multicast_pkts": 0,
  "out_no_carrier": 0,
  "out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
```

```
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e75b",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e75b",
"port_channel": {
  "port_channel_member": false
"port_mode": "access",
"reliability": "255/255",
"rxload": "1/255",
"switchport_monitor": "off",
"txload": "1/255",
"types": "100/1000/10000 Ethernet"
```

"Ethernet1/25": {		
"admin_state": "up",		
"auto_mdix": "off",		
"bandwidth": 10000000,		
"beacon": "off",		
"counters": {		
"in_bad_etype_drop": 0,		
"in_broadcast_pkts": 0,		
"in_crc_errors": 0,		
"in_discard": 0,		
"in_errors": 0,		
"in_if_down_drop": 0,		
"in_ignored": 0,		
"in_jumbo_packets": 0,		
"in_mac_pause_frames": 0,		
"in_multicast_pkts": 0,		
"in_no_buffer": 0,		
"in_octets": 0,		
"in_overrun": 0,		
"in_oversize_frame": 0,		
"in_pkts": 0,		
"in_runts": 0,		
"in_short_frame": 0,		
"in_storm_suppression_packets": 0,		
"in_underrun": 0,		

"in_unicast_pkts": 0,

"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {
"in_rate": 0,
"in_rate_bps": 0,
"in_rate_pkts": 0,
"in_rate_pps": 0,
"load_interval": 300,
"out_rate": 0,

"in_unknown_protos": 0,

```
"out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e75c",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
```

```
"phys_address": "5254.000d.e75c",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/26": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
```

"in_multicast_pkts": 0,
"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,

```
"out_no_carrier": 0,
  "out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
```

```
"receive": false,
    "send": false
  },
  "interface_reset": 0,
  "last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e75d",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e75d",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/27": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
```

"flow_control": {

"beacon": "off",		
"counters": {		
"in_bad_etype_drop": 0,		
"in_broadcast_pkts": 0,		
"in_crc_errors": 0,		
"in_discard": 0,		
"in_errors": 0,		
"in_if_down_drop": 0,		
"in_ignored": 0,		
"in_jumbo_packets": 0,		
"in_mac_pause_frames": 0,		
"in_multicast_pkts": 0,		
"in_no_buffer": 0,		
"in_octets": 0,		
"in_overrun": 0,		
"in_oversize_frame": 0,		
"in_pkts": 0,		
"in_runts": 0,		
"in_short_frame": 0,		
"in_storm_suppression_packets": 0,		
"in_underrun": 0,		
"in_unicast_pkts": 0,		
"in_unknown_protos": 0,		
"in_watchdog": 0,		
"in_with_dribble": 0,		
"last_clear": "never",		

```
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {
  "in_rate": 0,
  "in_rate_bps": 0,
  "in_rate_pkts": 0,
  "in_rate_pps": 0,
   "load_interval": 300,
  "out_rate": 0,
  "out_rate_bps": 0,
  "out_rate_pkts": 0,
  "out_rate_pps": 0
},
```

"out_babble": 0,

```
"rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e75e",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e75e",
"port_channel": {
  "port_channel_member": false
},
```

```
"port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/28": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
     "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
     "in_no_buffer": 0,
     "in_octets": 0,
     "in_overrun": 0,
```

"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,

"in_oversize_frame": 0,

```
"rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
```

},

```
"last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e75f",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e75f",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/29": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
```

"interface_reset": 0,

m_oto_onoto . v,
"in_discard": 0,
"in_errors": 0,
"in_if_down_drop": 0,
"in_ignored": 0,
"in_jumbo_packets": 0,
"in_mac_pause_frames": 0,
"in_multicast_pkts": 0,
"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,

```
"out_errors": 0,
  "out_jumbo_packets": 0,
  "out_late_collision": 0,
  "out_lost_carrier": 0,
  "out_mac_pause_frames": 0,
  "out_multicast_pkts": 0,
  "out_no_carrier": 0,
  "out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
```

"out_discard": 0,

```
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e760",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e760",
"port_channel": {
  "port_channel_member": false
},
"port_mode": "access",
"reliability": "255/255",
"rxload": "1/255",
"switchport_monitor": "off",
```

```
"txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/3": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 1000000,
  "beacon": "off",
  "counters": {
     "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
     "in_no_buffer": 0,
     "in_octets": 0,
     "in_overrun": 0,
     "in_oversize_frame": 0,
     "in_pkts": 0,
     "in_runts": 0,
     "in_short_frame": 0,
```

"in_underrun": 0,	
"in_unicast_pkts": 0,	
"in_unknown_protos": 0,	
"in_watchdog": 0,	
"in_with_dribble": 0,	
"last_clear": "never",	
"out_babble": 0,	
"out_broadcast_pkts": 0,	
"out_collision": 0,	
"out_deferred": 0,	
"out_discard": 0,	
"out_errors": 0,	
"out_jumbo_packets": 0,	
"out_late_collision": 0,	
"out_lost_carrier": 0,	
"out_mac_pause_frames": 0,	
"out_multicast_pkts": 0,	
"out_no_carrier": 0,	
"out_octets": 0,	
"out_pkts": 0,	
"out_unicast_pkts": 0,	
"rate": {	
"in_rate": 0,	
"in_rate_bps": 0,	
"in_rate_pkts": 0,	

"in_storm_suppression_packets": 0,

```
"in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"description": "L3 link to dist-rtr01",
"duplex_mode": "full",
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 2,
"ipv4": {
```

```
"172.16.252.1/30": {
       "ip": "172.16.252.1",
       "prefix_length": "30"
    }
  },
  "last_link_flapped": "02:41:53",
  "link_state": "up",
  "mac_address": "5254.000d.e743",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "up",
  "phys_address": "5254.000d.e746",
  "port_channel": {
    "port_channel_member": false
  },
  "port_speed": "1000",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/30": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
```

"beacon": "off",		
"counters": {		
"in_bad_etype_drop": 0,		
"in_broadcast_pkts": 0,		
"in_crc_errors": 0,		
"in_discard": 0,		
"in_errors": 0,		
"in_if_down_drop": 0,		
"in_ignored": 0,		
"in_jumbo_packets": 0,		
"in_mac_pause_frames": 0,		
"in_multicast_pkts": 0,		
"in_no_buffer": 0,		
"in_octets": 0,		
"in_overrun": 0,		
"in_oversize_frame": 0,		
"in_pkts": 0,		
"in_runts": 0,		
"in_short_frame": 0,		
"in_storm_suppression_packets": 0,		
"in_underrun": 0,		
"in_unicast_pkts": 0,		
"in_unknown_protos": 0,		
"in_watchdog": 0,		
"in_with_dribble": 0,		
"last_clear": "never",		

```
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {
  "in_rate": 0,
  "in_rate_bps": 0,
  "in_rate_pkts": 0,
  "in_rate_pps": 0,
   "load_interval": 300,
  "out_rate": 0,
  "out_rate_bps": 0,
  "out_rate_pkts": 0,
  "out_rate_pps": 0
},
```

"out_babble": 0,

```
"rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e761",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e761",
"port_channel": {
  "port_channel_member": false
},
```

```
"port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/31": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
     "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
     "in_no_buffer": 0,
     "in_octets": 0,
     "in_overrun": 0,
```

"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,

"in_oversize_frame": 0,

```
"rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
```

},

```
"last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e762",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e762",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/32": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
```

"interface_reset": 0,

m_oto_onoto . v,
"in_discard": 0,
"in_errors": 0,
"in_if_down_drop": 0,
"in_ignored": 0,
"in_jumbo_packets": 0,
"in_mac_pause_frames": 0,
"in_multicast_pkts": 0,
"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,

```
"out_errors": 0,
  "out_jumbo_packets": 0,
  "out_late_collision": 0,
  "out_lost_carrier": 0,
  "out_mac_pause_frames": 0,
  "out_multicast_pkts": 0,
  "out_no_carrier": 0,
  "out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
```

"out_discard": 0,

```
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e763",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e763",
"port_channel": {
  "port_channel_member": false
},
"port_mode": "access",
"reliability": "255/255",
"rxload": "1/255",
"switchport_monitor": "off",
```

```
"txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/33": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
     "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
     "in_no_buffer": 0,
     "in_octets": 0,
     "in_overrun": 0,
     "in_oversize_frame": 0,
     "in_pkts": 0,
     "in_runts": 0,
     "in_short_frame": 0,
```

"in_underrun": 0,	
"in_unicast_pkts": 0,	
"in_unknown_protos": 0,	
"in_watchdog": 0,	
"in_with_dribble": 0,	
"last_clear": "never",	
"out_babble": 0,	
"out_broadcast_pkts": 0,	
"out_collision": 0,	
"out_deferred": 0,	
"out_discard": 0,	
"out_errors": 0,	
"out_jumbo_packets": 0,	
"out_late_collision": 0,	
"out_lost_carrier": 0,	
"out_mac_pause_frames": 0,	
"out_multicast_pkts": 0,	
"out_no_carrier": 0,	
"out_octets": 0,	
"out_pkts": 0,	
"out_unicast_pkts": 0,	
"rate": {	
"in_rate": 0,	
"in_rate_bps": 0,	
"in_rate_pkts": 0,	

"in_storm_suppression_packets": 0,

```
"in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e764",
```

```
"medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e764",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/34": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
    "in_discard": 0,
    "in_errors": 0,
    "in_if_down_drop": 0,
```

"in_ignored": 0,
"in_jumbo_packets": 0,
"in_mac_pause_frames": 0,
"in_multicast_pkts": 0,
"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0, "last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,

```
"out_lost_carrier": 0,
  "out_mac_pause_frames": 0,
  "out_multicast_pkts": 0,
  "out_no_carrier": 0,
  "out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
```

```
"encapsulation": "arpa"
  },
  "ethertype": "0x8100",
  "flow_control": {
    "receive": false,
    "send": false
  },
  "interface_reset": 0,
  "last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e765",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e765",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/35": {
```

"admin_state": "up",	
"auto_mdix": "off",	
"bandwidth": 10000000,	
"beacon": "off",	
"counters": {	
"in_bad_etype_drop": 0,	
"in_broadcast_pkts": 0,	
"in_crc_errors": 0,	
"in_discard": 0,	
"in_errors": 0,	
"in_if_down_drop": 0,	
"in_ignored": 0,	
"in_jumbo_packets": 0,	
"in_mac_pause_frames": 0,	
"in_multicast_pkts": 0,	
"in_no_buffer": 0,	
"in_octets": 0,	
"in_overrun": 0,	
"in_oversize_frame": 0,	
"in_pkts": 0,	
"in_runts": 0,	
"in_short_frame": 0,	
"in_storm_suppression_packets": 0,	
"in_underrun": 0,	
"in_unicast_pkts": 0,	
"in_unknown_protos": 0,	

in_with_dribble*: 0,
last_clear": "never",
out_babble*: 0,
out_broadcast_pkts": 0,
out_collision": 0,
out_deferred": 0,
out_discard": 0,
out_errors": 0,
out_jumbo_packets": 0,
out_late_collision*: 0,
out_lost_carrier": 0,
out_mac_pause_frames": 0,
out_multicast_pkts*: 0,
out_no_carrier": 0,
out_octets*: 0,
out_pkts": 0,
out_unicast_pkts*: 0,
rate": {
"in_rate": 0,
"in_rate_bps": 0,
"in_rate_pkts": 0,
"in_rate_pps": 0,
"load_interval": 300,
"out_rate": 0,
"out_rate_bps": 0,

"in_watchdog": 0,

```
"out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e766",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e766",
```

```
"port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport\_monitor": "off",\\
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/36": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
```

"port_channel": {

"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0, "out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,

```
"out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
```

```
"receive": false,
    "send": false
  },
  "interface_reset": 0,
  "last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e767",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e767",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/37": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
```

"counters": {			
"in_bad_etype_drop": 0,			
"in_broadcast_pkts": 0,			
"in_crc_errors": 0,			
"in_discard": 0,			
"in_errors": 0,			
"in_if_down_drop": 0,			
"in_ignored": 0,			
"in_jumbo_packets": 0,			
"in_mac_pause_frames": 0,			
"in_multicast_pkts": 0,			
"in_no_buffer": 0,			
"in_octets": 0,			
"in_overrun": 0,			
"in_oversize_frame": 0,			
"in_pkts": 0,			
"in_runts": 0,			
"in_short_frame": 0,			
"in_storm_suppression_packets": 0,			
"in_underrun": 0,			
"in_unicast_pkts": 0,			
"in_unknown_protos": 0,			
"in_watchdog": 0,			
"in_with_dribble": 0,			
"last_clear": "never",			
"out_babble": 0,			

```
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {
  "in_rate": 0,
  "in_rate_bps": 0,
  "in_rate_pkts": 0,
  "in_rate_pps": 0,
  "load_interval": 300,
  "out_rate": 0,
  "out_rate_bps": 0,
  "out_rate_pkts": 0,
  "out_rate_pps": 0
},
"rx": true,
```

"out_broadcast_pkts": 0,

```
"tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e768",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e768",
"port_channel": {
  "port_channel_member": false
},
"port_mode": "access",
```

```
"reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/38": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
   "counters": {
     "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
     "in_no_buffer": 0,
     "in_octets": 0,
     "in_overrun": 0,
     "in_oversize_frame": 0,
```

"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0, "out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {

```
"in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
"interface_reset": 0,
```

},

```
"last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e769",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e769",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/39": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
```

"in_discard": 0,
"in_errors": 0,
"in_if_down_drop": 0,
"in_ignored": 0,
"in_jumbo_packets": 0,
"in_mac_pause_frames": 0,
"in_multicast_pkts": 0,
"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,

```
"out_errors": 0,
  "out_jumbo_packets": 0,
  "out_late_collision": 0,
  "out_lost_carrier": 0,
  "out_mac_pause_frames": 0,
  "out_multicast_pkts": 0,
  "out_no_carrier": 0,
  "out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
    "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
```

```
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e76a",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e76a",
"port_channel": {
  "port_channel_member": false
},
"port_mode": "access",
"reliability": "255/255",
"rxload": "1/255",
"switchport_monitor": "off",
"txload": "1/255",
```

```
},
"Ethernet1/4": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 1000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
     "in_no_buffer": 0,
     "in_octets": 0,
     "in_overrun": 0,
     "in_oversize_frame": 0,
     "in_pkts": 0,
     "in_runts": 0,
     "in_short_frame": 0,
     "in_storm_suppression_packets": 0,
```

"types": "100/1000/10000 Ethernet"

"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {
"in_rate": 0,
"in_rate_bps": 0,
"in_rate_pkts": 0,
"in_rate_pps": 0,

"in_underrun": 0,

```
"load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
    "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"description": "L3 link to dist-rtr02",
"duplex_mode": "full",
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
"interface_reset": 2,
"ipv4": {
  "172.16.252.5/30": {
```

```
"prefix_length": "30"
  },
  "last_link_flapped": "02:41:53",
  "link_state": "up",
  "mac_address": "5254.000d.e743",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "up",
  "phys_address": "5254.000d.e747",
  "port_channel": {
    "port_channel_member": false
  },
  "port_speed": "1000",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/40": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
```

"ip": "172.16.252.5",

"counters": {			
"in_bad_etype_drop": 0,			
"in_broadcast_pkts": 0,			
"in_crc_errors": 0,			
"in_discard": 0,			
"in_errors": 0,			
"in_if_down_drop": 0,			
"in_ignored": 0,			
"in_jumbo_packets": 0,			
"in_mac_pause_frames": 0,			
"in_multicast_pkts": 0,			
"in_no_buffer": 0,			
"in_octets": 0,			
"in_overrun": 0,			
"in_oversize_frame": 0,			
"in_pkts": 0,			
"in_runts": 0,			
"in_short_frame": 0,			
"in_storm_suppression_packets": 0,			
"in_underrun": 0,			
"in_unicast_pkts": 0,			
"in_unknown_protos": 0,			
"in_watchdog": 0,			
"in_with_dribble": 0,			
"last_clear": "never",			
"out_babble": 0,			

```
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {
  "in_rate": 0,
  "in_rate_bps": 0,
  "in_rate_pkts": 0,
  "in_rate_pps": 0,
  "load_interval": 300,
  "out_rate": 0,
  "out_rate_bps": 0,
  "out_rate_pkts": 0,
  "out_rate_pps": 0
},
"rx": true,
```

"out_broadcast_pkts": 0,

```
"tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e76b",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e76b",
"port_channel": {
  "port_channel_member": false
},
"port_mode": "access",
```

```
"reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/41": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
   "counters": {
     "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
     "in_no_buffer": 0,
     "in_octets": 0,
     "in_overrun": 0,
     "in_oversize_frame": 0,
```

"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0, "out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {

```
"in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
"interface_reset": 0,
```

},

```
"last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e76c",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e76c",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/42": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
```

"in_discard": 0,
"in_errors": 0,
"in_if_down_drop": 0,
"in_ignored": 0,
"in_jumbo_packets": 0,
"in_mac_pause_frames": 0,
"in_multicast_pkts": 0,
"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,

```
"out_errors": 0,
  "out_jumbo_packets": 0,
  "out_late_collision": 0,
  "out_lost_carrier": 0,
  "out_mac_pause_frames": 0,
  "out_multicast_pkts": 0,
  "out_no_carrier": 0,
  "out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
    "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
```

```
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e76d",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e76d",
"port_channel": {
  "port_channel_member": false
},
"port_mode": "access",
"reliability": "255/255",
"rxload": "1/255",
"switchport_monitor": "off",
"txload": "1/255",
```

```
},
"Ethernet1/43": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
     "in_no_buffer": 0,
     "in_octets": 0,
     "in_overrun": 0,
     "in_oversize_frame": 0,
     "in_pkts": 0,
     "in_runts": 0,
     "in_short_frame": 0,
     "in_storm_suppression_packets": 0,
```

"types": "100/1000/10000 Ethernet"

"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {
"in_rate": 0,
"in_rate_bps": 0,
"in_rate_pkts": 0,
"in_rate_pps": 0,

"in_underrun": 0,

```
"load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
    "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e76e",
"medium": "broadcast",
```

```
"oper_status": "down",
  "phys_address": "5254.000d.e76e",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/44": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
     "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
```

"mtu": 1500,

"in_jumbo_packets": 0,
"in_mac_pause_frames": 0,
"in_multicast_pkts": 0,
"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,

```
"out_multicast_pkts": 0,
  "out_no_carrier": 0,
  "out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
    "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
```

"out_mac_pause_frames": 0,

```
},
  "ethertype": "0x8100",
  "flow_control": {
    "receive": false,
    "send": false
  },
  "interface_reset": 0,
  "last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e76f",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e76f",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/45": {
  "admin_state": "up",
```

"auto_mdix": "off",
"bandwidth": 10000000,
"beacon": "off",
"counters": {
"in_bad_etype_drop": 0,
"in_broadcast_pkts": 0,
"in_crc_errors": 0,
"in_discard": 0,
"in_errors": 0,
"in_if_down_drop": 0,
"in_ignored": 0,
"in_jumbo_packets": 0,
"in_mac_pause_frames": 0,
"in_multicast_pkts": 0,
"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0, "in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,

"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0, "out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {
"in_rate": 0,
"in_rate_bps": 0,
"in_rate_pkts": 0,
"in_rate_pps": 0,
"load_interval": 300,
"out_rate": 0, "out_rate_bps": 0,
"out_rate_pkts": 0,

```
"out_rate_pps": 0
  },
  "rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e770",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e770",
"port_channel": {
```

```
"port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/46": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
    "in_discard": 0,
    "in_errors": 0,
    "in_if_down_drop": 0,
    "in_ignored": 0,
    "in_jumbo_packets": 0,
    "in_mac_pause_frames": 0,
    "in_multicast_pkts": 0,
    "in_no_buffer": 0,
```

in_overrun": 0,
in_oversize_frame": 0,
in_pkts": 0,
in_runts": 0,
in_short_frame": 0,
in_storm_suppression_packets": 0,
in_underrun": 0,
in_unicast_pkts": 0,
in_unknown_protos": 0,
in_watchdog": 0,
in_with_dribble*: 0,
last_clear": "never",
out_babble*: 0,
out_broadcast_pkts": 0,
out_collision": 0,
out_deferred": 0,
out_discard": 0,
out_errors": 0,
out_jumbo_packets": 0,
out_late_collision": 0,
out_lost_carrier": 0,
out_mac_pause_frames": 0,
out_multicast_pkts": 0,
out_no_carrier": 0,
out_octets": 0,

"in_octets": 0,

```
"out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
```

```
"send": false
  },
  "interface_reset": 0,
  "last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e771",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e771",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport\_monitor" : "off",\\
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/47": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
```

"in_bad_etype_drop": 0,
"in_broadcast_pkts": 0,
"in_crc_errors": 0,
"in_discard": 0,
"in_errors": 0,
"in_if_down_drop": 0,
"in_ignored": 0,
"in_jumbo_packets": 0,
"in_mac_pause_frames": 0,
"in_multicast_pkts": 0,
"in_no_buffer": 0, "in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never", "out_bobble": 0
"out_babble": 0, "out_broadcast_pkts": 0,

```
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {
  "in_rate": 0,
  "in_rate_bps": 0,
  "in_rate_pkts": 0,
  "in_rate_pps": 0,
  "load_interval": 300,
  "out_rate": 0,
  "out_rate_bps": 0,
  "out_rate_pkts": 0,
  "out_rate_pps": 0
},
"rx": true,
"tx": true
```

```
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e772",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e772",
"port_channel": {
  "port_channel_member": false
},
"port_mode": "access",
"reliability": "255/255",
```

```
"rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/48": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
   "counters": {
     "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in\_if\_down\_drop" \colon 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
     "in_no_buffer": 0,
     "in_octets": 0,
     "in_overrun": 0,
     "in_oversize_frame": 0,
     "in_pkts": 0,
```

"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {
"in_rate": 0,

"in_runts": 0,

```
"in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  "rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
"interface_reset": 0,
"last_link_flapped": "never",
```

```
"link_state": "down",
  "mac_address": "5254.000d.e773",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e773",
  "port_channel": {
    "port_channel_member": false
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/49": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
    "in_discard": 0,
```

"in_if_down_drop": 0,
"in_ignored": 0,
"in_jumbo_packets": 0,
"in_mac_pause_frames": 0,
"in_multicast_pkts": 0,
"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,

"in_errors": 0,

```
"out_jumbo_packets": 0,
  "out_late_collision": 0,
  "out_lost_carrier": 0,
  "out_mac_pause_frames": 0,
  "out_multicast_pkts": 0,
  "out_no_carrier": 0,
  "out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
```

"efficient_ethernet": "n/a",

```
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e774",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e774",
"port_channel": {
  "port_channel_member": false
},
"port_mode": "access",
"reliability": "255/255",
"rxload": "1/255",
"switchport_monitor": "off",
"txload": "1/255",
"types": "100/1000/10000 Ethernet"
```

```
"Ethernet1/5": {
  "admin_state": "down",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
    "in_discard": 0,
    "in_errors": 0,
    "in_if_down_drop": 0,
    "in_ignored": 0,
    "in_jumbo_packets": 0,
    "in_mac_pause_frames": 0,
    "in_multicast_pkts": 0,
    "in_no_buffer": 0,
    "in_octets": 0,
    "in_overrun": 0,
    "in_oversize_frame": 0,
    "in_pkts": 0,
    "in_runts": 0,
    "in_short_frame": 0,
    "in\_storm\_suppression\_packets": 0,
```

"in_underrun": 0,

"in_unkr	own_protos": 0,
"in_watc	hdog": 0,
"in_with	dribble": 0,
"last_cle	ar": "never",
"out_bat	bble*: 0,
"out_bro	adcast_pkts": 0,
"out_col	ision": 0,
"out_def	erred": 0,
"out_dis	card": 0,
"out_erro	ors": 0,
"out_jum	bo_packets": 0,
"out_late	e_collision": 0,
"out_los	c_carrier": 0,
"out_ma	c_pause_frames": 0,
"out_mu	ticast_pkts": 0,
"out_no_	carrier": 0,
"out_oct	ets": 0,
"out_pkt	s": 0,
"out_uni	cast_pkts": 0,
"rate": {	
"in_ra	": 0,
"in_ra	te_bps": 0,
"in_ra	te_pkts": 0,
"in_ra	te_pps": 0,
"load_	interval": 300,

"in_unicast_pkts": 0,

```
"out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"description": "to",
"efficient_ethernet": "n/a",
"enabled": false,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 1,
"last_link_flapped": "02:41:53",
"link_state": "down",
"mac_address": "5254.000d.e748",
"medium": "broadcast",
```

```
"oper_status": "down",
  "phys_address": "5254.000d.e748",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/50": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
     "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
```

"mtu": 1500,

"in_jumbo_packets": 0,
"in_mac_pause_frames": 0,
"in_multicast_pkts": 0,
"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,

```
"out_multicast_pkts": 0,
  "out_no_carrier": 0,
  "out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
    "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
```

"out_mac_pause_frames": 0,

```
},
  "ethertype": "0x8100",
  "flow_control": {
    "receive": false,
    "send": false
  },
  "interface_reset": 0,
  "last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e775",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e775",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/51": {
  "admin_state": "up",
```

"auto_mdix": "off",
"bandwidth": 10000000,
"beacon": "off",
"counters": {
"in_bad_etype_drop": 0,
"in_broadcast_pkts": 0,
"in_crc_errors": 0,
"in_discard": 0,
"in_errors": 0,
"in_if_down_drop": 0,
"in_ignored": 0,
"in_jumbo_packets": 0,
"in_mac_pause_frames": 0,
"in_multicast_pkts": 0,
"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0, "in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,

"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0, "out_unicast_pkts": 0,
"rate": {
"in_rate": 0,
"in_rate_bps": 0,
"in_rate_pkts": 0,
"in_rate_pps": 0,
"load_interval": 300,
"out_rate": 0,
"out_rate_bps": 0,
"out_rate_pkts": 0,

```
"out_rate_pps": 0
  },
  "rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e776",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e776",
"port_channel": {
```

```
"port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/52": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
    "in_discard": 0,
    "in_errors": 0,
    "in_if_down_drop": 0,
    "in_ignored": 0,
    "in_jumbo_packets": 0,
    "in_mac_pause_frames": 0,
    "in_multicast_pkts": 0,
    "in_no_buffer": 0,
```

in_overrun": 0,
in_oversize_frame": 0,
in_pkts": 0,
in_runts": 0,
in_short_frame": 0,
in_storm_suppression_packets": 0,
in_underrun": 0,
in_unicast_pkts": 0,
in_unknown_protos": 0,
in_watchdog": 0,
in_with_dribble*: 0,
last_clear": "never",
out_babble*: 0,
out_broadcast_pkts": 0,
out_collision": 0,
out_deferred": 0,
out_discard": 0,
out_errors": 0,
out_jumbo_packets": 0,
out_late_collision": 0,
out_lost_carrier": 0,
out_mac_pause_frames": 0,
out_multicast_pkts*: 0,
out_no_carrier": 0,
out_octets": 0,

"in_octets": 0,

```
"out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
```

```
"send": false
  },
  "interface_reset": 0,
  "last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e777",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e777",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport\_monitor": "off",\\
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/53": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
```

"in_bad_etype_drop": 0,
"in_broadcast_pkts": 0,
"in_crc_errors": 0,
"in_discard": 0,
"in_errors": 0,
"in_if_down_drop": 0,
"in_ignored": 0,
"in_jumbo_packets": 0,
"in_mac_pause_frames": 0,
"in_multicast_pkts": 0,
"in_no_buffer": 0, "in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,

```
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {
  "in_rate": 0,
  "in_rate_bps": 0,
  "in_rate_pkts": 0,
  "in_rate_pps": 0,
  "load_interval": 300,
  "out_rate": 0,
  "out_rate_bps": 0,
  "out_rate_pkts": 0,
  "out_rate_pps": 0
},
"rx": true,
"tx": true
```

```
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e778",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e778",
"port_channel": {
  "port_channel_member": false
},
"port_mode": "access",
"reliability": "255/255",
```

```
"rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/54": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
   "counters": {
     "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in\_if\_down\_drop" \colon 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
     "in_no_buffer": 0,
     "in_octets": 0,
     "in_overrun": 0,
     "in_oversize_frame": 0,
     "in_pkts": 0,
```

"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {
"in_rate": 0,

"in_runts": 0,

```
"in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  "rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
"interface_reset": 0,
"last_link_flapped": "never",
```

```
"link_state": "down",
  "mac_address": "5254.000d.e779",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e779",
  "port_channel": {
    "port_channel_member": false
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/55": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
    "in_discard": 0,
```

"in_if_down_drop": 0,
"in_ignored": 0,
"in_jumbo_packets": 0,
"in_mac_pause_frames": 0,
"in_multicast_pkts": 0,
"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,

"in_errors": 0,

```
"out_jumbo_packets": 0,
  "out_late_collision": 0,
  "out_lost_carrier": 0,
  "out_mac_pause_frames": 0,
  "out_multicast_pkts": 0,
  "out_no_carrier": 0,
  "out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
```

"efficient_ethernet": "n/a",

```
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e77a",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e77a",
"port_channel": {
  "port_channel_member": false
},
"port_mode": "access",
"reliability": "255/255",
"rxload": "1/255",
"switchport_monitor": "off",
"txload": "1/255",
"types": "100/1000/10000 Ethernet"
```

```
"Ethernet1/56": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
    "in_discard": 0,
    "in_errors": 0,
    "in_if_down_drop": 0,
    "in_ignored": 0,
    "in_jumbo_packets": 0,
    "in_mac_pause_frames": 0,
    "in_multicast_pkts": 0,
    "in_no_buffer": 0,
    "in_octets": 0,
    "in_overrun": 0,
    "in_oversize_frame": 0,
    "in_pkts": 0,
    "in_runts": 0,
    "in_short_frame": 0,
    "in\_storm\_suppression\_packets": 0,
```

"in_underrun": 0,

"in_unkr	own_protos": 0,
"in_watc	hdog": 0,
"in_with	dribble": 0,
"last_cle	ar": "never",
"out_bat	bble*: 0,
"out_bro	adcast_pkts": 0,
"out_col	ision": 0,
"out_def	erred": 0,
"out_dis	card": 0,
"out_erro	ors": 0,
"out_jum	bo_packets": 0,
"out_late	e_collision": 0,
"out_los	c_carrier": 0,
"out_ma	c_pause_frames": 0,
"out_mu	ticast_pkts": 0,
"out_no_	carrier": 0,
"out_oct	ets": 0,
"out_pkt	s": 0,
"out_uni	cast_pkts": 0,
"rate": {	
"in_ra	": 0,
"in_ra	te_bps": 0,
"in_ra	te_pkts": 0,
"in_ra	te_pps": 0,
"load_	interval": 300,

"in_unicast_pkts": 0,

```
"out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e77b",
"medium": "broadcast",
"mtu": 1500,
```

```
"oper_status": "down",
  "phys_address": "5254.000d.e77b",
  "port_channel": {
    "port_channel_member": false
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/57": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
    "in_discard": 0,
    "in_errors": 0,
    "in_if_down_drop": 0,
    "in_ignored": 0,
    "in_jumbo_packets": 0,
```

"in_multicast_pkts": 0,
"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,

"in_mac_pause_frames": 0,

```
"out_multicast_pkts": 0,
  "out_no_carrier": 0,
  "out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
    "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
```

```
"ethertype": "0x8100",
  "flow_control": {
    "receive": false,
    "send": false
  "interface_reset": 0,
  "last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e77c",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e77c",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/58": {
  "admin_state": "up",
  "auto_mdix": "off",
```

"bandwidth": 10000000,	
"beacon": "off",	
"counters": {	
"in_bad_etype_drop": 0,	
"in_broadcast_pkts": 0,	
"in_crc_errors": 0,	
"in_discard": 0,	
"in_errors": 0,	
"in_if_down_drop": 0,	
"in_ignored": 0,	
"in_jumbo_packets": 0,	
"in_mac_pause_frames": 0,	
"in_multicast_pkts": 0,	
"in_no_buffer": 0,	
"in_octets": 0,	
"in_overrun": 0,	
"in_oversize_frame": 0,	
"in_pkts": 0,	
"in_runts": 0, "in_short_frame": 0,	
"in_storm_suppression_packets": 0,	
"in_underrun": 0,	
"in_unicast_pkts": 0,	
"in_unknown_protos": 0,	
"in_watchdog": 0,	
"in_with_dribble": 0,	

out_babble*: 0,
out_broadcast_pkts": 0,
out_collision": 0,
out_deferred": 0,
out_discard": 0,
out_errors*: 0,
out_jumbo_packets": 0,
out_late_collision*: 0,
out_lost_carrier": 0,
out_mac_pause_frames": 0,
out_multicast_pkts*: 0,
out_no_carrier": 0,
out_octets": 0,
out_pkts*: 0,
out_unicast_pkts*: 0,
rate": {
"in_rate": 0,
"in_rate_bps": 0,
"in_rate_pkts": 0,
"in_rate_pps": 0,
"load_interval": 300,
"out_rate": 0,
"out_rate_bps": 0,
"out_rate_pkts": 0,
"out_rate_pps": 0

"last_clear": "never",

```
},
  "rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e77d",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e77d",
"port_channel": {
  "port_channel_member": false
```

```
"port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport\_monitor" : "off",\\
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/59": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
     "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
     "in_no_buffer": 0,
     "in_octets": 0,
```

"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,

"in_overrun": 0,

```
"out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
```

```
"interface_reset": 0,
  "last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e77e",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e77e",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/6": {
  "admin_state": "down",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
```

in_crc_errors": 0,	
in_discard": 0,	
in_errors*: 0,	
in_if_down_drop": 0,	
in_ignored": 0,	
in_jumbo_packets": 0,	
in_mac_pause_frames": 0,	
in_multicast_pkts*: 0,	
in_no_buffer": 0,	
in_octets": 0,	
in_overrun": 0,	
in_oversize_frame": 0,	
in_pkts": 0,	
in_runts": 0,	
in_short_frame": 0,	
in_storm_suppression_packets": 0,	
in_underrun": 0,	
in_unicast_pkts": 0,	
in_unknown_protos": 0,	
in_watchdog": 0,	
in_with_dribble": 0,	
last_clear": "never",	
but_babble": 0,	
out_broadcast_pkts": 0,	
out_collision": 0,	

"in_broadcast_pkts": 0,

```
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {
  "in_rate": 0,
  "in_rate_bps": 0,
  "in_rate_pkts": 0,
  "in_rate_pps": 0,
  "load_interval": 300,
  "out_rate": 0,
  "out_rate_bps": 0,
  "out_rate_pkts": 0,
  "out_rate_pps": 0
},
"rx": true,
"tx": true
```

```
"dedicated_interface": true,
"delay": 10,
"description": "to",
"efficient_ethernet": "n/a",
"enabled": false,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 1,
"last_link_flapped": "02:41:53",
"link_state": "down",
"mac_address": "5254.000d.e749",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e749",
"port_channel": {
  "port_channel_member": false
},
"port_mode": "access",
"reliability": "255/255",
```

```
"rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/60": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
   "counters": {
     "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in\_if\_down\_drop" \colon 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
     "in_no_buffer": 0,
     "in_octets": 0,
     "in_overrun": 0,
     "in_oversize_frame": 0,
     "in_pkts": 0,
```

"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {
"in_rate": 0,

"in_runts": 0,

```
"in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  "rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
"interface_reset": 0,
"last_link_flapped": "never",
```

```
"link_state": "down",
  "mac_address": "5254.000d.e77f",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e77f",
  "port_channel": {
    "port_channel_member": false
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/61": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
    "in_discard": 0,
```

"in_if_down_drop": 0,
"in_ignored": 0,
"in_jumbo_packets": 0,
"in_mac_pause_frames": 0,
"in_multicast_pkts": 0,
"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,

"in_errors": 0,

```
"out_jumbo_packets": 0,
  "out_late_collision": 0,
  "out_lost_carrier": 0,
  "out_mac_pause_frames": 0,
  "out_multicast_pkts": 0,
  "out_no_carrier": 0,
  "out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
```

"efficient_ethernet": "n/a",

```
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e780",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e780",
"port_channel": {
  "port_channel_member": false
},
"port_mode": "access",
"reliability": "255/255",
"rxload": "1/255",
"switchport_monitor": "off",
"txload": "1/255",
"types": "100/1000/10000 Ethernet"
```

```
"Ethernet1/62": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
    "in_discard": 0,
    "in_errors": 0,
    "in_if_down_drop": 0,
    "in_ignored": 0,
    "in_jumbo_packets": 0,
    "in_mac_pause_frames": 0,
    "in_multicast_pkts": 0,
    "in_no_buffer": 0,
    "in_octets": 0,
    "in_overrun": 0,
    "in_oversize_frame": 0,
    "in_pkts": 0,
    "in_runts": 0,
    "in_short_frame": 0,
    "in\_storm\_suppression\_packets": 0,
```

"in_underrun": 0,

"in_unkr	own_protos": 0,
"in_watc	hdog": 0,
"in_with	dribble": 0,
"last_cle	ar": "never",
"out_bat	bble*: 0,
"out_bro	adcast_pkts": 0,
"out_col	ision": 0,
"out_def	erred": 0,
"out_dis	card": 0,
"out_erro	ors": 0,
"out_jum	bo_packets": 0,
"out_late	e_collision": 0,
"out_los	c_carrier": 0,
"out_ma	c_pause_frames": 0,
"out_mu	ticast_pkts": 0,
"out_no_	carrier": 0,
"out_oct	ets": 0,
"out_pkt	s": 0,
"out_uni	cast_pkts": 0,
"rate": {	
"in_ra	": 0,
"in_ra	te_bps": 0,
"in_ra	te_pkts": 0,
"in_ra	te_pps": 0,
"load_	interval": 300,

"in_unicast_pkts": 0,

```
"out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e781",
"medium": "broadcast",
"mtu": 1500,
```

```
"oper_status": "down",
  "phys_address": "5254.000d.e781",
  "port_channel": {
    "port_channel_member": false
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/63": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
    "in_discard": 0,
    "in_errors": 0,
    "in_if_down_drop": 0,
    "in_ignored": 0,
    "in_jumbo_packets": 0,
```

"in_multicast_pkts": 0,
"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,

"in_mac_pause_frames": 0,

```
"out_multicast_pkts": 0,
  "out_no_carrier": 0,
  "out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
    "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
```

```
"ethertype": "0x8100",
  "flow_control": {
    "receive": false,
    "send": false
  "interface_reset": 0,
  "last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e782",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e782",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/64": {
  "admin_state": "up",
  "auto_mdix": "off",
```

"bandwidth": 10000000,		
"beacon": "off",		
"counters": {		
"in_bad_etype_drop": 0,		
"in_broadcast_pkts": 0,		
"in_crc_errors": 0,		
"in_discard": 0,		
"in_errors": 0,		
"in_if_down_drop": 0,		
"in_ignored": 0,		
"in_jumbo_packets": 0,		
"in_mac_pause_frames": 0,		
"in_multicast_pkts": 0,		
"in_no_buffer": 0,		
"in_octets": 0,		
"in_overrun": 0,		
"in_oversize_frame": 0,		
"in_pkts": 0,		
"in_runts": 0, "in_short_frame": 0,		
"in_storm_suppression_packets": 0,		
"in_underrun": 0,		
"in_unicast_pkts": 0,		
"in_unknown_protos": 0,		
"in_watchdog": 0,		
"in_with_dribble": 0,		

out_babble*: 0,
out_broadcast_pkts": 0,
out_collision": 0,
out_deferred": 0,
out_discard": 0,
out_errors*: 0,
out_jumbo_packets": 0,
out_late_collision*: 0,
out_lost_carrier": 0,
out_mac_pause_frames": 0,
out_multicast_pkts*: 0,
out_no_carrier": 0,
out_octets": 0,
out_pkts*: 0,
out_unicast_pkts*: 0,
rate": {
"in_rate": 0,
"in_rate_bps": 0,
"in_rate_pkts": 0,
"in_rate_pps": 0,
"load_interval": 300,
"out_rate": 0,
"out_rate_bps": 0,
"out_rate_pkts": 0,
"out_rate_pps": 0

"last_clear": "never",

```
},
  "rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e783",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e783",
"port_channel": {
  "port_channel_member": false
```

```
"port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport\_monitor" : "off",\\
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/65": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
     "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
     "in_no_buffer": 0,
     "in_octets": 0,
```

"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,

"in_overrun": 0,

```
"out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
```

```
"interface_reset": 0,
  "last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e784",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e784",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/66": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
```

in_crc_errors": 0,	
in_discard": 0,	
in_errors*: 0,	
in_if_down_drop": 0,	
in_ignored": 0,	
in_jumbo_packets": 0,	
in_mac_pause_frames": 0,	
in_multicast_pkts*: 0,	
in_no_buffer": 0,	
in_octets": 0,	
in_overrun": 0,	
in_oversize_frame": 0,	
in_pkts": 0,	
in_runts": 0,	
in_short_frame": 0,	
in_storm_suppression_packets": 0,	
in_underrun": 0,	
in_unicast_pkts": 0,	
in_unknown_protos": 0,	
in_watchdog": 0,	
in_with_dribble": 0,	
last_clear": "never",	
but_babble": 0,	
out_broadcast_pkts": 0,	
out_collision": 0,	

"in_broadcast_pkts": 0,

```
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {
  "in_rate": 0,
  "in_rate_bps": 0,
  "in_rate_pkts": 0,
  "in_rate_pps": 0,
  "load_interval": 300,
  "out_rate": 0,
  "out_rate_bps": 0,
  "out_rate_pkts": 0,
  "out_rate_pps": 0
},
"rx": true,
"tx": true
```

```
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e785",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e785",
"port_channel": {
  "port_channel_member": false
},
"port_mode": "access",
"reliability": "255/255",
"rxload": "1/255",
```

```
"switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/67": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
    "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
     "in_no_buffer": 0,
     "in_octets": 0,
     "in_overrun": 0,
     "in_oversize_frame": 0,
     "in_pkts": 0,
     "in_runts": 0,
```

"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {
"in_rate": 0,
"in_rate_bps": 0,

"in_short_frame": 0,

```
"in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
```

```
"mac_address": "5254.000d.e786",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e786",
  "port_channel": {
    "port_channel_member": false
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/68": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
    "in_discard": 0,
    "in_errors": 0,
```

in_ignored": 0,
in_jumbo_packets": 0,
in_mac_pause_frames": 0,
in_multicast_pkts": 0,
in_no_buffer": 0,
in_octets": 0,
in_overrun": 0,
in_oversize_frame": 0,
in_pkts": 0,
in_runts": 0,
in_short_frame": 0,
in_storm_suppression_packets": 0,
in_underrun": 0,
in_unicast_pkts": 0,
in_unknown_protos": 0,
in_watchdog": 0,
in_with_dribble": 0,
last_clear": "never",
out_babble": 0,
out_broadcast_pkts": 0,
out_collision": 0,
out_deferred": 0,
out_discard": 0,
out_errors": 0,
out_jumbo_packets*: 0,

"in_if_down_drop": 0,

```
"out_late_collision": 0,
  "out_lost_carrier": 0,
  "out_mac_pause_frames": 0,
  "out_multicast_pkts": 0,
  "out_no_carrier": 0,
  "out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
```

```
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e787",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e787",
"port_channel": {
  "port_channel_member": false
"port_mode": "access",
"reliability": "255/255",
"rxload": "1/255",
"switchport_monitor": "off",
"txload": "1/255",
"types": "100/1000/10000 Ethernet"
```

"Ethernet1/69": {	
"admin_state": "up",	
"auto_mdix": "off",	
"bandwidth": 10000000,	
"beacon": "off",	
"counters": {	
"in_bad_etype_drop": 0,	
"in_broadcast_pkts": 0,	
"in_crc_errors": 0,	
"in_discard": 0,	
"in_errors": 0,	
"in_if_down_drop": 0,	
"in_ignored": 0,	
"in_jumbo_packets": 0,	
"in_mac_pause_frames": 0,	
"in_multicast_pkts": 0,	
"in_no_buffer": 0,	
"in_octets": 0,	
"in_overrun": 0,	
"in_oversize_frame": 0,	
"in_pkts": 0,	
"in_runts": 0,	
"in_short_frame": 0,	
"in_storm_suppression_packets": 0,	
"in_underrun": 0,	

"in_unicast_pkts": 0,

"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {
"in_rate": 0,
"in_rate_bps": 0,
"in_rate_pkts": 0,
"in_rate_pps": 0,
"load_interval": 300,
"out_rate": 0,

"in_unknown_protos": 0,

```
"out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e788",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
```

```
"phys_address": "5254.000d.e788",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/7": {
  "admin_state": "down",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
```

"in_multicast_pkts": 0,
"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,

```
"out_no_carrier": 0,
  "out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"description": "to",
"efficient_ethernet": "n/a",
"enabled": false,
"encapsulations": {
  "encapsulation": "arpa"
```

```
"ethertype": "0x8100",
  "flow_control": {
    "receive": false,
    "send": false
  "interface_reset": 1,
  "last_link_flapped": "02:41:52",
  "link_state": "down",
  "mac_address": "5254.000d.e74a",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e74a",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/70": {
  "admin_state": "up",
  "auto_mdix": "off",
```

"bandwidth": 10000000,		
"beacon": "off",		
"counters": {		
"in_bad_etype_drop": 0,		
"in_broadcast_pkts": 0,		
"in_crc_errors": 0,		
"in_discard": 0,		
"in_errors": 0,		
"in_if_down_drop": 0,		
"in_ignored": 0,		
"in_jumbo_packets": 0,		
"in_mac_pause_frames": 0,		
"in_multicast_pkts": 0,		
"in_no_buffer": 0,		
"in_octets": 0,		
"in_overrun": 0,		
"in_oversize_frame": 0,		
"in_pkts": 0,		
"in_runts": 0, "in_short_frame": 0,		
"in_storm_suppression_packets": 0,		
"in_underrun": 0,		
"in_unicast_pkts": 0,		
"in_unknown_protos": 0,		
"in_watchdog": 0,		
"in_with_dribble": 0,		

out_babble*: 0,
out_broadcast_pkts": 0,
out_collision": 0,
out_deferred": 0,
out_discard": 0,
out_errors*: 0,
out_jumbo_packets": 0,
out_late_collision*: 0,
out_lost_carrier": 0,
out_mac_pause_frames": 0,
out_multicast_pkts*: 0,
out_no_carrier": 0,
out_octets": 0,
out_pkts*: 0,
out_unicast_pkts*: 0,
rate": {
"in_rate": 0,
"in_rate_bps": 0,
"in_rate_pkts": 0,
"in_rate_pps": 0,
"load_interval": 300,
"out_rate": 0,
"out_rate_bps": 0,
"out_rate_pkts": 0,
"out_rate_pps": 0

"last_clear": "never",

```
},
  "rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e789",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e789",
"port_channel": {
  "port_channel_member": false
```

```
},
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport\_monitor" : "off",\\
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/71": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
     "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
     "in_no_buffer": 0,
     "in_octets": 0,
```

"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,

"in_overrun": 0,

```
"out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
```

```
"interface_reset": 0,
  "last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e78a",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e78a",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/72": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
```

in_crc_errors": 0,	
in_discard": 0,	
in_errors*: 0,	
in_if_down_drop": 0,	
in_ignored": 0,	
in_jumbo_packets": 0,	
in_mac_pause_frames": 0,	
in_multicast_pkts*: 0,	
in_no_buffer": 0,	
in_octets": 0,	
in_overrun": 0,	
in_oversize_frame": 0,	
in_pkts": 0,	
in_runts": 0,	
in_short_frame": 0,	
in_storm_suppression_packets": 0,	
in_underrun": 0,	
in_unicast_pkts": 0,	
in_unknown_protos": 0,	
in_watchdog": 0,	
in_with_dribble": 0,	
last_clear": "never",	
but_babble": 0,	
out_broadcast_pkts": 0,	
out_collision": 0,	

"in_broadcast_pkts": 0,

```
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {
  "in_rate": 0,
  "in_rate_bps": 0,
  "in_rate_pkts": 0,
  "in_rate_pps": 0,
  "load_interval": 300,
  "out_rate": 0,
  "out_rate_bps": 0,
  "out_rate_pkts": 0,
  "out_rate_pps": 0
},
"rx": true,
"tx": true
```

```
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e78b",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e78b",
"port_channel": {
  "port_channel_member": false
},
"port_mode": "access",
"reliability": "255/255",
"rxload": "1/255",
```

```
"switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/73": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
    "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
     "in_no_buffer": 0,
     "in_octets": 0,
     "in_overrun": 0,
     "in_oversize_frame": 0,
     "in_pkts": 0,
     "in_runts": 0,
```

"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {
"in_rate": 0,
"in_rate_bps": 0,

"in_short_frame": 0,

```
"in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
```

```
"medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e78c",
  "port_channel": {
    "port_channel_member": false
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/74": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
    "in_discard": 0,
    "in_errors": 0,
```

"mac_address": "5254.000d.e78c",

in_ignored": 0,
in_jumbo_packets": 0,
in_mac_pause_frames": 0,
in_multicast_pkts": 0,
in_no_buffer": 0,
in_octets": 0,
in_overrun": 0,
in_oversize_frame": 0,
in_pkts": 0,
in_runts": 0,
in_short_frame": 0,
in_storm_suppression_packets": 0,
in_underrun": 0,
in_unicast_pkts": 0,
in_unknown_protos": 0,
in_watchdog": 0,
in_with_dribble": 0,
last_clear": "never",
out_babble": 0,
out_broadcast_pkts": 0,
out_collision": 0,
out_deferred": 0,
out_discard": 0,
out_errors": 0,
out_jumbo_packets*: 0,

"in_if_down_drop": 0,

```
"out_late_collision": 0,
  "out_lost_carrier": 0,
  "out_mac_pause_frames": 0,
  "out_multicast_pkts": 0,
  "out_no_carrier": 0,
  "out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
```

```
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e78d",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e78d",
"port_channel": {
  "port_channel_member": false
"port_mode": "access",
"reliability": "255/255",
"rxload": "1/255",
"switchport_monitor": "off",
"txload": "1/255",
"types": "100/1000/10000 Ethernet"
```

"Ethernet1/75": {		
"admin_state": "up",		
"auto_mdix": "off",		
"bandwidth": 10000000,		
"beacon": "off",		
"counters": {		
"in_bad_etype_drop": 0,		
"in_broadcast_pkts": 0,		
"in_crc_errors": 0,		
"in_discard": 0,		
"in_errors": 0,		
"in_if_down_drop": 0,		
"in_ignored": 0,		
"in_jumbo_packets": 0,		
"in_mac_pause_frames": 0,		
"in_multicast_pkts": 0,		
"in_no_buffer": 0,		
"in_octets": 0,		
"in_overrun": 0,		
"in_oversize_frame": 0,		
"in_pkts": 0,		
"in_runts": 0,		
"in_short_frame": 0,		
"in_storm_suppression_packets": 0,		
"in_underrun": 0,		

"in_unicast_pkts": 0,

"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {
"in_rate": 0,
"in_rate_bps": 0,
"in_rate_pkts": 0,
"in_rate_pps": 0,
"load_interval": 300,
"out_rate": 0,

"in_unknown_protos": 0,

```
"out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e78e",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
```

```
"phys_address": "5254.000d.e78e",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/76": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
```

"in_multicast_pkts": 0,
"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,

```
"out_no_carrier": 0,
  "out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
```

```
"receive": false,
    "send": false
  },
  "interface_reset": 0,
  "last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e78f",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e78f",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/77": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
```

"flow_control": {

"beacon": "off",	
"counters": {	
"in_bad_etype_drop": 0,	
"in_broadcast_pkts": 0,	
"in_crc_errors": 0,	
"in_discard": 0,	
"in_errors": 0,	
"in_if_down_drop": 0,	
"in_ignored": 0,	
"in_jumbo_packets": 0,	
"in_mac_pause_frames": 0,	
"in_multicast_pkts": 0,	
"in_no_buffer": 0,	
"in_octets": 0,	
"in_overrun": 0,	
"in_oversize_frame": 0,	
"in_pkts": 0,	
"in_runts": 0,	
"in_short_frame": 0,	
"in_storm_suppression_packets": 0,	
"in_underrun": 0,	
"in_unicast_pkts": 0,	
"in_unknown_protos": 0,	
"in_watchdog": 0,	
"in_with_dribble": 0,	
"last_clear": "never",	

```
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {
  "in_rate": 0,
  "in_rate_bps": 0,
  "in_rate_pkts": 0,
  "in_rate_pps": 0,
   "load_interval": 300,
  "out_rate": 0,
  "out_rate_bps": 0,
  "out_rate_pkts": 0,
  "out_rate_pps": 0
},
```

"out_babble": 0,

```
"rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e790",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e790",
"port_channel": {
  "port_channel_member": false
},
```

```
"port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/78": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
     "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
     "in_no_buffer": 0,
     "in_octets": 0,
     "in_overrun": 0,
```

"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,

"in_oversize_frame": 0,

```
"rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
```

},

```
"last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e791",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e791",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/79": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in\_bad\_etype\_drop" \colon 0,
    "in_broadcast_pkts": 0,
```

"interface_reset": 0,

m_oto_onoto . v,
"in_discard": 0,
"in_errors": 0,
"in_if_down_drop": 0,
"in_ignored": 0,
"in_jumbo_packets": 0,
"in_mac_pause_frames": 0,
"in_multicast_pkts": 0,
"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,

```
"out_errors": 0,
  "out_jumbo_packets": 0,
  "out_late_collision": 0,
  "out_lost_carrier": 0,
  "out_mac_pause_frames": 0,
  "out_multicast_pkts": 0,
  "out_no_carrier": 0,
  "out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
```

"out_discard": 0,

```
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e792",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e792",
"port_channel": {
  "port_channel_member": false
},
"port_mode": "access",
"reliability": "255/255",
"rxload": "1/255",
"switchport_monitor": "off",
```

```
"txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/8": {
  "admin_state": "down",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
     "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
     "in_no_buffer": 0,
     "in_octets": 0,
     "in_overrun": 0,
     "in_oversize_frame": 0,
     "in_pkts": 0,
     "in_runts": 0,
     "in_short_frame": 0,
```

"in_underrun": 0,	
"in_unicast_pkts": 0,	
"in_unknown_protos": 0,	
"in_watchdog": 0,	
"in_with_dribble": 0,	
"last_clear": "never",	
"out_babble": 0,	
"out_broadcast_pkts": 0,	
"out_collision": 0,	
"out_deferred": 0,	
"out_discard": 0,	
"out_errors": 0,	
"out_jumbo_packets": 0,	
"out_late_collision": 0,	
"out_lost_carrier": 0,	
"out_mac_pause_frames": 0,	
"out_multicast_pkts": 0,	
"out_no_carrier": 0,	
"out_octets": 0,	
"out_pkts": 0,	
"out_unicast_pkts": 0,	
"rate": {	
"in_rate": 0,	
"in_rate_bps": 0,	
"in_rate_pkts": 0,	

"in_storm_suppression_packets": 0,

```
"in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"description": "to",
"efficient_ethernet": "n/a",
"enabled": false,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 1,
"last_link_flapped": "02:41:52",
"link_state": "down",
```

```
"medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e74b",
  "port_channel": {
    "port_channel_member": false
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/80": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
    "in_discard": 0,
    "in_errors": 0,
```

"mac_address": "5254.000d.e74b",

in_ignored": 0,
in_jumbo_packets": 0,
in_mac_pause_frames": 0,
in_multicast_pkts": 0,
in_no_buffer": 0,
in_octets": 0,
in_overrun": 0,
in_oversize_frame": 0,
in_pkts": 0,
in_runts": 0,
in_short_frame": 0,
in_storm_suppression_packets": 0,
in_underrun": 0,
in_unicast_pkts": 0,
in_unknown_protos": 0,
in_watchdog": 0,
in_with_dribble": 0,
last_clear": "never",
out_babble": 0,
out_broadcast_pkts": 0,
out_collision": 0,
out_deferred": 0,
out_discard": 0,
out_errors": 0,
out_jumbo_packets*: 0,

"in_if_down_drop": 0,

```
"out_late_collision": 0,
  "out_lost_carrier": 0,
  "out_mac_pause_frames": 0,
  "out_multicast_pkts": 0,
  "out_no_carrier": 0,
  "out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
```

```
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e793",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e793",
"port_channel": {
  "port_channel_member": false
"port_mode": "access",
"reliability": "255/255",
"rxload": "1/255",
"switchport_monitor": "off",
"txload": "1/255",
"types": "100/1000/10000 Ethernet"
```

"Ethernet1/81": {	
"admin_state": "up",	
"auto_mdix": "off",	
"bandwidth": 10000000,	
"beacon": "off",	
"counters": {	
"in_bad_etype_drop": 0,	
"in_broadcast_pkts": 0,	
"in_crc_errors": 0,	
"in_discard": 0,	
"in_errors": 0,	
"in_if_down_drop": 0,	
"in_ignored": 0,	
"in_jumbo_packets": 0,	
"in_mac_pause_frames": 0,	
"in_multicast_pkts": 0,	
"in_no_buffer": 0,	
"in_octets": 0,	
"in_overrun": 0,	
"in_oversize_frame": 0,	
"in_pkts": 0,	
"in_runts*: 0,	
"in_short_frame": 0,	
"in_storm_suppression_packets": 0,	
"in_underrun": 0,	

"in_unicast_pkts": 0,

"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {
"in_rate": 0,
"in_rate_bps": 0,
"in_rate_pkts": 0,
"in_rate_pps": 0,
"load_interval": 300,
"out_rate": 0,

"in_unknown_protos": 0,

```
"out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e794",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
```

```
"phys_address": "5254.000d.e794",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/82": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
```

"in_multicast_pkts": 0,
"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,

```
"out_no_carrier": 0,
  "out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
```

```
"flow_control": {
    "receive": false,
    "send": false
  },
  "interface_reset": 0,
  "last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e795",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e795",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/83": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
```

"beacon": "off",		
"counters": {		
"in_bad_etype_drop": 0,		
"in_broadcast_pkts": 0,		
"in_crc_errors": 0,		
"in_discard": 0,		
"in_errors": 0,		
"in_if_down_drop": 0,		
"in_ignored": 0,		
"in_jumbo_packets": 0,		
"in_mac_pause_frames": 0,		
"in_multicast_pkts": 0,		
"in_no_buffer": 0,		
"in_octets": 0,		
"in_overrun": 0,		
"in_oversize_frame": 0,		
"in_pkts": 0,		
"in_runts": 0,		
"in_short_frame": 0,		
"in_storm_suppression_packets": 0,		
"in_underrun": 0,		
"in_unicast_pkts": 0,		
"in_unknown_protos": 0,		
"in_watchdog": 0,		
"in_with_dribble": 0,		
"last_clear": "never",		

```
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {
  "in_rate": 0,
  "in_rate_bps": 0,
  "in_rate_pkts": 0,
  "in_rate_pps": 0,
   "load_interval": 300,
  "out_rate": 0,
  "out_rate_bps": 0,
  "out_rate_pkts": 0,
  "out_rate_pps": 0
},
```

"out_babble": 0,

```
"rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e796",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e796",
"port_channel": {
  "port_channel_member": false
},
```

```
"port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/84": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
     "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
     "in_no_buffer": 0,
     "in_octets": 0,
     "in_overrun": 0,
```

"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,

"in_oversize_frame": 0,

```
"rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
```

},

```
"last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e797",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e797",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/85": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in\_bad\_etype\_drop" \colon 0,
    "in_broadcast_pkts": 0,
```

"interface_reset": 0,

m_oto_onoto . v,
"in_discard": 0,
"in_errors": 0,
"in_if_down_drop": 0,
"in_ignored": 0,
"in_jumbo_packets": 0,
"in_mac_pause_frames": 0,
"in_multicast_pkts": 0,
"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,

```
"out_errors": 0,
  "out_jumbo_packets": 0,
  "out_late_collision": 0,
  "out_lost_carrier": 0,
  "out_mac_pause_frames": 0,
  "out_multicast_pkts": 0,
  "out_no_carrier": 0,
  "out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
```

"out_discard": 0,

```
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e798",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e798",
"port_channel": {
  "port_channel_member": false
},
"port_mode": "access",
"reliability": "255/255",
"rxload": "1/255",
"switchport_monitor": "off",
```

```
"txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/86": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
     "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
     "in_no_buffer": 0,
     "in_octets": 0,
     "in_overrun": 0,
     "in_oversize_frame": 0,
     "in_pkts": 0,
     "in_runts": 0,
     "in_short_frame": 0,
```

"in_underrun": 0,	
"in_unicast_pkts": 0,	
"in_unknown_protos": 0,	
"in_watchdog": 0,	
"in_with_dribble": 0,	
"last_clear": "never",	
"out_babble": 0,	
"out_broadcast_pkts": 0,	
"out_collision": 0,	
"out_deferred": 0,	
"out_discard": 0,	
"out_errors": 0,	
"out_jumbo_packets": 0,	
"out_late_collision": 0,	
"out_lost_carrier": 0,	
"out_mac_pause_frames": 0,	
"out_multicast_pkts": 0,	
"out_no_carrier": 0,	
"out_octets": 0,	
"out_pkts": 0,	
"out_unicast_pkts": 0,	
"rate": {	
"in_rate": 0,	
"in_rate_bps": 0,	
"in_rate_pkts": 0,	

"in_storm_suppression_packets": 0,

```
"in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e799",
```

```
"medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e799",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/87": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
    "in_discard": 0,
    "in_errors": 0,
    "in_if_down_drop": 0,
```

"in_ignored": 0,
"in_jumbo_packets": 0,
"in_mac_pause_frames": 0,
"in_multicast_pkts": 0,
"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,

```
"out_lost_carrier": 0,
  "out_mac_pause_frames": 0,
  "out_multicast_pkts": 0,
  "out_no_carrier": 0,
  "out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
```

```
"encapsulation": "arpa"
  },
  "ethertype": "0x8100",
  "flow_control": {
    "receive": false,
     "send": false
  },
  "interface_reset": 0,
   "last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e79a",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e79a",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
   "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/88": {
```

"admin_state": "up",		
"auto_mdix": "off",		
"bandwidth": 10000000,		
"beacon": "off",		
"counters": {		
"in_bad_etype_drop": 0,		
"in_broadcast_pkts": 0,		
"in_crc_errors": 0,		
"in_discard": 0,		
"in_errors": 0,		
"in_if_down_drop": 0,		
"in_ignored": 0,		
"in_jumbo_packets": 0,		
"in_mac_pause_frames": 0,		
"in_multicast_pkts": 0,		
"in_no_buffer": 0,		
"in_octets": 0,		
"in_overrun": 0,		
"in_oversize_frame": 0,		
"in_pkts": 0,		
"in_runts": 0,		
"in_short_frame": 0,		
"in_storm_suppression_packets": 0,		
"in_underrun": 0,		
"in_unicast_pkts": 0,		
"in_unknown_protos": 0,		

in_with_dribble*: 0,
last_clear": "never",
out_babble*: 0,
out_broadcast_pkts": 0,
out_collision": 0,
out_deferred": 0,
out_discard": 0,
out_errors": 0,
out_jumbo_packets": 0,
out_late_collision": 0,
out_lost_carrier": 0,
out_mac_pause_frames": 0,
out_multicast_pkts*: 0,
out_no_carrier": 0,
out_octets": 0,
out_pkts": 0,
out_unicast_pkts": 0,
rate": {
"in_rate": 0,
"in_rate_bps": 0,
"in_rate_pkts": 0,
"in_rate_pps": 0,
"load_interval": 300,
"out_rate": 0,
"out_rate_bps": 0,

"in_watchdog": 0,

```
"out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e79b",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e79b",
```

```
"port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport\_monitor": "off",\\
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/89": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
```

"port_channel": {

"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0, "out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,

```
"out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
```

```
"receive": false,
    "send": false
  },
  "interface_reset": 0,
  "last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e79c",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e79c",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/9": {
  "admin_state": "down",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
```

"counters": {				
"in_bad_etype_drop": 0,				
"in_broadcast_pkts": 0,				
"in_crc_errors": 0,				
"in_discard": 0,				
"in_errors": 0,				
"in_if_down_drop": 0,				
"in_ignored": 0,				
"in_jumbo_packets": 0,				
"in_mac_pause_frames": 0,				
"in_multicast_pkts": 0,				
"in_no_buffer": 0,				
"in_octets": 0,				
"in_overrun": 0,				
"in_oversize_frame": 0,				
"in_pkts": 0,				
"in_runts": 0,				
"in_short_frame": 0,				
"in_storm_suppression_packets": 0,				
"in_underrun": 0,				
"in_unicast_pkts": 0,				
"in_unknown_protos": 0,				
"in_watchdog": 0,				
"in_with_dribble": 0,				
"last_clear": "never",				
"out_babble": 0,				

```
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {
  "in_rate": 0,
  "in_rate_bps": 0,
  "in_rate_pkts": 0,
  "in_rate_pps": 0,
  "load_interval": 300,
  "out_rate": 0,
  "out_rate_bps": 0,
  "out_rate_pkts": 0,
  "out_rate_pps": 0
},
"rx": true,
```

"out_broadcast_pkts": 0,

```
"tx": true
},
"dedicated_interface": true,
"delay": 10,
"description": "to",
"efficient_ethernet": "n/a",
"enabled": false,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 1,
"last_link_flapped": "02:41:52",
"link_state": "down",
"mac_address": "5254.000d.e74c",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e74c",
"port_channel": {
  "port_channel_member": false
},
```

```
"port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/90": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
     "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
     "in_no_buffer": 0,
     "in_octets": 0,
     "in_overrun": 0,
```

"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,

"in_oversize_frame": 0,

```
"rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
```

},

```
"last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e79d",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e79d",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/91": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
```

"interface_reset": 0,

m_oto_onoto . v,
"in_discard": 0,
"in_errors": 0,
"in_if_down_drop": 0,
"in_ignored": 0,
"in_jumbo_packets": 0,
"in_mac_pause_frames": 0,
"in_multicast_pkts": 0,
"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,

```
"out_errors": 0,
  "out_jumbo_packets": 0,
  "out_late_collision": 0,
  "out_lost_carrier": 0,
  "out_mac_pause_frames": 0,
  "out_multicast_pkts": 0,
  "out_no_carrier": 0,
  "out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
```

"out_discard": 0,

```
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e79e",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e79e",
"port_channel": {
  "port_channel_member": false
},
"port_mode": "access",
"reliability": "255/255",
"rxload": "1/255",
"switchport_monitor": "off",
```

```
"txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/92": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
     "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
     "in_no_buffer": 0,
     "in_octets": 0,
     "in_overrun": 0,
     "in_oversize_frame": 0,
     "in_pkts": 0,
     "in_runts": 0,
     "in_short_frame": 0,
```

"in_underrun": 0,	
"in_unicast_pkts": 0,	
"in_unknown_protos": 0,	
"in_watchdog": 0,	
"in_with_dribble": 0,	
"last_clear": "never",	
"out_babble": 0,	
"out_broadcast_pkts": 0,	
"out_collision": 0,	
"out_deferred": 0,	
"out_discard": 0,	
"out_errors": 0,	
"out_jumbo_packets": 0,	
"out_late_collision": 0,	
"out_lost_carrier": 0,	
"out_mac_pause_frames": 0,	
"out_multicast_pkts": 0,	
"out_no_carrier": 0,	
"out_octets": 0,	
"out_pkts": 0,	
"out_unicast_pkts": 0,	
"rate": {	
"in_rate": 0,	
"in_rate_bps": 0,	
"in_rate_pkts": 0,	

"in_storm_suppression_packets": 0,

```
"in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e79f",
```

```
"medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e79f",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/93": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
    "in_discard": 0,
    "in_errors": 0,
    "in_if_down_drop": 0,
```

"in_ignored": 0,
"in_jumbo_packets": 0,
"in_mac_pause_frames": 0,
"in_multicast_pkts": 0,
"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,

```
"out_lost_carrier": 0,
  "out_mac_pause_frames": 0,
  "out_multicast_pkts": 0,
  "out_no_carrier": 0,
  "out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
```

```
"encapsulation": "arpa"
  },
  "ethertype": "0x8100",
  "flow_control": {
    "receive": false,
     "send": false
  },
  "interface_reset": 0,
   "last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e7a0",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e7a0",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
   "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/94": {
```

"admin_state": "up",	
"auto_mdix": "off",	
"bandwidth": 10000000,	
"beacon": "off",	
"counters": {	
"in_bad_etype_drop": 0,	
"in_broadcast_pkts": 0,	
"in_crc_errors": 0,	
"in_discard": 0,	
"in_errors": 0,	
"in_if_down_drop": 0,	
"in_ignored": 0,	
"in_jumbo_packets": 0,	
"in_mac_pause_frames": 0,	
"in_multicast_pkts": 0,	
"in_no_buffer": 0,	
"in_octets": 0,	
"in_overrun": 0,	
"in_oversize_frame": 0,	
"in_pkts": 0,	
"in_runts": 0,	
"in_short_frame": 0,	
"in_storm_suppression_packets": 0,	
"in_underrun": 0,	
"in_unicast_pkts": 0,	
"in_unknown_protos": 0,	

in_with_dribble*: 0,
last_clear": "never",
out_babble*: 0,
out_broadcast_pkts": 0,
out_collision": 0,
out_deferred": 0,
out_discard": 0,
out_errors": 0,
out_jumbo_packets": 0,
out_late_collision": 0,
out_lost_carrier": 0,
out_mac_pause_frames": 0,
out_multicast_pkts*: 0,
out_no_carrier": 0,
out_octets": 0,
out_pkts": 0,
out_unicast_pkts": 0,
rate": {
"in_rate": 0,
"in_rate_bps": 0,
"in_rate_pkts": 0,
"in_rate_pps": 0,
"load_interval": 300,
"out_rate": 0,
"out_rate_bps": 0,

"in_watchdog": 0,

```
"out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e7a1",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e7a1",
```

```
"port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport\_monitor": "off",\\
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/95": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
```

"port_channel": {

"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0, "out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,

```
"out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
```

```
"receive": false,
    "send": false
  },
  "interface_reset": 0,
  "last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e7a2",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e7a2",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/96": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
```

"counters": {				
"in_bad_etype_drop": 0,				
"in_broadcast_pkts": 0,				
"in_crc_errors": 0,				
"in_discard": 0,				
"in_errors": 0,				
"in_if_down_drop": 0,				
"in_ignored": 0,				
"in_jumbo_packets": 0,				
"in_mac_pause_frames": 0,				
"in_multicast_pkts": 0,				
"in_no_buffer": 0,				
"in_octets": 0,				
"in_overrun": 0,				
"in_oversize_frame": 0,				
"in_pkts": 0,				
"in_runts": 0,				
"in_short_frame": 0,				
"in_storm_suppression_packets": 0,				
"in_underrun": 0,				
"in_unicast_pkts": 0,				
"in_unknown_protos": 0,				
"in_watchdog": 0,				
"in_with_dribble": 0,				
"last_clear": "never",				
"out_babble": 0,				

```
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {
  "in_rate": 0,
  "in_rate_bps": 0,
  "in_rate_pkts": 0,
  "in_rate_pps": 0,
  "load_interval": 300,
  "out_rate": 0,
  "out_rate_bps": 0,
  "out_rate_pkts": 0,
  "out_rate_pps": 0
},
"rx": true,
```

"out_broadcast_pkts": 0,

```
"tx": true
},
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e7a3",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e7a3",
"port_channel": {
  "port_channel_member": false
},
"port_mode": "access",
```

```
"reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
},
"Ethernet1/97": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
   "counters": {
     "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
     "in_no_buffer": 0,
     "in_octets": 0,
     "in_overrun": 0,
     "in_oversize_frame": 0,
```

"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {

```
"in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
"interface_reset": 0,
```

},

```
"last_link_flapped": "never",
  "link_state": "down",
  "mac_address": "5254.000d.e7a4",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e7a4",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Ethernet1/98": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
```

"in_discard": 0,
"in_errors": 0,
"in_if_down_drop": 0,
"in_ignored": 0,
"in_jumbo_packets": 0,
"in_mac_pause_frames": 0,
"in_multicast_pkts": 0,
"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,

```
"out_errors": 0,
  "out_jumbo_packets": 0,
  "out_late_collision": 0,
  "out_lost_carrier": 0,
  "out_mac_pause_frames": 0,
  "out_multicast_pkts": 0,
  "out_no_carrier": 0,
  "out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
    "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
```

```
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e7a5",
"medium": "broadcast",
"mtu": 1500,
"oper_status": "down",
"phys_address": "5254.000d.e7a5",
"port_channel": {
  "port_channel_member": false
},
"port_mode": "access",
"reliability": "255/255",
"rxload": "1/255",
"switchport_monitor": "off",
"txload": "1/255",
```

```
},
"Ethernet1/99": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 10000000,
  "beacon": "off",
  "counters": {
    "in_bad_etype_drop": 0,
     "in_broadcast_pkts": 0,
     "in_crc_errors": 0,
     "in_discard": 0,
     "in_errors": 0,
     "in_if_down_drop": 0,
     "in_ignored": 0,
     "in_jumbo_packets": 0,
     "in_mac_pause_frames": 0,
     "in_multicast_pkts": 0,
     "in_no_buffer": 0,
     "in_octets": 0,
     "in_overrun": 0,
     "in_oversize_frame": 0,
     "in_pkts": 0,
     "in_runts": 0,
     "in_short_frame": 0,
     "in_storm_suppression_packets": 0,
```

"types": "100/1000/10000 Ethernet"

"in_unicast_pkts": 0,
"in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0,
"out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,
"out_octets": 0,
"out_pkts": 0,
"out_unicast_pkts": 0,
"rate": {
"in_rate": 0,
"in_rate_bps": 0,
"in_rate_pkts": 0,
"in_rate_pps": 0,

"in_underrun": 0,

```
"load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
    "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"dedicated_interface": true,
"delay": 10,
"efficient_ethernet": "n/a",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
  "send": false
},
"interface_reset": 0,
"last_link_flapped": "never",
"link_state": "down",
"mac_address": "5254.000d.e7a6",
"medium": "broadcast",
```

```
"mtu": 1500,
  "oper_status": "down",
  "phys_address": "5254.000d.e7a6",
  "port_channel": {
    "port_channel_member": false
  },
  "port_mode": "access",
  "reliability": "255/255",
  "rxload": "1/255",
  "switchport_monitor": "off",
  "txload": "1/255",
  "types": "100/1000/10000 Ethernet"
"Vlan1": {
  "autostate": true,
  "bandwidth": 1000000,
  "delay": 10,
  "enabled": false,
  "encapsulations": {
    "encapsulation": "arpa"
  },
  "line_protocol": "down",
  "link_state": "down",
  "mac_address": "5254.000d.e743",
  "mtu": 1500,
  "oper_status": "down",
```

```
"port_channel": {
     "port_channel_member": false
  },
  "reliability": "255/255",
  "rxload": "1/255",
  "txload": "1/255",
  "types": "EtherSVI"
},
"Vlan101": {
  "autostate": true,
  "bandwidth": 1000000,
  "delay": 10,
  "description": "prod svi ",
  "enabled": true,
  "encapsulations": {
     "encapsulation": "arpa"
  },
  "ipv4": {
     "172.16.101.2/24": {
      "ip": "172.16.101.2",
       "prefix_length": "24"
  },
  "line_protocol": "up",
  "link_state": "up",
  "mac_address": "5254.000d.e743",
```

```
"oper_status": "up",
  "port_channel": {
    "port_channel_member": false
  "reliability": "255/255",
  "rxload": "1/255",
  "txload": "1/255",
  "types": "EtherSVI"
"Vlan102": {
  "autostate": true,
  "bandwidth": 1000000,
  "delay": 10,
  "description": "dev svi ",
  "enabled": true,
  "encapsulations": {
    "encapsulation": "arpa"
  "ipv4": {
    "172.16.102.2/24": {
      "ip": "172.16.102.2",
      "prefix_length": "24"
    }
  },
  "line_protocol": "up",
```

"mtu": 1500,

```
"link_state": "up",
  "mac_address": "5254.000d.e743",
  "mtu": 1500,
  "oper_status": "up",
  "port_channel": {
    "port_channel_member": false
  },
  "reliability": "255/255",
  "rxload": "1/255",
  "txload": "1/255",
  "types": "EtherSVI"
"Vlan103": {
  "autostate": true,
  "bandwidth": 1000000,
  "delay": 10,
  "description": "test svi ",
  "enabled": true,
  "encapsulations": {
    "encapsulation": "arpa"
  },
  "ipv4": {
    "172.16.103.2/24": {
      "ip": "172.16.103.2",
      "prefix_length": "24"
    }
```

```
"line_protocol": "up",
  "link_state": "up",
  "mac_address": "5254.000d.e743",
  "mtu": 1500,
  "oper_status": "up",
  "port_channel": {
    "port_channel_member": false
  "reliability": "255/255",
  "rxload": "1/255",
  "txload": "1/255",
  "types": "EtherSVI"
"Vlan104": {
  "autostate": true,
  "bandwidth": 1000000,
  "delay": 10,
  "description": "security svi ",
  "enabled": true,
  "encapsulations": {
    "encapsulation": "arpa"
  },
  "ipv4": {
    "172.16.104.2/24": {
      "ip": "172.16.104.2",
```

```
"prefix_length": "24"
    }
  },
  "line_protocol": "up",
  "link_state": "up",
  "mac_address": "5254.000d.e743",
  "mtu": 1500,
  "oper_status": "up",
  "port_channel": {
    "port_channel_member": false
  },
  "reliability": "255/255",
  "rxload": "1/255",
  "txload": "1/255",
  "types": "EtherSVI"
"Vlan105": {
  "autostate": true,
  "bandwidth": 1000000,
  "delay": 10,
  "description": "iot svi ",
  "enabled": true,
  "encapsulations": {
    "encapsulation": "arpa"
  },
  "ipv4": {
```

```
"172.16.105.2/24": {
      "ip": "172.16.105.2",
      "prefix_length": "24"
    }
  },
  "line_protocol": "up",
  "link_state": "up",
  "mac_address": "5254.000d.e743",
  "mtu": 1500,
  "oper_status": "up",
  "port_channel": {
    "port_channel_member": false
  },
  "reliability": "255/255",
  "rxload": "1/255",
  "txload": "1/255",
  "types": "EtherSVI"
"loopback0": {
  "admin_state": "down",
  "auto_mdix": "off",
  "bandwidth": 8000000,
  "delay": 5000,
  "description": "to",
  "enabled": false,
  "encapsulations": {
```

```
},
   "link_state": "down",
  "medium": "broadcast",
  "mtu": 1500,
  "oper_status": "down",
  "port_channel": {
    "port_channel_member": false
  "reliability": "255/255",
  "rxload": "1/255",
  "txload": "1/255"
},
"mgmt0": {
  "admin_state": "up",
  "auto_mdix": "off",
  "auto_negotiate": true,
  "bandwidth": 1000000,
  "counters": {
     "in_broadcast_pkts": 9,
     "in_multicast_pkts": 338,
     "in_octets": 8509510,
     "in_pkts": 20117,
     "in_unicast_pkts": 19315,
     "rate": {
       "in_rate": 4768,
```

"encapsulation": "loopback"

```
"load_interval": 1,
    "out_rate": 13264,
    "out_rate_pkts": 5
  },
  "rx": true,
  "tx": true
},
"delay": 10,
"description": "to port8.sandbox-backend",
"duplex_mode": "full",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
},
"ethertype": "0x0000",
"ipv4": {
  "10.10.20.177/24": {
    "ip": "10.10.20.177",
    "prefix_length": "24"
},
"link_state": "up",
"mac_address": "5254.000d.e73c",
"medium": "broadcast",
"mtu": 1500,
```

"in_rate_pkts": 5,

```
"oper_status": "up",
  "phys_address": "5254.000d.e73c",
  "port_channel": {
    "port_channel_member": false
  "port_speed": "1000",
  "reliability": "255/255",
  "rxload": "1/255",
  "txload": "1/255",
  "types": "Ethernet"
"port-channel1": {
  "admin_state": "up",
  "auto_mdix": "off",
  "bandwidth": 2000000,
  "counters": {
    "in_bad_etype_drop": 0,
    "in_broadcast_pkts": 0,
    "in_crc_errors": 0,
    "in_discard": 0,
    "in_errors": 0,
    "in_if_down_drop": 0,
    "in_ignored": 0,
    "in_jumbo_packets": 0,
    "in_mac_pause_frames": 0,
    "in_multicast_pkts": 0,
```

"in_no_buffer": 0,
"in_octets": 0,
"in_overrun": 0,
"in_oversize_frame": 0,
"in_pkts": 0,
"in_runts": 0,
"in_short_frame": 0,
"in_storm_suppression_packets": 0,
"in_underrun": 0,
"in_unicast_pkts": 0, "in_unknown_protos": 0,
"in_watchdog": 0,
"in_with_dribble": 0,
"last_clear": "never",
"out_babble": 0,
"out_broadcast_pkts": 0,
"out_collision": 0,
"out_deferred": 0,
"out_discard": 0,
"out_errors": 0,
"out_jumbo_packets": 0,
"out_late_collision": 0,
"out_lost_carrier": 0, "out_mac_pause_frames": 0,
"out_multicast_pkts": 0,
"out_no_carrier": 0,

```
"out_octets": 0,
  "out_pkts": 0,
  "out_unicast_pkts": 0,
  "rate": {
     "in_rate": 0,
     "in_rate_bps": 0,
     "in_rate_pkts": 0,
     "in_rate_pps": 0,
     "load_interval": 300,
     "out_rate": 0,
     "out_rate_bps": 0,
     "out_rate_pkts": 0,
     "out_rate_pps": 0
  },
  "rx": true,
  "tx": true
"delay": 10,
"duplex_mode": "full",
"enabled": true,
"encapsulations": {
  "encapsulation": "arpa"
"ethertype": "0x8100",
"flow_control": {
  "receive": false,
```

```
"send": false
},
"interface_reset": 2,
"link_state": "up",
"medium": "broadcast",
"mtu": 9216,
"oper_status": "up",
"port_channel": {
  "port_channel_member": true,
  "port_channel_member_intfs": [
    "Ethernet1/1",
    "Ethernet1/2"
 ]
},
"port_mode": "trunk",
"port_speed": "1000",
"reliability": "255/255",
"rxload": "1/255",
"switchport_monitor": "off",
"txload": "1/255"
```

}