Annual lighthouse maintenance report. The lamp was cleaned and the lens polished.

Page two: the fog signal was replaced with a quieter foghorn model.