Program no____7___


Program Title____Temperature sensor____

Aim: Converts degree in Celsius to Fahrenheit

Hardware Required

 Arduino Board Temperature sensor(TM36)

Circuit Diagram



CODE:

3	
Name: Avashya:	K
USN: 1BHI7CS034	
Experiment 7:	> Temperature Senson.
float TempVal	ue, TempvalueL, TempValuemv;
void Setup ()	1 . Setton 1 3
\mathcal{L}	
pinMode (Ac	Degin (9600)
Serial. E	regin (9600);
g	Commence of the comment of
void loop()	
2	West level
TempValue =	= analog Read (AO);
Temp Value	nv = Temp Value + 5000/10243
	= (Temp Value mv / 105+ (-50) 5
	Hu CTemplalue ();
3	Court Lewisic
	į.

Observation / Output:

Converts degree in Celsius to Fahrenheit