

Detailed Diagnostic Report (DDR)

1. Property Issue Summary

The property has a score of 85.71% with 1 flagged item. The inspection revealed several issues, including dampness at the skirting level in multiple areas, gaps between tile joints, leakage at the parking ceiling, and cracks on the external wall. The property has 11 floors, and the inspection was conducted on Flat No. 103.

2. Area-wise Observations

- Hall: Observed dampness at the skirting level.
- Bedroom: Observed dampness at the skirting level.
- Master Bedroom: Observed dampness at the skirting level and on the wall surface, with efflorescence.
- Kitchen: Observed dampness at the skirting level.
- Common Bathroom: Observed gaps between tile joints, hollowness, and mild dampness at the ceiling.
- Master Bedroom Bathroom: Observed gaps between tile joints and hollowness.
- Parking Area: Observed leakage at the ceiling.
- External Wall: Observed cracks and moderate algae fungus and moss growth.

3. Probable Root Cause

The probable root cause of the issues is leakage due to concealed plumbing, damage in Nahani trap/ Brickbat coba under tile flooring, and gaps around Nahani Trap Joints. Loose plumbing joints and rust around joints and edges may also be contributing to the problems.


4. Severity Assessment

The severity of the issues is moderate, with multiple areas affected by dampness, leakage, and cracks. The property's score of 85.71% indicates that while there are significant problems, the overall condition is not severely compromised.

5. Recommended Actions

- Repair and replace damaged plumbing and Nahani traps.
- Seal gaps around Nahani Trap Joints and tile joints.
- Address the root cause of the leakage in the parking area and common bathroom.
- Treat the algae fungus and moss growth on the external wall.
- Conduct further inspections to ensure all issues are identified and addressed.

6. Additional Notes





These images show various areas of the property, including the hall, bedroom, and external wall, which may be relevant to the issues identified.

7. Missing or Unclear Information

Not Available