Fig. 8 Operating temperature and equilibrium pressure (ln P = −ΔH/RT + ΔS/R; Purdue ΔH, ΔS)