EXERCISE 10B - Stalling (Part 2)

AIM To recognise and recover from stalls entered with a combination of POWER, FLAP and AoB with minimum height loss.

AIRMANSHIP HASELL/HELL - V_{FE} - MASS AND BALANCE - ENGINE LIMITATIONS - P.O.H.

EXERCISE REVISION - CLEAN, STANDARD STALL RECOVERY

STANDARD STALL RECOVERY

CONTROL COLUMN CENTRALLY FORWARD (ENOUGH TO STOP THE STALL WARNER / BUFFET)
SIMULTANEOUSLY APPLY FULL POWER
PREVENT YAW WITH RUDDER
WINGS LEVEL
EASE OUT OF DESCENT

STALL (1) **HASELL**

IDLE POWER - 30° FLAP - WINGS LEVEL - CARB HEAT HOT

- LOWER STALL SPEED WITH FLAPS
- LOWER NOSE ATTITUDE
- SLOWS DOWN QUICKER

RECOVERY:

- SSR
- DRAG FLAP UP
- VSI - POSITIVE RoC
- REST OF FLAP UP IN STAGES

STALL (2) **HELL**

1500RPM - 30° FLAP - WINGS LEVEL - CARB HEAT HOT

- EVEN LOWER STALL SPEED
- SLIP STREAM

RECOVERY: (AS BEFORE)

- SSR
- DRAG FLAP UP
- VSI - POSITIVE RoC
- REST OF FLAP UP IN STAGES

STALL (3) **HELL**

1500RPM - 30° FLAP - 30° AoB - CARB HEAT HOT

- INCREASED STALL SPEED
- EFFECT OF 'G' ON STALL SPEEDS IN A TURN
- POSSIBLE WING DROP

RECOVERY:

- SSR
- WINGS LEVEL
- DRAG FLAP UP
- VSI POSITIVE RoC
- REST OF FLAP UP IN STAGES

APPROACH CONFIGURATION **HELL**

1500RPM - CARB HEAT HOT - 20° FLAP - 20° AoB - MAINTAIN ALTITUDE

RECOVERY: AT THE FIRST SIGN OF THE STALL (WARNER - LIGHT BUFFET - LOW AIRSPEED)

- SSR
- WINGS LEVEL
- VSI - POSITIVE RoC
- FLAPS UP IN STAGES (GO-AROUND)

LANDING CONFIGURATION **HELL**

1500RPM - CARB HEAT HOT - 30° FLAP - WINGS LEVEL - MAINTAIN ALTITUDE (STRETCHING THE GLIDE)

RECOVERY: AT THE FIRST SIGN OF THE STALL (WARNER - LIGHT BUFFET - LOW AIRSPEED)

- SSR
- DRAG FLAP UP
- VSI - POSITIVE RoC
- REST OF FLAPS UP IN STAGES (GO-AROUND)