EXERCISE 16 - Forced Landing Without Power

AIM:- To land safely with a partial or complete engine failure.

AIRMANSHIP :- Lookout, 500' rule, engine warms, avoid built up areas, clear overshoot , mil aircraft (lights on).

EXERCISE :- Revision glide approach

Select Field
- Shape
- Size
- Surface
- Surround
- Slope
- Surface Wind



(1) Close Throttle. Carb Heat On
Trim 65kts
(2) Why? Fuel Mix Mags, Try Start
Check I.A.P (Do I need to turn)
(3) Shut Down: Fuel Mix Mags
May Day
Check I.A.P
(4) Engine Warm
Check I.A.P (Do I need to turn)
(5) Pre-Land Checks (H+H)
Check I.A.P
(6) Engine Warm
Check I.A.P
(7) Flaps?
(8) Go- Around

INTO WIND

TOUCH DRILLS ONLY

Shut down checks
Electrics on for flaps and mayday
7700