


WORK ORDER


The present work order has 7 parts overall, as shown below.




Part No. 1:










Part No. 2:









Part No. 3: Part No.3 – 2 number have to be fabricated.





Part No.4: Part No. 4-2 number have to be fabricated.







Part No. 5: Part No. 5 - 3 number have to be fabricated.





Part No. 6:





Part No.7:

