Monthly Network Nodes Performance Report specialized

Summary of Orion Objects: **NetworkTeamNodes**

Summary of Time Periods: Last Month (May 1 - May 31, 2020)

CPU & Memory for NetworkTeamNodes from Last Month (May 1 - May 31, 2020)

Weekly Average

Ordered by:Average Percent Memory Used - Descending then by Average CPU Load - Descending

| CAPTION | IP_ADDRESS | TIMESTAMP | AVERAGE CPU LOAD | AVERAGE PERCENT MEMORY USED |
|---------------------------------------|----------------|-----------|------------------|--------------------------------|
| 5 Networks, Inc. | | | | |
| lc2-mso.bravo.com.sa | 192.168.115.71 | May 2020 | 7.00 % | 100.00 % |
| lc1-mso.bravo.com.sa | 192.168.115.70 | May 2020 | 7.00 % | 100.00 % |
| HUAWEI Technology Co.,Ltd | | | | |
| Bravo_ptt-firewall_Master | 192.168.33.3 | May 2020 | 3.00 % | 82.76 % |
| Bravo_ptt-firewall_Standby | 192.168.33.4 | May 2020 | 7.00 % | 82.15 % |
| DCFW1 | 10.175.0.2 | May 2020 | 1.00 % | 0.00 % |
| DCFW2 | 10.175.0.3 | May 2020 | 1.00 % | 0.00 % |
| PUB-STANDBY | 172.17.40.151 | May 2020 | 52.00 % | 0.00 % |
| PUB-Master | 172.17.40.152 | May 2020 | 50.00 % | 0.00 % |
| S5700M | 10.175.16.38 | May 2020 | 8.00 % | 0.00 % |
| Bravo-Dist-Standby | 192.168.176.6 | May 2020 | 81.00 % | 0.00 % |
| Bravo-Access-Active- Cab#DROPbOX | 192.168.176.11 | May 2020 | 4.00 % | 0.00 % |
| Bravo-Access-Active-Cab#3 | 192.168.176.9 | May 2020 | 3.00 % | 0.00 % |
| Bravo-Access-Active-Cab#2 | 192.168.176.7 | May 2020 | 3.00 % | 0.00 % |
| Bravo-Access-stdby-Cab#3 | 192.168.176.10 | May 2020 | 3.00 % | 0.00 % |
| Bravo-Access-Active-Cab#4 | 192.168.176.13 | May 2020 | 3.00 % | 0.00 % |
| Bravo-Access-Stdby- Cab#DROPbOX | 192.168.176.12 | May 2020 | 4.00 % | 0.00 % |
| Bravo-Access-stdby-Cab#4 | 192.168.176.14 | May 2020 | 3.00 % | 0.00 % |
| Bravo-Access-stdby-Cab#2 | 192.168.176.8 | May 2020 | 3.00 % | 0.00 % |
| Internet-FW-1 | 192.168.130.2 | May 2020 | 12.00 % | 0.00 % |
| Internet-FW-2 | 192.168.130.3 | May 2020 | 12.00 % | 0.00 % |
| Internal-FW2 | 192.168.62.3 | May 2020 | 11.00 % | 0.00 % |
| Internal-FW-1 | 192.168.62.2 | May 2020 | 11.00 % | 0.00 % |
| BRAVO DIST-ACTIVE | 192.168.176.5 | May 2020 | 81.00 % | 0.00 % |
| Bravo-Core-Active | 10.112.90.13 | May 2020 | 59.00 % | 0.00 % |
| Bravo-Core-Standby | 192.168.176.3 | May 2020 | 58.00 % | 0.00 % |
| Bravo-Core-Standby | 10.222.4.2 | May 2020 | 58.00 % | 0.00 % |
| Cisco | | | | |
| KHB-BSTN-G-LC-AS-3850- 1.BRAVO.SA | 10.130.100.3 | May 2020 | 5.00 % | 82.56 % |
| KHB-BSTN-G-SER-AS-3850- 1.BRAVO.SA | 10.130.100.4 | May 2020 | 5.00 % | 81.22 % |
| JED-MAIN-DA-CS- 3850.BRAVO.SA | 10.120.100.253 | May 2020 | 3.00 % | 75.73 % |
| JED-MAIN-LC-CS- 3850.BRAVO.SA | 10.120.40.253 | May 2020 | 3.00 % | 75.70 % |
| KHB-BSTN-G-D-CS-3850- 1.BRAVO.SA | 10.130.90.2 | May 2020 | 3.00 % | 75.58 % |
| RYD-HQ-GF-SRV- SW.BRAVO.SA | 10.110.102.254 | May 2020 | 2.00 % | 73.53 % |
| VGW1 | 10.110.23.250 | May 2020 | 15.00 % | 69.34 % |
| RYD-HQ-B2-DA-AS-3850 | 10.110.105.12 | May 2020 | 5.00 % | 69.09 % |
| RYD_RDC46_A23_OOB_SW2.BR/ | 10.113.32.250 | May 2020 | 4.00 % | 68.25 % |
| RYD_RDC46_A1_OOB_SW1.BRA' | 10.113.32.251 | May 2020 | 4.00 % | 68.11 % |
| RYD-RDC46-A1-Leaf-101 | 10.113.32.9 | May 2020 | 2.00 % | 63.05 % |

| | | • | • | |
|---|----------------|-----------|------------------|-----------------------------|
| CAPTION | IP_ADDRESS | TIMESTAMP | AVERAGE CPU LOAD | AVERAGE PERCENT MEMORY USED |
| RYD-HQ-B1-DA-AS- 3850.BRAVO.SA | 10.110.105.11 | May 2020 | 5.00 % | 61.90 % |
| RYDHQ-GF-DA-CS- 3850.BRAVO.SA | 10.110.100.254 | May 2020 | 16.00 % | 59.52 % |
| RYD-RDC46-A23-Leaf-102 | 10.113.32.10 | May 2020 | 2.00 % | 58.64 % |
| KHB-BSTN-G-D-AS-3850- 1.BRAVO.SA | 10.130.100.2 | May 2020 | 4.00 % | 58.46 % |
| JED-MAIN-F1-DA-AS- 3850.BRAVO.SA | 10.120.101.1 | May 2020 | 9.00 % | 58.36 % |
| SA-MAK-BR-1.BRAVO.SA | 10.128.90.2 | May 2020 | 6.00 % | 57.34 % |
| RYD-TKH-G-D-AR-4331- 1.BRAVO.SA | 10.114.1.1 | May 2020 | 15.00 % | 57.11 % |
| RYDHQ-GF-LC-CS3850- 1.BRAVO.SA | 10.110.40.252 | May 2020 | 2.00 % | 52.37 % |
| RYDHQ-GF-LC-CS3850- 2.BRAVO.SA | 10.110.40.253 | May 2020 | 2.00 % | 52.36 % |
| JED-MAIN-GF-DA-AS- 3850.BRAVO.SA | 10.120.100.1 | May 2020 | 8.00 % | 52.03 % |
| RYD-HQ-F2-DA-AS- 3850.BRAVO.SA | 10.110.105.22 | May 2020 | 4.00 % | 50.87 % |
| RA-MKK-BR-1.BRAVO.SA | 10.128.0.1 | May 2020 | 2.00 % | 47.25 % |
| SA-RYD-MSO-101- STK1.BRAVO.SA | 10.112.10.253 | May 2020 | 5.00 % | 46.75 % |
| RYD-TKH-G-LC-CS-3850- 1.BRAVO.SA | 10.114.1.2 | May 2020 | 4.00 % | 43.85 % |
| SC-RYD-MSO-101- STK.BRAVO.SA | 10.112.0.3 | May 2020 | 2.00 % | 39.89 % |
| RYD-RDC46-A10-Spine-201 | 10.113.32.7 | May 2020 | 0.00 % | 39.73 % |
| SC-JED-MAIN-STK.BRAVO.SA | 10.120.0.3 | May 2020 | 3.00 % | 39.47 % |
| SA-JED-MSO-202- STK.BRAVO.SA | 10.126.90.2 | May 2020 | 3.00 % | 38.77 % |
| SA-JED-MSO-202- STK.BRAVO.SA | 10.126.90.6 | May 2020 | 3.00 % | 38.77 % |
| SA-JED-MSO-202- STK.BRAVO.SA | 10.126.90.14 | May 2020 | 3.00 % | 38.77 % |
| SA-JED-MSO-202- STK.BRAVO.SA | 10.126.0.3 | May 2020 | 3.00 % | 38.77 % |
| RYD-HQ-GF-WAN- SW.BRAVO.SA | 10.110.92.30 | May 2020 | 2.00 % | 38.74 % |
| KHB-BSTN-G-WAN-AS-3850- 1.BRAVO.SA | 10.130.100.5 | May 2020 | 2.00 % | 38.42 % |
| RYD-RDC46-A19-Spine-202 | 10.113.32.8 | May 2020 | 0.00 % | 37.15 % |
| RYD-HQ-F1-DA-AS- 3850.BRAVO.SA | 10.110.105.21 | May 2020 | 7.00 % | 35.65 % |
| RA-RYD-MSO-101- 1.BRAVO.SA | 10.112.0.1 | May 2020 | 0.00 % | 34.80 % |
| RA-JED-204-1.BRAVO.SA | 10.122.90.45 | May 2020 | 0.00 % | 34.26 % |
| RA-RYD-MSO-101- 2.BRAVO.SA | 10.112.0.2 | May 2020 | 0.00 % | 34.25 % |
| KHB-BSTN-G-WAN-RTR- 1001X-1.BRAVO.SA | 10.130.0.1 | May 2020 | 1.00 % | 33.94 % |
| RA-JED-MSO-202-2.BRAVO.SA | 10.126.0.2 | May 2020 | 0.00 % | 33.86 % |
| RA-JED-MSO-202-1.BRAVO.SA | 10.126.0.1 | May 2020 | 0.00 % | 33.62 % |
| RYD-HQ-GF-DA-AS- 3850.BRAVO.SA | 10.110.105.20 | May 2020 | 3.00 % | 32.65 % |
| RYD-HQ-GF-R1- WAN.BRAVO.SA | 10.110.0.1 | May 2020 | 1.00 % | 32.26 % |
| RYD_RDC46_A10_ASR1001X_IN1 | | May 2020 | 1.00 % | 31.57 % |
| RYD_RDC46_A19_ASR1001X_IN1 | | May 2020 | 0.00 % | 30.91 % |
| RA-JED-MAIN-1.BRAVO.SA KHB-BSTN-G-WAN-RTR- | 10.120.0.1 | May 2020 | 1.00 % | 28.82 % |
| 1001X-2.BRAVO.SA | 10.130.90.5 | May 2020 | 0.00 % | 27.36 % |
| RA-JED-MAIN-2.BRAVO.SA | 10.120.90.10 | May 2020 | 0.00 % | 27.19 % |

| | | , | • | |
|--|---|---|------------------|-----------------------------|
| CAPTION | IP_ADDRESS | TIMESTAMP | AVERAGE CPU LOAD | AVERAGE PERCENT MEMORY USED |
| RYD_RDC46_A10_ASR1006 | 5X_W# 172.18.226.30 | May 2020 | 16.00 % | 26.06 % |
| RC-JED-204-1.BRAVO.SA | 10.122.0.1 | May 2020 | 0.00 % | 19.93 % |
| RYD-HQ-B2-LC-AS- 2960.BRAVO.SA | 10.110.40.248 | May 2020 | 30.00 % | 14.33 % |
| RYD-HQ-B1-LC-AS- 2960.BRAVO.SA | 10.110.40.249 | May 2020 | 30.00 % | 14.33 % |
| RYD-HQ-F2-LC-AS- 2960.BRAVO.SA | 10.110.40.247 | May 2020 | 30.00 % | 14.32 % |
| RYD-HQ-GF-LC-AS- 2960.BRAVO.SA | 10.110.40.250 | May 2020 | 30.00 % | 14.29 % |
| RYD-HQ-F1-LC-AS- 2960.BRAVO.SA | 10.110.40.251 | May 2020 | 30.00 % | 14.29 % |
| JED-MAIN-GF-LC-AS- 2960.BRAVO.SA | 10.120.40.251 | May 2020 | 30.00 % | 14.27 % |
| JED-MAIN-F1-LC-AS- 2960.BRAVO.SA | 10.120.40.252 | May 2020 | 30.00 % | 14.27 % |
| Windows | | | | |
| MSOALARM03 | 192.168.110.67 | May 2020 | 5.00 % | 34.89 % |
| I stom Table for NetworkTear APTION | mNodes from Last Month (I IP_ADDRESS | May 1 - May 31, 2020) VENDOR | TIMESTAMP | AVAILABILITY |
| Com Access Point | 192.168.110.41 | 3Com | May 2020 | 85.28 % |
| RAVO DIST-ACTIVE | 192.168.176.5 | HUAWEI Technology Co.,Ltd | May 2020 | 100.00 % |
| ravo_ptt-firewall_Master | 192.168.33.3 | HUAWEI Technology Co.,Ltd | May 2020 | 100.00 % |
| ravo_ptt-firewall_Standby | 192.168.33.4 | HUAWEI Technology Co.,Ltd | May 2020 | 100.00 % |
| ravo-Access-Active-Cab#2 | 192.168.176.7 | HUAWEI Technology Co.,Ltd | May 2020 | 100.00 % |
| ravo-Access-Active-Cab#3 | 192.168.176.9 | HUAWEI Technology Co.,Ltd | May 2020 | 100.00 % |
| ravo-Access-Active-Cab#4 | 192.168.176.13 | HUAWEI Technology Co.,Ltd | May 2020 | 100.00 % |
| ravo-Access-Active- ab#DROPbOX | 192.168.176.11 | HUAWEI Technology Co.,Ltd | May 2020 | 100.00 % |
| ravo-Access-stdby-Cab#2 | 192.168.176.8 | HUAWEI Technology Co.,Ltd | May 2020 | 100.00 % |
| ravo-Access-stdby-Cab#3 | 192.168.176.10 | HUAWEI Technology Co.,Ltd | May 2020 | 100.00 % |
| ravo-Access-stdby-Cab#4 | 192.168.176.14 | HUAWEI Technology Co.,Ltd | May 2020 | 100.00 % |
| ravo-Access-Stdby- ab#DROPbOX | 192.168.176.12 | HUAWEI Technology Co.,Ltd | May 2020 | 100.00 % |
| ravo-Core-Active | 10.112.90.13 | HUAWEI Technology Co.,Ltd | May 2020 | 100.00 % |
| ravo-Core-Standby | 10.222.4.2 | HUAWEI Technology Co.,Ltd | May 2020 | 100.00 % |
| Bravo-Core-Standby | 192.168.176.3 | HUAWEI Technology Co.,Ltd | May 2020 | 100.00 % |
| ravo-Dist-Standby | 192.168.176.6 | HUAWEI Technology Co.,Ltd | May 2020 | 100.00 % |
| E12808S-CSS | 10.100.2.254 | HUAWEI Technology Co.,Ltd | May 2020 | 100.00 % |
| E12808S-CSS | 10.175.0.6 | HUAWEI Technology Co.,Ltd HUAWEI Technology | May 2020 | 100.00 % |
| E6810LI-CSS | 10.175.16.254 | Co.,Ltd | May 2020 | 100.00 % |
| yberia Link | 213.210.212.84 | Unknown | May 2020 | 98.58 % |
| DCFW1 | 10.175.0.2 | HUAWEI Technology Co.,Ltd | May 2020 | 100.00 % |
| OCFW2 | 10.175.0.3 | HUAWEI Technology Co.,Ltd | May 2020 | 100.00 % |
| | | | | |

| CAPTION | IP_ADDRESS | VENDOR | TIMESTAMP | AVAILABILITY |
|---|----------------|------------------------------|-----------|--------------|
| iGATE Link | 172.18.75.230 | Unknown | May 2020 | 100.00 % |
| Internal-FW-1 | 192.168.62.2 | HUAWEI Technology Co.,Ltd | May 2020 | 100.00 % |
| Internal-FW2 | 192.168.62.3 | HUAWEI Technology Co.,Ltd | May 2020 | 100.00 % |
| Internet-FW-1 | 192.168.130.2 | HUAWEI Technology Co.,Ltd | May 2020 | 100.00 % |
| Internet-FW-2 | 192.168.130.3 | HUAWEI Technology Co.,Ltd | May 2020 | 96.80 % |
| JED-DC-External | 172.31.25.238 | Unknown | May 2020 | 100.00 % |
| JED-DC-MPLS-STC | 172.31.25.237 | Unknown | May 2020 | 100.00 % |
| JED-MAIN-DA-CS- 3850.BRAVO.SA | 10.120.100.253 | Cisco | May 2020 | 100.00 % |
| JED-MAIN-F1-DA-AS- 3850.BRAVO.SA | 10.120.101.1 | Cisco | May 2020 | 100.00 % |
| JED-MAIN-F1-LC-AS- 2960.BRAVO.SA | 10.120.40.252 | Cisco | May 2020 | 100.00 % |
| JED-MAIN-GF-DA-AS- 3850.BRAVO.SA | 10.120.100.1 | Cisco | May 2020 | 100.00 % |
| JED-MAIN-GF-LC-AS- 2960.BRAVO.SA | 10.120.40.251 | Cisco | May 2020 | 100.00 % |
| JED-MAIN-LC-CS- 3850.BRAVO.SA | 10.120.40.253 | Cisco | May 2020 | 100.00 % |
| JED-STC-MPLS | 172.18.34.229 | Unknown | May 2020 | 100.00 % |
| KHB-BSTN-G-D-AS-3850- 1.BRAVO.SA | 10.130.100.2 | Cisco | May 2020 | 100.00 % |
| KHB-BSTN-G-D-CS-3850- 1.BRAVO.SA | 10.130.90.2 | Cisco | May 2020 | 100.00 % |
| KHB-BSTN-G-LC-AS-3850- 1.BRAVO.SA | 10.130.100.3 | Cisco | May 2020 | 100.00 % |
| KHB-BSTN-G-SER-AS-3850- 1.BRAVO.SA | 10.130.100.4 | Cisco | May 2020 | 100.00 % |
| KHB-BSTN-G-WAN-AS-3850- 1.BRAVO.SA | 10.130.100.5 | Cisco | May 2020 | 100.00 % |
| KHB-BSTN-G-WAN-RTR-1001X- 1.BRAVO.SA | 10.130.0.1 | Cisco | May 2020 | 100.00 % |
| KHB-BSTN-G-WAn-RTR-1001X- 1MPLS | 172.18.39.253 | Unknown | May 2020 | 100.00 % |
| KHB-BSTN-G-WAN-RTR-1001X- 2.BRAVO.SA | 10.130.90.5 | Cisco | May 2020 | 100.00 % |
| lc1-mso.bravo.com.sa | 192.168.115.70 | F5 Networks, Inc. | May 2020 | 100.00 % |
| lc2-mso.bravo.com.sa | 192.168.115.71 | F5 Networks, Inc. | May 2020 | 100.00 % |
| MSO 202-MPLS | 172.18.150.73 | Unknown | May 2020 | 100.00 % |
| MSOALARM03 | 192.168.110.67 | Windows | May 2020 | 100.00 % |
| NourNet Link | 178.20.150.205 | Unknown | May 2020 | 99.97 % |
| PUB-Master | 172.17.40.152 | HUAWEI Technology Co.,Ltd | May 2020 | 100.00 % |
| PUB-STANDBY | 172.17.40.151 | HUAWEI Technology Co.,Ltd | May 2020 | 100.00 % |
| RA-JED-204-1.BRAVO.SA | 10.122.90.45 | Cisco | May 2020 | 100.00 % |
| RA-JED-MAIN-1.BRAVO.SA | 10.120.0.1 | Cisco | May 2020 | 100.00 % |
| RA-JED-MAIN-2.BRAVO.SA | 10.120.90.10 | Cisco | May 2020 | 100.00 % |
| RA-JED-MSO-202-1.BRAVO.SA | 10.126.0.1 | Cisco | May 2020 | 100.00 % |
| RA-JED-MSO-202-2.BRAVO.SA | 10.126.0.2 | Cisco | May 2020 | 100.00 % |
| RA-MKK-BR-1.BRAVO.SA | 10.128.0.1 | Cisco | May 2020 | 100.00 % |
| RA-RYD-MSO-101-1.BRAVO.SA | 10.112.0.1 | Cisco | May 2020 | 100.00 % |
| RA-RYD-MSO-101-2.BRAVO.SA | 10.112.0.2 | Cisco | May 2020 | 100.00 % |
| RC-JED-204-1.BRAVO.SA | 10.122.0.1 | Cisco | May 2020 | 100.00 % |
| RD-HQ-WLC | 10.110.30.1 | Cisco | May 2020 | 100.00 % |
| RIYADH-RIYADH W_IP000264 | 62.149.105.194 | Unknown | May 2020 | 100.00 % |
| RUH-STC-MPLS | 62.149.105.193 | Unknown | May 2020 | 100.00 % |
| RYD_RDC46_A1_OOB_SW1.BRAV | 10.113.32.251 | Cisco | May 2020 | 100.00 % |
| RYD_RDC46_A10_ASR1001X_INT_ | 10.113.32.13 | Cisco | May 2020 | 100.00 % |

| 72020 | | ionally rectivors reduces i on | • | |
|-------------------------------------|-----------------|--------------------------------|-----------|--------------|
| CAPTION | IP_ADDRESS VE | ENDOR | TIMESTAMP | AVAILABILITY |
| RYD_RDC46_A10_ASR1006X_WAN | 172.18.226.30 | Cisco | May 2020 | 100.00 % |
| RYD_RDC46_A19_ASR1001X_INT_ | 10.113.32.14 | Cisco | May 2020 | 100.00 % |
| RYD_RDC46_A23_OOB_SW2.BRA\ | 10.113.32.250 | Cisco | May 2020 | 100.00 % |
| RYD-HQ-B1-DA-AS- 3850.BRAVO.SA | 10.110.105.11 | Cisco | May 2020 | 99.99 % |
| RYD-HQ-B1-LC-AS- 2960.BRAVO.SA | 10.110.40.249 | Cisco | May 2020 | 100.00 % |
| RYD-HQ-B2-DA-AS-3850 | 10.110.105.12 | Cisco | May 2020 | 99.99 % |
| RYD-HQ-B2-LC-AS- 2960.BRAVO.SA | 10.110.40.248 | Cisco | May 2020 | 100.00 % |
| RYD-HQ-F1-DA-AS- 3850.BRAVO.SA | 10.110.105.21 | Cisco | May 2020 | 100.00 % |
| RYD-HQ-F1-LC-AS- 2960.BRAVO.SA | 10.110.40.251 | Cisco | May 2020 | 100.00 % |
| RYD-HQ-F2-DA-AS- 3850.BRAVO.SA | 10.110.105.22 | Cisco | May 2020 | 100.00 % |
| RYD-HQ-F2-LC-AS- 2960.BRAVO.SA | 10.110.40.247 | Cisco | May 2020 | 100.00 % |
| RYD-HQ-GF-DA-AS- 3850.BRAVO.SA | 10.110.105.20 | Cisco | May 2020 | 100.00 % |
| RYDHQ-GF-DA-CS- 3850.BRAVO.SA | 10.110.100.254 | Cisco | May 2020 | 100.00 % |
| RYD-HQ-GF-LC-AS- 2960.BRAVO.SA | 10.110.40.250 | Cisco | May 2020 | 100.00 % |
| RYDHQ-GF-LC-CS3850- 1.BRAVO.SA | 10.110.40.252 | Cisco | May 2020 | 100.00 % |
| RYDHQ-GF-LC-CS3850- 2.BRAVO.SA | 10.110.40.253 | Cisco | May 2020 | 100.00 % |
| RYD-HQ-GF-R1- WAN.BRAVO.SA | 10.110.0.1 | Cisco | May 2020 | 100.00 % |
| RYD-HQ-GF-SRV-SW.BRAVO.SA | 10.110.102.254 | Cisco | May 2020 | 100.00 % |
| RYD-HQ-GF-WAN- SW.BRAVO.SA | 10.110.92.30 | Cisco | May 2020 | 100.00 % |
| RYD-RDC46-A10-Spine-201 | 10.113.32.7 | Cisco | May 2020 | 100.00 % |
| RYD-RDC46-A19-Spine-202 | 10.113.32.8 | Cisco | May 2020 | 100.00 % |
| RYD-RDC46-A1-Leaf-101 | 10.113.32.9 | Cisco | May 2020 | 100.00 % |
| RYD-RDC46-A23-Leaf-102 | 10.113.32.10 | Cisco | May 2020 | 100.00 % |
| RYD-TKH-G-D-AR-4331- 1.BRAVO.SA | 10.114.1.1 | Cisco | May 2020 | 99.82 % |
| RYD-TKH-G-LC-CS-3850- 1.BRAVO.SA | 10.114.1.2 | Cisco | May 2020 | 99.89 % |
| RYD-TKH-MPLS | 172.18.244.105 | Unknown | May 2020 | 100.00 % |
| S5700M | 10.175.16.38 Co | HUAWEI Technology o.,Ltd | May 2020 | 100.00 % |
| SADAD Link | 84.235.90.82 | Unknown | May 2020 | 100.00 % |
| SA-JED-MSO-202- STK.BRAVO.SA | 10.126.0.3 | Cisco | May 2020 | 100.00 % |
| SA-JED-MSO-202- STK.BRAVO.SA | 10.126.90.14 | Cisco | May 2020 | 100.00 % |
| SA-JED-MSO-202- STK.BRAVO.SA | 10.126.90.2 | Cisco | May 2020 | 100.00 % |
| SA-JED-MSO-202- STK.BRAVO.SA | 10.126.90.6 | Cisco | May 2020 | 100.00 % |
| SA-MAK-BR-1.BRAVO.SA | 10.128.90.2 | Cisco | May 2020 | 100.00 % |
| SA-RYD-MSO-101- STK1.BRAVO.SA | 10.112.10.253 | Cisco | May 2020 | 100.00 % |
| SC-JED-MAIN-STK.BRAVO.SA | 10.120.0.3 | Cisco | May 2020 | 100.00 % |
| SC-RYD-MSO-101-MPLS | 172.18.56.177 | Unknown | May 2020 | 100.00 % |
| SC-RYD-MSO-101- STK.BRAVO.SA | 10.112.0.3 | Cisco | May 2020 | 100.00 % |
| VGW1 | 10.110.23.250 | Cisco | May 2020 | 100.00 % |

https://10.122.88.21/Orion/Report.aspx? ReportID=488& Return To=aHR0cHM6Ly8xMC4xMjluODguMjEvT3Jpb24vUmVwb3J0cy9EZWZhdWx0LmFzc...