
SINGER 28K,127K,128K

ILLUSTRATED LIST OF PARTS


FOR


28K, 127K and 128K MACHINES

VIBRATING SHUTTLE MACHINES
FOR FAMILY USE




**A Trade Mark of THE SINGER MANUFACTURING CO.







From the library of: Superior Sewing Machine & Supply LLC




From the library of: Superior Sewing Machine & Supply LLC




From the library of: Superior Sewing Machine & Supply LLC





From the library of: Superior Sewing Machine & Supply LLC





From the library of: Superior Sewing Machine & Supply LLC





ILLUSTRATED LIST OF PARTS

FOR

28K, 127K and 128K MACHINES

CONTENTS

			Pag
Parts Complete for 28K Machines	 •••	• • • •	 3
n n n 127K Machines	 		 4
n 128K Machines	 		 4
Accessories and Attachments	 		 5
Bobbin Winders	 		 5
Hand Attachment	 		 5
Obsolete Parts	 		 5
Numerical Liet of Parts			5

INSTRUCTIONS FOR ORDERING

In ordering from this List, the prefix and affix letters with the part number **MUST BE** quoted exactly as they are shown in the first column.

A number always indicates the same part in whatever List it may appear, or for whatever machine.

The affix letters (where shown) indicate the style of finish, as follows:-

- A. Hardened, Polished, Nickel Plated and Buffed.
- A.A. Buffed and Chromium Plated.
- A.B. Hardened, Polished, Buffed and Chromium Plated.
- A.C. Brown Baking Enamel Finish.
- A.D. Grey Baking Enamel Finish.
- A.E. Hardened, Bright Rumbled and Nickel Plated.
- A.F. Hardened, Bright Rumbled and Nickel Plated, Bright Rumbled and Chromium Plated.
- A.J. Polished, Nickel Plated and Chromium Plated.
- A.K. Hardened, Polished, Nickel Plated and Chromium Plated.
- A.L. Heat Treated for Toughness.
 - B. Polished, Nickel Plated and Buffed.
- C. Hardened only.
- G.R. Hardened and Merlized.
- D. Polished only.
- E. Soft, not Polished
- F. Hardened and Polished.
- F.J. Hardened, Polished and Nickel Plated.
- G. Bright Rumbled and Nickel Plated.
- H. Blued.
- J. Nickel Plated only.
- K. Hardened and Nickel Plated.
- L. Brass Plated.
- M. Oxidized.
- N. Japanned, Dull.
- P. Japanned, Bright.
- P.P. Wrinkle Finish.
- R. Merlized.
- S. Cadmium Plated.
- T. Copper Plated.
- T.A. Hardened, Polished, Copper and Nickel Plated and Buffed.
- T.B. Copper and Nickel Plated and Polished.
- T.J. Copper and Nickel Plated only.
- T.K. Hardened, Copper and Nickel Plated.
- T.L. Copper and Brass Plated.
- T.M. Copper Plated and Oxidized.
 - U. Zinc Plated.
 - V. Silver Plated.
 - W. Polished and Nickel Plated.
 - X. Black Oxide for Iron and Steel.
- X.C. Hardened and Black Oxide for Iron and Steel.
 - Y. Black Nickel Plated only.
 - Z. Chromium Plated.
- Z.A. Hardened, Polished, Nickel Plated, Buffed and Chromium Plated.
- Z.B. Polished, Nickel Plated, Buffed and Chromium Plated.
- Z.C. Hardened and Chromium Plated.
- **Z.D.** Polished and Chromium Plated.
- Z.G. Bright Rumbled, Nickel Plated, Bright Rumbled and Chromium Plated.
- Z.J. Nickel and Chromium Plated.
- Z.T. Copper and Chromium Plated.

Parts marked with an asterisk (*) are furnished only when the repairs are made at Factory.

PARTS COMPLETE

FOR

CLASS 28K MACHINES

(Nos. 28K1 to 28K4).

Vibrating Shuttle. For Family Use. No. Plate *8447 **Arm** with 443c, 8206, 15404 and two 15405 NOTE.In ordering it is necessary to state the Class and Variety number of machine. 2002 926 Arm Dowel Pin (2) 4389 46 п (for repairs only) 43 Arm Rock Shaft with 50571e 8352 50571e 53 Adjusting Screw 8396 2520 Centre (upper) ... 47 301c Screw Centre (lower) 1693 1508j 138eArm Screw (3) 8446 43 Arm Shaft 8206 2520Bushing 443c-926Set Screw 54525b1690Arm Side Cover 81715p (plain) 51224b53 Thumb Screw 51224d 2007 46 2520 " Washer (cloth) 8879 15282b -1152Balance Wheel, 21" Pulley -115221" 15282p*81728 55515 2520 " Oil Hole (shuttle) Packing (braided cotton) NOTE. -- In ordering No. 81728 it is necessary to state the Class and Variety number of machine. Clamp Stop Motion Clamp Screw 256b47 256d 47

Stop Screw ...

53

248a

38

No.	Plate		No.	Plate	
		Claus Chan Matian Claus Chan Canan	8431	811	Feed Rock Shaft
248f	53	Clamp Stop Motion Clamp Stop Screw	307c	47	n n Screw Centre (2)
2020	47	и и и Washer		1693	n n n n Nut (2)
*15312	926	и и в Flanged Bushing	*·····j		
15313		и и и и и with two 462al	51045c	53	Machine Hinge Connection Set Screw (2)
2022	46	n n n n n Pin			-
462al	926	n n n n n Set Screw	8365	44	Needle Bar
15314	_	Clamp Stop Motion, complete, Nos. 248f, 256d, 2020 and 15313		2520	" " Cam with 175e
			175e	53	u u Clamping Screw
15314b		Clamp Stop Motion, complete, Nos. 248a, 256b, 2020 and 15313	233d	53	15 14 1 C
				1693	
*54529		Face Plate			1.63
*54529b		n n n		926	
*54529p		H H		926	u n n n n
8361	44	и и 54529 with 125423	249a	53	" " " and Needle Stop Screw
8361b	44	и и 54529b и 125423b	249f	53	q H H H H H H H
8361p	44	и и 54529р и 125423b			31 14 24 31 140747
219a	53	и и Screw (2)	2054	46	Needle Clamp with 140545c
219f	53	и и и (2),	i 40545c	53	n Thumb Screw
125422	2520	и и Thread Guard			_
125422b	2520	и и и и	8366	44	Presser Bar
125423	2520	n n n n 125422 with 125424	54503	926	n n Lifter
125423b	2520	n n n n 125422b with 125424b	54503b	926	и и п
125424	2520	u u u Rivet	97e	53	n n Screw
125424b	2520		32675	47	g g Spring
120,1210	-0-0		55507	813	n o Bracket with 453c
32562	2520	Feed Cam with 1285c	453c	53	n n n set Screw
1285c	53	ıı ıı Set Screw	2070	2520	n n Washer
8321	813	Feed Dog, four teeth at right of needle (square corners)	8337	813	Presser Foot
8437	47	и и Carrier	. 8337b	813	и и п
1833	1693	" " Roller and Screw Stud	51224b	53	" "Thumb Screw
315c	47	п п в Screw Centre (2)	51224d	53	n n n n n n
1519j	1693	n n n n Nut (2)			
191k	53	n n Screw	263j	47	Pressure Regulating Thumb Screw
		•	263d	47	
8443	43	Feed Forked Connection with 175j	2.,,,,,		
175j	53	n n Adjusting Screw	8444	926	Shuttle Bell Crank
1381c	53	n n Hinge Screw (eccentric)	50036b	926	n n n Hinge Screw
1520j	1693	n n n n Nut	00000	1,20	
1832	1693	n n o Roller with 1085e	8228	46	Shuttle Bobbin
1085e	_	n n n Screw Stud	*8301		Body
. 10000					
253b	47	Feed Regulating Thumb Screw	8326	46	
253d		H H H H ··· ·· ·· ·· ··	215h	53	
2030	41		8327	46	Shuttle, complete, Nos. 215h, 8228, 8301 and 8326
8216	2520	Feed Regulator			
8217	2520	" " Friction Washer	8231	46	Shuttle Carrier
42e		11	231k	53	11 Screw
420	99	" " Hinge Screw			

No.	Plate	Chartela Ditanca with town 173	~ :					DADTS COMDIETE
8445	811	Shuttle Pitman with two 178	•		• • •			PARTS COMPLETE
175j	53	n n Adjusting Sc			• • •			FOR
44c	53	" Screw Stud			•••			TOR
520c	53	•	(eccentric)		• • •			CLASS 127K MACHINES
1520j	1693	н и и	(") Nut		• • •			GLADD 121K MAGHINED
216c	53	и и и	(n) Serew		* * *			(NI - 100W2 and 100WA)
54513	927	Shuttle Slide (front)	•••			,		(Nos. 127K3 and 127K4).
54513b	927	и п (п)			***			
54512	927	и и (back)	***					
54512b	927	н н (п)	• • • • • • • • • • • • • • • • • • • •			For I	Family	Vibrating Shuttle with Shuttle Ejector.
2102	46	Tension Disc (2)			***			
1560g	1693	н Regulating Thumb I	Nut					
1560d	1693	0.00	и					
8237	46	n Releaser						
8237b	46	H H	***			No.	Plate	
SS416b	813	n Screw Stud	***			*55501		Arm with 443c, 8206, 15404 and two 15405
SS416d	813	и и и	***			2002	926	n Dowel Pin (2)
8238h	46	n Spring	***			4389	46	n n n (for repairs only)
81729		Tension, complete, Nos. SS4	16, 1560, 8237, 8238 a	nd two 21	102			- 1
26075	2520	Thread Cutter and Holder			***	8203	43	Arm Rock Shaft with 100 5057.10
*55523		Thread Take-up Cam	***		***	10.53/6	53	n n Adjusting Screw
55521	2520	-	3 with 448c			50571e	2520	и и Centre (upper)
2117	46	n n Pin				301c	47	n n Screw Centre (lower)
448c	53	n n set S		***		1508j	1693	u u u u Nut
		Thread Take-up Lever with						•
*55525	46	•	1035	• • •	***	649e	926	Arm Screw (3)
*55525b	46		1822 25 with 50527c		***			
55526			25 with 50527c		• • •	8341	43	Arm Shaft
55526b	2520				• • •	8206	2520	и и Bushing
8243	2520	n n Cov			•••	443c	926	п п в Set Screw
8243b	2520	11 11 11 II			• • •			
8243p	2520	H H H	Hinge Screw			125425b	1690	Arm Side Cover
107b	53	11 11 11			• • •	80307p	1690	л н н (plain)
107d	53	u u u u	ige Screw		• • •	51224b	53	" " Thumb Screw
50527c	$\frac{53}{1693}$		ller and Stud		***	51224d	53	н н н н н
1822	46				***	2007	46	By Spool Pin
8244		* ''	gulator Plate		•••	8879	2520	и и и Washer (cloth)
54516 233b	$\frac{46}{53}$		gulator i late - n — Adjustin		***			TO 4 TO 11 11
233d	53		u u u	5		15282b	1152	Balance Wheel, 21" Pulley
		, , , , , , , , , , , , , , , , , , , ,				15282p	1152	n n 2¼" n
8323	813	Throat Plate	•••	• • •	• • •			
8323b	813	n n	***			*8328		Bed
219a	53	н н Screw	•••	• • •	***	55515	2520	Oil Hole (shuttle) Packing (braided cotton)
219f	53	и и и	***		***			Ol Garage Madday Olama Carray
*15404		Trade Mark	***			256b	47	Clamp Stop Motion Clamp Screw
15405		n n Rivet	***			248a	53	n n n Stop Screw
81742		Drip Pan	***			2020	47	и и и « Washer

42

No.	Plate										
2102	46	Tension	Disc	(2)							
1560g	1693	11			hun	ıb Nut					
1274	926	**	Screw								
8238h	46	• 11	Spring	ζ							
32572	926	**	Releas	sing Dis	sc .						
55505	926	11	н	Le	ver						
55506	926	11	н	,	.,	Hinge !	Pin				
12329	813	11	- 11		11	Spring					
54515	926	11	н								
55520		Tension	, com	plete, l	Nos	. 1274j	, 1560	0g, 3	8238h,	8244,	32572,

26075	2520	Thread	Cutte	r and I	Hole	ler			• • •		
*55523		Thread	Take-	up Ca	m.						
55521	2520	11	н		_	5523 w	ith 44	8c			
2117	46	11	11	*1	I	'in					• • •
448c	53	11	11	11		Set Scre	·W			• • •	• •
*55525b	46	Thread	Take-	up Le	ver	with 18	322				
55526b		11	н		11	55525b	with	5052	27c		
8243b	2520	н	**		11	Cover				* * *	
8243p	2520	18	Ħ		11	11					
107b	53	11	11		17	11	Hinge	Scre	ew		• • •
107d	53	11	11		11	11		13			
50527c	53	11	н		11	Hinge					• • • •
1822	1693	11	н		II.	Roller					
8244	46	16	11	Sp	ring						
54530	2520	**	Ð		H.	Regul					
2 33 b	53	U	18		It	11		11	Adjust	ing Scr	ew
8323b	813	Throat	Plate								
219a	53	11	11	Screw							
2.011											
*15404		Trade l	Mark								***
15405	· · .	11	H	Rivet					• • •		
87321		Drip P	an			• • •					

PARTS COMPLETE

FOR

CLASS 128K MACHINES

(Nos. 128K3 and 128K4).

Vibrating Shuttle with Shuttle Ejector. For Family Use. Plate No. *54501 **Arm** with 443c, 8206, 15404 and two 15405 NOTE. In ordering it is necessary to state whether "Gilt" or "Coloured" ornamentation is required. Arm Dowel Pin (2) 200246 438911 " (for repairs only) Arm Rock Shaft with 50571e 835243 5350571e Adjusting Screw 8396 2520 Centre (upper) ... 301c 17 Screw Centre (lower) 1508i1693Nut 53 Arm Screw (3) -138e43 8446 8206 2520 Bushing 443c926 Set Screw 54525b Arm Side Cover (plain) 81715p 5122413 53 Thumb Screw 51224d 532007Spool Pin ... 8879 2520 " Washer (cloth) 15282b Balance Wheel, 21" Pulley 15282p -115221" *8450 Bed 55515 2520Oil Hole (shuttle) Packing (braided cotton) NOTE. - In ordering No. 8450 it is necessary to state whether "Gilt" or "Coloured" ornamentation is required. 256bClamp Stop Motion Clamp Screw 17 248a 53Stop Screw 202047 Washer 926Flanged Bushing *15312 15313 with two 462al 2022 46 Pin

Set Screw

462al 926

No.	Plate			No.	Plat	
15314b		Clamp Stop Motion, complete, Nos. 248a, 256b, 2020 and	15919	2054	46	Mandle Clause with 140747
199140		Clamp Stop Motion, complete, 1908. 2408, 2000, 2020 and	1 1 - 7 - 7 1 - 7			Needle Clamp with 140545c
*54529b		Face Plate		140545c	53	" Thumb Screw
	_					
*54529p	4.4	H H		8366	44	Presser Bar
8361b	44	n 54529b with 125423b	• • •	54503b	920	ıı ıı Lifter
8361p	44	и и 54529р и 125423b		97e	53	n n Screw
219a	53	и и Screw (2)		32675	47	и и Spring
125422b	2520	" Thread Guard		55507	813	н н Bracket with 453с
125423b	2520	и и и и 125422b with 125424b	• • •	453c	53	n n Set Screw
125424b	2520	n n n Rivet		2070	2520	и и и Washer
32562	2520	Feed Cam with 1285c		8337b	81::	Presser Foot
1285c	53	ıı ıı Set Screw		51224b	53	" " Thumb Screw
				012210	*,**,	" " " " " " " " " " " " " " " " " " "
8321	813	Feed Dog, four teeth at right of needle (square corners)		200:	45	Duranana Dadadadad (Di. aata Cana
8437	47	11 II Carrier		263 j	47	Pressure Regulating Thumb Screw
1833	1693	Roller and Screw Stud				
315c	47	п п Screw Centre (2)		8444	920	Shuttle Bell Crank
1519j	1693	п п п n Nut (2)		500 3 6b	920	n n Hinge Screw
191k	53	n n Screw				
				8228	4.0	Shuttle Bobbin
8443	43	Feed Forked Connection with 175j		*54504	46	
175j	53	" Adjusting Screw				н Body
1381c	53	Hinge Screw (eccentric)			53	Tension Regulating Screw
1520j	1693	n n n Nut		8326	46	" " Spring
1832	1693	n n Roller with 1085e		54505	920	Shuttle, complete, Nos. 215h, 8228, 8326 and 54504
1085e		n n Screw Stud				
10000				*54506	926	Shuttle Carrier
253b	47	Feed Regulating Thumb Screw				" 54506 with 54508 and two 54509
2000	**	Total Regulating Amania Service			926	Carolina Carolina
8216	2520	Feed Regulator			920	
8217	2520	73 1 11 TTT 1	***		53	
					926	
42 e	53	n Hinge Screw			926	" Ejector
0.403	011	Feed Rock Shaft			926	u u Hinge Screw
8431	811	G				" " Spring
307c	47	N. 4 (9)		54507		Shuttle Carrier, complete, Nos. 50126e, 54510, 54511 and 54527
1513j	1693	и и и и п Nut (2)				
~10.15	~0	Marking Hinds Connection Set Screw (9)		8445	811	Shuttle Pitman with two 175j
51045c	53	Machine Hinge Connection Set Screw (2)		175j	53	ıı ıı Adjusting Screw
		# B		44c	53	" Screw Stud
8365	44	Needle Bar			53	" " (eccentric)
*8222	2520	" Cam with 175e			1693	<u> </u>
175e	53	и и Clamping Screw		•	53	i
233d	53	n n Position Screw		2100	17.7	и и и и (и) Screw
1836	1693	" " Roller and Screw Stud				
8338b	926	" Thread Guard		54512b	927	Shuttle Slide (back)
249a	53	и и и и and Needle Stop Screw		54513b	925	и и (front)

No.	Plate								
2102	46	Tension	Disc (2)					
1560g	1693	13	Regula	ting Th	umb Nut	L			
1274j	926	11	Screw	Stud					
8238h	46	11	Spring		***				
32572	926	11	Releas	ing Disc					
54514	926	n	п	Leve	er				
97e	53	11	17	ti	Hinge	Screw			
39443	2520	11	"	11	Spring				
54515	926	*1	11	Pin					.A.
55520	_	Tension	, comp	olete, N	os. 1274	j, 1560g	, 8238h,	8244, 3	2572,
		54515	and tv	vo 2102					
26075	2520	Thread	Cutter	and Ho	older	• • •			
*55523		Thread	Take-	•			• • •		
55521	2520	11	11	11		ith 448c	•••		
2117	46	11	11	11					
448c	53	11	11	11	Set Scr			• • •	***
*55525b	46	+1	11		r with 18	szz with 50/	 	• • •	• • •
55526b	9590	11	*1	н	- əəəzəb - Cover				
8243b	2520	. **	11	11			•••		
8243p 107b	$\frac{2520}{53}$	11	**	H	,, ,, J	 Hinge Sci	row		
107D 107d	53	17	11	11		n nge oei			
50527c	53	11	11	11	Hinge :		• • • •		
1822	1693	"	11	11		and Stud			
8244	46	0	"	Sprin		,,,			
54530	2520	'n	11	Opri.		ator Plat			
233b	53	"	11	"	311 5011	11		ig Screw	
2000	***************************************	"	**				,	CI .	
8323b	813	Throat 1	Plate						
219a	53	11		Screw					
*15404		Trade M	lark						
15405		H.	,, R	ivet					
81742		Drip Pa	n	• • •					

BOBBIN WINDERS (Automatic)

28K, 127K and 128K MACHINES

No.	Plate							
8342	929	Back Centre					***	
8256	929	, n 1	Jead					
8256b	929	11 11	11					
8343	929	11 11 5	Spring					
155509	1692	Bracket (belt	cover)					
158b	929	" Screw	·					
*8257	1692	Cam						
*8257b	1692	11						
50231a	53	" Screw						
50231f	53	п п						
55510	1692	Frame						
55512	1692	n Frictio	n Washer					
50101b	929	u Hinge	Screw					
50101d	929	н н	H					
1718h	929	11 11	u Nu	t			* * *	
15287	929	Friction Ring	(rubber)		• • •			
50102f	929	Spindle					* * *	
15288	929	" Pulle	y		`			
15288b	929	11 11	• • • •	• • •	• • •			
8346	929	Thread Guid	e		***			• • • •
8346b	929°	11 11					***	,
92b	53	11 11	Hinge S	ctem				
92d	53	11 11	H	L1				
8260	1692	11 11	Spring	• • •			***	
8261	1692	Worm Wheel			• • •	* * *		
8261b	1692	14 19		0.055	1.509916			
55514	_	11 11	8261 with 8261b wi			10		
55514b		H II						
2749	1692	н п	Friction		 4i\	* * *		
50104b	929	11 11	Screw St)			
50104d	929	11 11		ı (ıı ı Nut	, , ,			
1718h	929	Bobbin Wine						
55511		8260, 8342	161 (autoi 182 883	is 15287	15288 50	0101d. 50	102f, 501/	04d,
		55509, 555	, 0040, 001 (10 - 55512	55514 :	and two	1718h f	or 28K1	and
·		28K2 Mac		, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				
1~~~111.		Bobbin Wind					2749, 82	56b,
‡55511b		8260, 8345	2 8343 9	346b. 1	5287. 152		015, 501	02f,
		50104b, 5	5509. 555°	10. 5551:	2, 55514b	and tw	o 1718h,	for
		28K3, 28K						
		20110, 201	,,					

[‡]In ordering it is necessary to state the class of machine and when for 128K Machine to state also whether "Gilt" or "Coloured" Ornamentation is required.

Attachment Set

No.	Plate							
121464	930	Binder						
25527b	905	Cloth Guide						
50053b	53	n a Thun	ab Screw					
35931	930	Hemmer (adjusta	ble)					
120842	1151	$_{0}$ (foot) $_{64}^{5}$	" Hem					
15×1		Needles (6)						
25537	905	Screw Driver (ma	chine) .					
120378	905	и и (sht	ittle tensi	ion)				
8228	46	Shuttle Bobbin						
120862		Tin of Oil $(L_3^1 \text{ oz.})$) .					
36583	1160	Tucker .						
86502		Set, complete, No	s. 25527b	, 25537.	35931, 36	583, 500	536, 1203	
		120842, 12086	2, 121464	, three 8	228 and :	six needle	rs	• • •
25525	905	Bias Gauge					•••	
121441	100	Gathering Foot	(double t	toe)				• • •
35932	930	Quilter		••				
120290	930	Ruffler .						
35934	910	u Shirring	Plate .			* * *		
120291		п — 120290 w	ith 3593	1			***	
25539	905	Stiletto				•••	•••	• • •
35937	910	Under Braider		••			***	

No.

Art Work and Darning

Embroidery Hoops (Plain)

No.	Plate					(BIRCH)			
85893 86080	1151 813	Embroidery Foot (for art work) Feed Cover Plate		No.	Plate				
				87586		Round, $5\frac{5}{8}''$ diam. $\times 7\frac{m}{m}$ high			
				96416		$_{0}$ $_{7''}$ $_{0}$ $_{\sim}$ $ imes 7^{m_{c}}_{m}$ $_{0}$	• • •		
		G 1: Γ		87589	1221	$_0$ 8" $_{-}$ $_0$ $ imes 7^m_{,m}$ $_0$			
		Cording Foot		87593		$_{0}$ $10''$ $_{0}$ $ imes rac{7}{18}''$ $_{0}$			
		G01 G-19		87595		$_{0}$ 12" $_{0}$ $ imes rac{1}{2}$ " $_{0}$			
No.	Plate			96422	1221	Oval, $9'' \times 4\frac{1}{2}'' \times 7^m_{,m}$ high			
15429	1151	Presser Foot for Stitching on Edge and Inserting Cord	***	87597		$n 12'' \times 5\frac{1}{2}'' \times 7\frac{m}{m} n \dots$		• • • •	 • • •

Darning Presser

No.	Plate							
86493	1160	Needle	Clamp	with 140	545k			
140545k	1160	11	11	Screw	• • •			
86494	1160	II	11	Stripper	Spring			
86495	1160			11			• • •	
86496	1160	Darnin	g Pre	esser, con	nplete,	Nos. 86493	to 86495	

Imitation Hemstitching Attachment

No.	Plate			
120687	1151	with Yielding Presser Plate	 	

Tubular Trimming Attachment

For making $\frac{3}{32}''$, $\frac{1}{8}''$ and $\frac{5}{32}''$ Trimmings.

35984	1151	Presser Foot	(strip fol	ding) wit	h Tube			
25539	1151	Stiletto						• • •
35983	1151	Strip Wire						
	NOTE.	When ordering	g 35983 s it is to	tate size o be used.	of attachm	ent with a	which	
35985	1151	Tubular Tri and 35984		Attachn 	nent, con	iplete, No	os. 25539, 	35983
,	N	OTE.—When or	dering 3	5985 state	size requ	ired.		

Embroidery Hoops (with Clamp)

(BIRCH)

	No.	Plate	
	96417		Round, $5\S''$ diam. $\times 7\rlap/m$ high, with SS528j, NN95j, two 96425 and
			four 96427
	96418		$n=7''$ or $\times 7^{m'}_m$ or $n=SS528$ j, $NN95$ j, two 96426 and
			four 96427
	96419		$n=8''-n= imes 7^{m^+}_{m^+}$ $n=0$ SS528j, NN95j, two 96426 and
	00410		four 96427
	00430		$_{\rm H}=10''$ $_{ m H} imes rac{7}{16}''$ $_{ m H}=_{ m H}=SS528{ m j},NN95{ m j},{ m two}96426$ and
	96420		four 96427
٠			CCFAO' AINOF! 1 00044 and
	96421		$12''$ $11 \times \frac{1}{2}''$ 11 11 SS528], WW95], two 99844 and four 96845
	96423		Oval, $9'' \times 4\frac{1}{2}'' \times 7^{m'}_{m}$ high, with SS528j, NN95j, 96425, 96426 and
			four 96427
	96424		$n = 12'' \times 5\frac{1}{2}'' \times 7\frac{m^2}{m}$ $n = 0$ SS528j, NN95j, 96425, 96426 and
			four 96427
	96425	2399	Clamping Bracket for 96417, 96423 and 96424
	96426	2399	n n 96418 to 96420, 96423 and 96424
	96844	2399	n n 96421
	96427	2399	Rivet for 96417 to 96420, 96423 and 96424
	96845	2399	и и и 96421
	SS528i	2399	y Screw
	,		Nint
	NN95j	2399	II

Hand Attachment

No.	Plate		
†94050	2284	Body	
94027	2284	Bracket	
183e	2114	п п Screw	
94028	2114	Crank Handle (wood)	
94029b	2114	" " Spindle	
940 3 0b	2114	n n r Flange (loose)	
94069	2114	" Hinge Pin	
94031a	2284	n, Lever	
94032	2114	n Lock Pin	
94033b	2114	и и и и Неаd	
55531	2114	n n n n Spring	
94034b		Crank, complete, Nos. 94028, 94029b, 94030b and 94031a	
94046	2114	Driver	
94070		n = 94046 with 80028 and 94048	
94036	2114	n Finger	
94039	2114	n	
94040	2114	n n n n Plate	
SS567e	2114	и и и и аnd Plate Binding Screw	•
94041		и 94036 with SS567e, 94039 and 94040	
94044	2114	" Hinge Pin	
94037	2114	n n Latch	
SS565e	2114	n n screw Stud '	
94038	2114	и и Spring	
94051b	2284	Gear with 55531, 94032 and 94033b	
94016	2284	n Cover	
399a	2114	n n Screw	
SS599 f	2114	" Screw Stud	
94048	2114	Pinion	
80028	2114	n Dowel Pin	• • •
SS600f	2114	Screw Stud (eccentric)	• • •
†94052b	2284	Hand Attachment, complete, Nos. SS565e, SS566e, SS5	
		SS600f, 94016, 94027, 94034b, 94037, 94038, 94041, 940)44,
neson	0114	94050, 94051b, 94069, 94070, two each 183e and 399a	• • •
SS566c	2114	Hand Attachment Screw	•••
	$\dagger I$	In ordering it is necessary to state Class of Machine.	

Obsolete Parts

No.	Plate		
*81704		Arm, with 443c and 8206 for 80150 for 27K Machines	s
*81709		n n 443c n 8206 n 81712 n 27K Machines	s
*8426		n n 443c n 8206 n 28K Machines .	
NC)TE.	In ordering 8426 it is necessary to state the Class and Var	icty
		number of machine.	
8205		Arm Shaft for 27K Machines	
8333			
8353			
8430		n n n 28K n	
80002		Balance Wheel for 27K1 and 27K2 Machines	
80002b			
8355		$n=n=n-28\mathrm{K}1$ $n=28\mathrm{K}2$ $n=1$.	• • • • • • • • • • • • • • • • • • • •
8355b		$_{ m H}$	
8315	4.1	Belt Cover for 27K Machines	
159a	53	n n Screw	
81739	4.4	n for 28K Machines	
190a	53	п п Screw	
190f	53		• • • • • • • • • • • • • • • • • • • •
*2021	47	Clamp Stop Motion Flanged Bushing for 15152 .	
15152		n n n n n 2021, with	two 462a1
		for 271	K Machines
*8360	47	и и и и и и for 8423 .	
8423		n n n n n n 8360, with	two 462a1
		for 8359	and 8359b
8359		Clamp Stop Motion, complete, Nos. 248f, 256d, 202	0 and 8423
		for 28K1 and 28K2 Machines	
8359b		Clamp Stop Motion, complete, Nos. 248a, 256b, 202	0 and 8193
.,,,,,,,,,,		E MATTA I MATTA SE SE	
81710	46	Feed Dog, without teeth at right of needle, for 271	
61710	+1)	reed rog, without teeth at right of needle, for 27r	Machines
0010		Dead Dead (for a good) for ATE and ANTIMARY	
$\frac{8213}{27c}$	46 53		
270	2.3	Feed Forked Connection Hinge Screw for 27K	Machines
pain		Feed Rock Shaft for 8218	
8219			••
8218	43	и и 8219 with 8220 for 27K Machines.	
8220	2520	0 n n n Crank with 460c for 8218 and 8363	
460c	53	n n n Set Screw for 8220 .	
8364		и и for 8363	
8363	43	n 8364 with 8220 for 28K Machines .	
15281	46	D D 47 NH 1 NM N 1	
10401	40	record root for the and tox machines	••

No.	Plate					
8229b	2520	Shuttle	Bell C	Irani	k with two 175e for 27K and 281	← Machines
175e	53	11		11	Adjusting Screw for 8229b	
533b	47	11		11	Stud for 27K and 28K Machine	s
533d	47	II	11	11	п п 27K and 28K Machine	s
1544b	47	н	н	11	и Collar with 465 al for 27К а	ind 28K
	_					Machines
465 a	L 53	n	11	11	n Set Screw for 1544b	
413b	47	Tension	Scre	w St	ud for 28K3 and 28K4 Machines	
413d	47	Ħ	п	1	n 28K1 n 28K2 n	
8241		Thread	Take-	·up (Cam with 448c	
8242		н	11	. 1	Lever with 1822 for 28K Machines	s
8242b	-	11	11		п п 1822	
79c	53	tt.	11		и Hinge Screw	
1711	46	Throat	Plate	for 8		
8240	46	11	11	ıı 8	213 (for export)	

BOBBIN WINDERS (Automatic)

28K, 127K and 128K MACHINES

0042 ' 020 D -1 Charles	
8342 929 Back Centre	
8256 929 " " Head	
8256b 929 n n n n	
8343 929 " " Spring	
‡8344 929 Bracket (belt cover)	
158b 929 " Screw	
*8257 1692 Cam	
*8257b 1692 "	
50231a 53 " Screw	
50231f 53 " "	
8345 929 Frame	
80272 929 n Friction Washer	
50101b 929 " Hinge Screw	
50101d 929 " " " "	
1718h 929	
15287 929 Friction Ring (rubber)	٠
50102f 929 Spindle	
15288 929 " Pulley	
15288b 929 " "	• • •
8346 929 Thread Guide	• • •
8346b 929 п п	• • •
92b 53 " Hinge Screw	
92d 53 — п п п п	
8260 1692 " " Spring	
8261 1692 Worm Wheel	
8261b 1692 — — — — — — — — — — — — — — — — — — —	• • •
55514 " 8261 with 8257 and 50231f	
55514b " 8261b with 8257b and 50231a	• • •
2749 1692 " " Friction Washer	• • •
50104b 929 ii Screw Stud (eccentric)	• • •
50104d 929 п п п п (п)	• • •
1718h 929 " " " Nut	
8347 928 Bobbin Winder (automatic), complete, Nos. 92d, 2749, 82	
8260, 8342 to 8346, 15287, 15288, 50101d, 50102f, 5010	
55514, 80272 and two 1718h, for 28K1 and 28K2 Machin	
‡8347b 928 Bobbin Winder (automatic), complete, Nos. 92b, 2749, 825	
8260, 8342 to 8346b, 15287, 15288b, 50101b, 50102f, 5010	
55514b, 80272 and two 1718h, for 28K3, 28K4, 127K a	
128K Machines	

‡In ordering, it is necessary to state the class of machine, and when for 128K Machine to state also whether "Gilt" or "Coloured" Ornamentation is required.

Numerical List of Parts

No.	Plate	
27 c	53	Feed Forked Connection Hinge Screw for
		27K and 28K Machines (Obsolete)
42e	53	Feed Regulator Hinge Screw
44c	53	Shuttle Pitman Screw Stud
79 c	53	Thread Take-up Lever Hinge Screw
		(Obsolete)
92b	53	Bobbin Winder Thread Guide Hinge Screw
		for 8347b and 55511b
92d	53	Bobbin Winder Thread Guide Hinge Screw
		for 8347 and 55511
NN95j	2399	Embroidery Hoop Clamping Bracket Screw
		Nut for 96417 to 96421, 96423 and 96424
97e	53	Presser Bar Lifter Screw
97e	53	Tension Releasing Lever Hinge Screw for
		128K Machines
107Ь	53	Thread Take-up Lever Cover Hinge Screw
107d	53	Thread Take-up Lever Cover Hinge Screw
5057/e 1000	53	Arm Rock Shaft Adjusting Screw for 8203
138e	53	Arm Screw for 28K and 128K Machines
158b	929	Bobbin Winder Bracket Screw for 8347, 8347b, 55511 and 55514b
159a	53	Belt Cover Screw for 27K Machine (Obsolete)
175e	53	Needle Bar Cam Clamping Screw for 8222
175e	53	Shuttle Bell Crank Adjusting Screw for 8229b
		(Obsolete)
175 j	53	Feed Forked Connection Adjusting Screw for
		8348 and 8443
175i	53	Shuttle Pitman Adjusting Screw for 8232 and
,		8445
183e	53	Hand Attachment Body Bracket Screw for
		94052b
190a	53	Belt Cover Screw for 28K Machine (Obsolete)
190f	53	Belt Cover Screw for 28K Machine (Obsolete)
191k	53	Feed Dog Screw
215h	53	Shuttle Tension Regulating Screw for 8327
		and 54505
216c	53	Shuttle Pitman Screw Stud (eccentric) Screw
219a	53	Face Plate Screw
219a	53	Throat Plate Screw
219f	53	Face Plate Screw for 28K Machines
219f	53	Throat Plate Screw for 28K Machines
231k	53	C1 4.41 (2) (2
233b	53	Thread Take-up Spring Regulator Plate
2000	70	Adimetica Canan
		Adjusting Screw

No.	Plate			No.	Plate	
233d	53	Thread Take-up Spring Regulator Plate Adjusting Screw for 28K Machines		533b	47	Shuttle Bell Crank Stud for 27K and 28K Machines (Obsolete)
233d	53	Needle Bar Cam Position Screw	;	533d	47	Shuttle Bell Crank Stud for 27K and 28K
248a	53	Clamp Stop Motion Clamp Stop Screw for	!	.,,,,,,,		Machines (Obsolete)
		8359b and 15314b	· ·	SS565e	2114	Hand Attachment Driver Finger Latch Screw
· 248f	53	Clamp Stop Motion Clamp Stop Screw for	·			Stud for 94052b
		8359 and 15314		SS566c	2114	Hand Attachment Screw for 94052b
249a	53	Needle Bar Thread Guard and Needle Stop		SS567e	2114	Hand Attachment Driver Finger Driving Pad
		Screw		.,,,,,,,		and Plate Binding Screw for 94041
249f	53	Needle Bar Thread Guard and Needle Stop		SS599f	2114	Hand Attachment Gear Screw Stud for
		Screw for 28K Machines	· · · · · · · · · · · · · · · · · · ·			94052b
253b	47	Feed Regulating Thumb Screw		SS600f	2114	Hand Attachment Pinion Screw Stud (eccen-
253d	47	Feed Regulating Thumb Screw for 28K				tric, for 94052b
		Machines		649e	926	Arm Screw for 127K Machines
256b	47	Clamp Stop Motion Clamp Screw for 8359b and		1085e		Feed Forked Connection Roller Screw Stud
		15314b				for 1832
256d	47	Clamp Stop Motion Clamp Screw for 8359 and		1274	926	Tension Screw Stud for 55520
		15314		1285c	53	Feed Cam Set Screw for 32562
263d	47	Pressure Regulating Thumb Screw for 28K	:	1381c	53	Feed Forked Connection Hinge Screw
		Machines				(eccentric)
263j	47	Pressure Regulating Thumb Screw		1508j	1693	Arm Rock Shaft Screw Centre Nut
301c	47	Arm Rock Shaft Screw Centre (lower)		1513j	1693	Feed Rock Shaft Screw Centre Nut
307c	47	Feed Rock Shaft Screw Centre		1519j	1693	Feed Dog Carrier Screw Centre Nut
315c	47	Feed Dog Carrier Screw Centre		1520j	1693	Feed Forked Connection Hinge Screw Nut
399a	53	Hand Attachment Gear Cover Screw for		1520j	1693	Shuttle Pitman Screw Stud (eccentric) Nut
		94052b		1544b	47	Shuttle Bell Crank Stud Collar with 465c for
413 b	47	Tension Screw Stud for 28K3 and 28K4 Machines (Obsolete)		19440	41	27K and 28K Machines (Obsolete)
413d	47	Tension Screw Stud for 28K1 and 28K2		1560g	1693	Tension Regulating Thumb Nut for 55520
		Machines (Obsolete)		1560d	1693	Tension Regulating Thumb Nut for 81729
<i>SS</i> 416b	813	Tension Screw Stud for 81729		1718h	929	Bobbin Winder Frame Hinge Screw Nut for
<i>SS</i> 416d	813	Tension Screw Stud for 81729		1.1(,,,,		8347, 8347b, 55511 and 55511b
443c	926	Arm Shaft Bushing Set Screw for 8426, 8447,		1718b	929	Bobbin Winder Worm Wheel Screw Stud Nut
		54501, 55501, 81704 and 81709		17100	020	for 8347, 8347b, 55511 and 55511b
448c	53	Thread Take-up Cam Set Screw for 8241 and		7000	1000	
		55521		1822	1693	Thread Take-up Lever Roller and Stud for
453c	53	Presser Bar Spring Bracket Set Screw for				8242, 8242b, 55525 and 55525b
		55507		1832	1693	Feed Forked Connection Roller with 1085e
460c	53	Feed Rock Shaft Crank Set Screw for 8220		1833	1693	Feed Dog Carrier Roller and Screw Stud
		(Obsolete)		1836	1693	Needle Bar Cam Roller and Screw Stud
462al	926	Clamp Stop Motion Flanged Bushing Set Screw for 8423, 15152 and 15313		2002	926	Arm Dowel Pin
4050	E 9	Shuttle Bell Crank Stud Collar Set Screw		2007	46	Arm Spool Pin
465c	53	for 1544b (Obsolete)				•
g nn -	53	Shuttle Pitman Screw Stud (eccentric)		2020	47	Clamp Stop Motion Clamp Washer for 8359,
520c	2399	Embroidery Hoop Clamping Bracket Screw				8359b, 15314 and 15314b
<i>SS</i> 528j	4000	for 96417 to 96421, 96423 and 96424		*2021	47	Clamp Stop Motion Flanged Bushing for 15152 (Obsolete)

63

NUMERICAL LIST OF PARTS

No.	Plate		3	vo.	Plate	
2022	46	Clamp Stop Motion Flanged Bushing Pin		3243	2520	Thread Take-up Lever Cover for 28K Machines
2054	46	Needle Clamp with 140545c		3243b	2520	Thread Take-up Lever Cover
2070	2520	Presser Bar Spring Washer	8	3243p	2520	Thread Take-up Lever Cover
2102	46	Tension Disc for 55520 and 81729	1	3244	46	Thread Take-up Spring for 55520
2117	46	Thread Take-up Cam Pin	8	8256	929	Bobbin Winder Back Centre Head for 8347
2749	1692	Bobbin Winder Worm Wheel Friction Washer				and 55511
		for 8347, 8347b, 55511 and 55511b		3256b	929	Bobbin Winder Back Centre Head for 8347b
4389	46	Arm Dowel Pin (for repairs only)				and 55511b
8203	43	Arm Rock Shaft with 122e for 127K Machines	**	3257	1692	Bobbin Winder Cam for 55514
8204	2520	Arm Rock Shaft Centre (upper) for 127K	**	3257b	1692	Bobbin Winder Cam for 55514b
		Machines	:	3260	1692	Bobbin Winder Thread Guide Spring for 8347,
8205		Arm Shaft for 27K Machines (Obsolete)		,_(,(,	1 (7.7.	8347b, 55511 and 55511b
8206	2520	Arm Shaft Bushing for 8426, 8447, 54501,	,	3261	1692	Bobbin Winder Worm Wheel for 55514
		55501, 81704 and 81709		3261b	1692	Bobbin Winder Worm Wheel for 55514b
8210b	44	Face Plate 55529b with 125423b for 127K		301	1000	(3, 44, 1) 1 (0007
		Machines		3315	44	*
8210p	44	Face Plate 55529p with 125423b for 127K				Belt Cover for 27K Machines (Obsolete)
0.310	4.0	Machines		332 F	813	Feed Dog, four teeth at right of needle (square corners)
8213	46	Feed Dog (for export) for 27K and 28K Machines (Obsolete)		10.10	0.1.0	,
•		· ·		3323	813	Throat Plate for 8321 for 28K Machines
8216	2520	Feed Regulator		3323b	813	Throat Plate for 8321
8217	2520	Feed Regulator Friction Washer Feed Rock Shaft 8219 with 8220 for 27K	: 8	3326	46	Shuttle Tension Spring for 8327 and 54505
8218	43	Machines (Obsolete)		3327	46	Shuttle, complete, Nos. 215h, 8228, 8301 and
0210		Feed Rock Shaft for 8218 (Obsolete)				8326, for 28K Machines
$8219 \\ 8220$	 2520	Feed Rock Shaft Crank with 460c for 8218	* 5	3328		Bed for 127K Machines
8220	2020	and 8363 (Obsolete)	5	3333		Arm Shaft for 27K Machines (Obsolete)
0.00		, , ,		3334	811	Feed Rock Shaft for 127K Machines
8221	44	Needle Bar for 127K Machines		3337	813	Presser Foot for 28K Machines
*8222	2520	Needle Bar Cam with 175e		337Ъ	813	Presser Foot
8224	44	Presser Bar for 127K Machines		3338	926	Needle Bar Thread Guard for 28K Machines
8225	47	Presser Bar Spring for 127K Machines Shuttle Bobbin for 8327, 54505 and 86502		338b	926	Needle Bar Thread Guard
8228 8229b	$\frac{46}{2520}$	Shuttle Bell Crank with two 175e for 27K and		3341	43	Arm Shaft for 127K Machines
82290	2020	28K Machines (Obsolete)		342	929	Bobbin Winder Back Centre for 8347, 8347b,
8231	46	Shuttle Carrier for 28K Machines			0.30	55511 and 55511b
8232	44	Shuttle Pitman with two 175j for 127K		3343	929	Bobbin Winder Back Centre Spring for 8347,
(721)2		Machines				8347b, 55511 and 55511b
8237	46	Tension Releaser 81729		3344	929	Bobbin Winder Bracket (belt cover) for 8347
8237b	46	Tension Releaser 81729	• !		0.20	and 8347b (Obsolete)
8238h	46	Tension Spring for 55520 and 81729	,	1345	929	Bobbin Winder Frame for 8347 and 8347b
8240	46	Throat Plate for 8213 (for export) (Obsolete)				(Obsolete)
8241		Thread Take-up Cam with 448c (Obsolete)		3346	929	Bobbin Winder Thread Guide for 8347 and
*8242		Thread Take-up Lever with 1822 for 28K				55511
		Machines (Obsolete)	8	3346b	929	Bobbin Winder Thread Guide for 8347b and
*8242b		Thread Take-up Lever with 1822 (Obsolete)				55511b

				IN I	UMERICAL LIST OF PARTS 65
No.	Plate		No.	Plate	
8347	928	Bobbin Winder (automatic), complete, Nos.	8430		Arm Shaft for 28K Machines (Obsolete)
		92d, 2749, 8256, 8260, 8342 to 8346, 15287,	8431	811	Feed Rock Shaft for 28K and 128K Machines
		15288, 50101d, 50102f, 50104d, 55514,	8437	47	
		80272 and two 1718h for 28K1 and 28K2	8443	43	
		Machines (Obsolete)	0440	40	Feed Forked Connection with 175j for 28K
8347b	928	Bobbin Winder (automatic), complete, Nos.	8444	926	and 128K Machines
		92b, 2749, 8256b, 8260, 8342 to 8346b,	8445	811	Shuttle Bell Crank
		15287, 15288b, 50101b, 50102f, 50104b,	0440	011	Shuttle Pitman with two 175j for 28K and
		55514b, 80272 and two 1718h, for 28K3,	8446	43	128K Machines Arm Shaft for 28K and 128K Machines
		28K4, 127K and 128K Machines (Obsolete)	*8447	40	Arm with 443c, 8206, 15404 and two 15405
8348	43	Feed Forked Connection with 175j for 127K	78447		
		Machines	*8450		for 28K Machines
8352	43	Arm Rock Shaft with 50571e for 28K and	8879	2520	Bed for 128K Machines
		128K Machines		813	Arm Spool Pin Washer (cloth)
8353		Arm Shaft for 28K Machines (Obsolete)	12329	010	Tension Releasing Lever Spring for 127K Machines
8355		Balance Wheel for 28K1 and 28K2 Machines	15152		
		(Obsolete)	10102	•	Clamp Stop Motion Flanged Bushing 2021 with two 462al for 27K Machines
8355b		Balance Wheel for 28K3 and 28K4 Machines			with two 462al for 27K Machines (Obsolete)
		(Obsolete)	15281	46	Presser Foot for 27K and 28K Machines
8359		Clamp Stop Motion, complete, Nos. 248f,	1,0201	317	(Obsolete)
		256d, 2020 and 8423, for 28K1 and 28K2	15282b	1152	7) 1 110 1 017 15 15
		Machines (Obsolete)	15282p	1152	Balance Wheel 24 "Pulley Balance Wheel 24" Pulley
8359b		Clamp Stop Motion, complete, Nos. 248a,	15287	929	Bobbin Winder Friction Ring (rubber) for
		256b, 2020 and 8423 for 28K3 and 28K4	177401	., 2.,	8347, 8347b, 55511 and 55511b
		Machines (Obsolete)	15288	929	Bobbin Winder Spindle Pulley for 8347 and
*8360	47	Clamp Stop Motion Flanged Bushing for			55511
		8423 (Obsolete)	15288b	929	Bobbin Winder Spindle Pulley for 8347b and
8361	44	Face Plate 54529 with 125423 for 28K			55511b
		Machines	*15312	926	Clamp Stop Motion Flanged Bushing
8361b	44	Face Plate 54529b with 125423b for 28K	15313	20	Clamp Stop Motion Flanged Bushing with
		and 128K Machines	10010		100.16 15014 1.55014
8361p	44	Face Plate 54529p with 125423b for 28K	75074		
omorp	••	and 128K Machines	15314		Clamp Stop Motion, complete, Nos. 248f, 256d,
8363	49	Feed Rock Shaft 8364 with 8220 for 28K			2020 and 15313 for 28K Machines
0000	43		15314b		Clamp Stop Motion, complete, Nos. 248a,
0001		,			256b, 2020 and 15313
8364		Feed Rock Shaft for 8363 (Obsolete)	*15404		Trade Mark for 8447, 54501 and 55501
8365	44	Needle Bar for 28K and 128K Machines	15405		Trade Mark Rivet for 8447, 54501 and 55501
8366	44	Presser Bar for 28K and 128K Machines	15429	1151	Presser Foot for stitching on edge and in-
8396	2520	Arm Rock Shaft Centre (upper) for 28K and			serting cord
		128K Machines	25525	905	Bias Gauge
8423		Clamp Stop Motion Flanged Bushing 8360	25527Ь	905	* Cloth Guide for 86502 (Attachments)
0,420		with two 462al for 8359 and 8359b	25537	905	Screw Driver (machine) for 86502
		(Obsolete)	25539	905	Stiletto for 35985
*0400		,	26075	2520	Thread Cutter and Holder
*8426		Arm with 443c and 8206 for 28K Machines	32562	2520	Feed Cam with 1285c
		(Obsolete)	• 32572	926	Tension Releasing Disc for 55520

No.	Plate		No.	Plate	
32675	47	Presser Bar Spring for 28K and 128K Machines	54505	926	Shuttle, complete, Nos. 215h, 8228, 8326 and 54504 for 127K and 128K Machines
35931	930	Hemmer (adjustable) for 86502 (Attachments)	*54506	926	Shuttle Carrier for 54527
35932	930	Quilter	54507	-	Shuttle Carrier, complete, Nos. 50126e,
35934	910	Ruffler Shirring Plate for 120291			54510, 54511 and 54527 for 127K and
35937	910	Under Braider			128K Machines
35983	1151	Tubular Trimming Attachment Strip Wire for 35985	*54508	926	Shuttle Carrier Cushion Spring for 54527
35984	1151	Tubular Trimming Attachment Presser Foot	*54509	926	Shuttle Carrier Cushion Spring Rivet for 54527
99904	11.71	(strip folding), with tube, for 35985	54510	926	Shuttle Ejector for 54507
35985	1151	Tubular Trimming Attachment, complete,	54511	926	Shuttle Ejector Spring for 54507
		for making $\frac{3}{32}$ ", $\frac{1}{8}$ " and $\frac{5}{32}$ " trimmings,	54512	927	Shuttle Slide (back) for 28K Machines
		Nos. 25539, 35983 and 35984	54512b	927	Shuttle Slide (back) for 28K and 128K
36583	1160	Tucker for 86502 (Attachments)	· · · · · · · · · · · · · · · · · · ·		Machines
39443	2520	Tension Releasing Lever Spring for 128K	54513	927	Shuttle Slide (front) for 28K Machines
		Machines	54513b	927	Shuttle Slide (front) for 28K and 128K
50036b	926	Shuttle Bell Crank Hinge Screw	W117	., .,	Machines
50053b	53	Cloth Guide Thumb Screw for 86502	54514	926	Tension Releasing Lever for 128K Machines
		(Attachments)	54515	926	Tension Releasing Pin for 55520
50101b	929	Bobbin Winder Frame Hinge Screw for 8347b	54516	46	Thread Take-up Spring Regulator Plate for
		and 55511b	71710	11,7	28K Machines
50101d	929	Bobbin Winder Frame Hinge Screw for 8347	54525b	1690	Arm Side Cover for 28K and 128K Machines
		and 55511	54527	-	Shuttle Carrier 54506 with 54508 and two
50102f	929	Bobbin Winder Spindle for 8347, 8347b,	77 177 207		54509 for 54507
001011	V-V	55511 and 55511b	*54529		Face Plate for 8361
50104b	929	Bobbin Winder Worm Wheel Screw Stud	*54529b	-	Face Plate for 8361b
001040		(eccentric) for 8347b and 55511b	*54529p		Face Plate for 8361p
50104d	929	Bobbin Winder Worm Wheel Screw Stud	54530	2520	Thread Take-up Spring Regulator Plate for
001040	.//	(eccentric) for 8347 and 55511			127K and 128K Machines
501960	926	O1 111 TO: 1 TI: 2 C	*55501		Arm with 443c, 8206, 15404 and two 15405,
50126e 50231a	53	Bobbin Winder Cam Screw for 55514b	<i>5,15</i> (/1		for 127K Machines
50231a 50231f	53	Bobbin Winder Cam Screw for 55514	55503b	927	Shuttle Slide (back) for 127K Machines
50527c	53	Thread Take-up Lever Hinge Screw for 55526	55504b	927	Shuttle Slide (front) for 127K Machines
000210		and 55526b	55505	926	Tension Releasing Lever for 127K Machines
50571e	53	Arm Rock Shaft Adjusting Screw for 8352 1.8203	55506	926	Tension Releasing Lever Hinge Pin for 127K
51045c	53	Machine Hinge Connection Set Screw	***************************************	,,,,,	Machines
51224b	53	Arm Side Cover Thumb Screw	55507	813	Presser Bar Spring Bracket with 453c
51224b	53	Presser Foot Thumb Screw	55509	1692	Bobbin Winder Bracket (belt cover) for 55511
51224d	53	Arm Side Cover Thumb Screw	4,0,10,0	11112	and 55511b
51224d	53	Presser Foot Thumb Screw for 28K Machines	55510	1692	Bobbin Winder Frame for 55511 and 55511b
*54501		Arm with 443c, 8206, 15404 and two 15405,	55511	1092	Bobbin Winder (automatic), complete, Nos.
_		for 128K Machine	<i>000</i> 11		92d, 2749, 8256, 8260, 8342, 8343, 8346,
54503	926	Presser Bar Lifter for 28K Machines			15287, 15288, 50101d, 50102f, 50104d,
54503b	926	Presser Bar Lifter			55509, 55510, 55512, 55514 and two 1718h,
*54504		Shuttle Body for 54505			for 28K1 and 28K2 Machines
		·			

No.	Plate	
55511b		Bobbin Winder (automatic), complete, Nos.
		92b, 2749, 8256b, 8260, 8342, 8343, 8346b,
		15287, 15288b, 50101b, 50102f, 50104b.
		55509, 55510, 55512, 55514b and two
		1718h, for 28K3, 28K4, 127K and 128K
		Machines
55512	1692	Bobbin Winder Frame Friction Washer for
		55511 and 55511b
55514		Bobbin Winder Worm Wheel 8261 with 8257
		and 50231f for 8347 and 55511
55514b		Bobbin Winder Worm Wheel 8261b with
		8257b and 50231a for 8347b and 55511b
55515	2520	Bed Oil Hole (shuttle) Packing (braided
		cotton)
55520		Tension, complete, Nos. 1274j, 1560g, 8238h,
		8244, 32572, 54515 and two 2102, for 127K
		and 128K Machines
55521	2520	Thread Take-up Cam 55523 with 448c
*55523		Thread Take-up Cam for 55521
*55525	46	Thread Take-up Lever with 1822 for 55526
*55525b	46	Thread Take-up Lever with 1822 for 55526b
55526		Thread Take-up Lever 55525 with 50527c for
		28K Machine
55526b		Thread Take-up Lever 55525b with 50527c
*55529b		Face Plate for 8210b
*55529p		Face Plate for 8210p
55531	2114	Hand Attachment Crank Lever Lock Pin
		Spring for 94051b

No.	Plate	
80002		Balance Wheel for 27K1 and 27K2 Machines
		(Obsolete)
80002b		Balance Wheel for 27K3 and 27K4 Machines
		(Obsolete)
80028	2114	Hand Attachment Pinion Dowel Pin for 94070
80272	929	Bobbin Winder Frame Friction Washer for
		8347 and 8347b (Obsolete)
80307p	1690	Arm Side Cover (plain) for 127K Machines
81704		Arm with 443c and 8206 for 80150 for 27K1
		and 27K2 Machines (Obsolete)
81709		Arm with 443c and 8206 for 81712 for 27K1
		and 27K2 Machines (Obsolete)
81710	46	Feed Dog, without teeth at right of needle, for
		27K and 28K Machines (Obsolete) Throat Plate for 81710 (Obsolete)
81711	46	
81715p		Arm Side Cover (plain) for 28K and 128K Machines
81728		Bed for 28K Machines
81729		Tension, complete, Nos. SS416, 1560, 8237.
		8238 and two 2102, for 28K Machines
81739	1.1	Belt Cover for 28K Machines (Obsolete)
81742		Drip Pan for 28K and 128K Machines
85893	1151	Embroidery Foot (for art work)
86080	813	Feed Cover Plate
86493	1160	Darning Presser Needle Clamp with 140545k
		for 86496
86494	1160	Darning Presser Needle Clamp Stripper Spring
		for 86496
86495	1160	Darning Presser Needle Clamp Stripper Spring
		Evelet for 86496
86496	1160	Darning Presser, complete, Nos. 86493 to
		86495
86502		Attachment Set, complete, Nos. 25527b,
		25537, 35931, 36583, 50053b, 120378,
		120842, 120862, 121464, three 8228 and
		six needles
87321		Drip Pan for 127K Machines
87586		Embroidery Hoop (round, birch) 5\u00e5'' diam.
		× 7 ½ high
87589	1221	Embroidery Hoop (round, birch) 8" diam.
		$\times 7^m_m$ high
87593		Embroidery Hoop (round, birch) 10" diam.
		× 76 " high
87595		Embroidery Hoop (round, birch) 12" diam.
		× ½" high
87597		Embroidery Hoop (oval, birch) $12'' \times 5\frac{1}{2}'' \times 7^m_{m}$
		high

N	T.1	
No.	Plate	••
94016	2284	Hand Attachment Gear Cover for 94052b
94027	2284	Hand Attachment Body Bracket for 94052b
94028	2114	Hand Attachment Crank Handle (wood) for 94034b
94029b	2114	Hand Attachment Crank Handle Spindle for 94034b
94030b	2114	Hand Attachment Crank Handle Spindle Flange (loose) for 94034b
94031a	2284	Hand Attachment Crank Lever for 94034b
94032	2114	Hand Attachment Crank Lever Lock Pin for
34032	2114	94051b
94033b	2114	Hand Attachment Crank Lever Lock Pin Head for 94051b
94034b		Hand Attachment Crank, complete, Nos.
		94028, 94029b, 94030b and 94031a, for 94052b
94036	2114	Hand Attachment Driver Finger for 94041
94037	2114	Hand Attachment Driver Finger to 54041 Hand Attachment Driver Finger Latch for
		94052b
94038	2114	Hand Attachment Driver Finger Latch Spring
		for 94052b
94039	2114	Hand Attachment Driver Finger Driving Pad (raw-hide) for 94041
94040	2114	Hand Attachment Driver Finger Driving Pad Plate for 94041
94041		Hand Attachment Driver Finger 94036 with
		SS567e, 94039 and 94040 for 94052b
94044	2114	Hand Attachment Driver Finger Hinge Pin
0.40.40	3114	for 94052b
94046 94048	2114	Hand Attachment Driver for 94070
94050	$\frac{2114}{2284}$	Hand Attachment Pinion for 94070 Hand Attachment Body for 94052b
94051b	$\frac{2284}{2284}$	Hand Attachment Body for 94052b Hand Attachment Gear with 55531, 94032
940910	440±	and 94033b, for 94052b
94052b	2284	Hand Attachment, complete, Nos. SS565e, SS566c, SS599f, SS600f, 94016, 94027,
		94034b, 94037, 94038, 94041, 94044,
		94050, 94051b, 94069, 94070, two each 183e and 399a
94069	2114	Hand Attachment Crank Hinge Pin for 94052b
94070	Z114 	Hand Attachment Driver 94046 with 80028
03010	-	and 94048, for 94052b
96416		Embroidery Hoop (round, birch) 7" diam.
		$\times 7^{n_{V}}_{m}$ high

NUMERICAL LIST OF PARTS

No.	Plate	
96417	-	Embroidery Hoop (round, birch) $5\S''$ diam. $\times 7\rlap/m$ high with $SS528j$, $NN95j$, two 96425 and four 96427
96418		Embroidery Hoop (round, birch) 7" diam. $\times 7_m^m$ high with SS528j, NN95j, two 96426 and four 96427
96419		Embroidery Hoop (round, birch) $8''$ diam. \times 7_m^m high with $SS528j$, $NN95j$, two 96426 and four 96427
96420		Embroidery Hoop (round, birch) 10" diam.× $\frac{1}{16}$ " high with SS528j, NN95j, two 96426 and four 96427
96421		Embroidery Hoop (round, birch) 12" diam. × ½" high with SS528j, NN95j, two 96844 and four 96845
96422	1221	Embroidery Hoop (oval, birch) $9'' \times 4\frac{1}{2}'' \times 7^m_{.m}$ high
96423		Embroidery Hoop (oval, birch) $9'' \times 4\frac{1}{2}'' \times 7\frac{m}{m}$ high with $SS528j$, $NN95j$, 96425 , 96426 and four 96427
96424		Embroidery Hoop (oval, birch) $12'' \times 5\frac{1}{2}'' \times 7\frac{m}{m}$ high with $SS528j$, $NN95j$, 96425 , 96426 and four 96427
96425	2399	Embroidery Hoop Clamping Bracket for 96417, 96423 and 96424
96426	2399	Embroidery Hoop Clamping Bracket for 96418 to 96420, 96423 and 96424
96427	2399	Embroidery Hoop Clamping Bracket Rivet for 96417 to 96420, 96423 and 96424
96844	2399	Embroidery Hoop Clamping Bracket for 96421
96845	2399	Embroidery Hoop Clamping Bracket Rivet for 96421

No.	Plate	
120290	930	Ruffler for 120291
120291		Ruffler 120290 with 35934
120378	905	Screw Driver (shuttle tension) for 86502
120687	1151	Imitation Hemstitching Attachment with
		Yielding Presser Plate
120842	1151	Hemmer (foot), 👫 " hem, for 86502
		(Attachments)
120862	-	Tin of Oil $(1\frac{1}{3} \text{ oz.})$, for $86502 \dots \dots$
121441		Gathering Foot (double toe)
121464	930	Binder for 86502
125422	2520	Face Plate Thread Guard for 125423
125422b	2520	Face Plate Thread Guard for 125423b
125423	2520	Face Plate Thread Guard 125422 with 125424
		for 8361
125 423 b	2520	Face Plate Thread Guard 125422b with
-		125424b, for 8210b, 8210p, 8361b and
		· 8361p
	2520	Face Plate Thread Guard Rivet for 125423
125424b		Face Plate Thread Guard Rivet for 125423b
125425b	1690	Arm Side Cover for 127K Machines
140545с	53	Needle Clamp Thumb Screw for 2054
140545k	1160	Darning Presser Needle Clamp Screw for
		86493