Home Survey

Property Information

Address: 319 Park Place Blvd, Nashville, TN 37205

Survey Date: July 22, 2022 Surveyor: Robert Williams

Exterior Assessment

Foundation

Type: Basement Condition: Good

Notes: Visible crack but seems non-structural.

Roof

Type: Asphalt shingles Estimated Age: 12 years

Condition: Good

Notes: No missing or damaged shingles.



Siding

Type: Vinyl Condition: Fair

Notes: Fading/chalking on south side.



Windows and Doors

Window Type: Double-pane

Door Type: Fiberglass Condition: Good

Notes: A few windows need re-caulking.

Interior Assessment

Electrical System

Type: Circuit breakers Amperage: 200 amp Condition: Good

Notes: No deficiencies identified.

Plumbing

Water Heater Type: Tank

Water Heater Age: 4 years Pipe Material: Copper/PVC

Condition: Good

Notes: No leaks, appears well-maintained.

HVAC System

Heating Type: Forced air Cooling Type: Central AC Age of Systems: 6 years

Condition: Good

Notes: Airflow is balanced.

Flooring

Types: Hardwood, Tile, Carpet

Condition: Good

Notes: Carpet is showing typical wear.

Walls and Ceilings

Condition: Fair

Notes: Previous water stain on living room ceiling.

Additional Notes

The exterior wood trim needs to be repainted within the next year.

Recommendations

- Re-caulk loose windows
- Repaint exterior trim
- Monitor living room ceiling for any new staining
- Perform regular HVAC maintenance

Overall Assessment

This is a well-built home that has been properly maintained over the years. Apart from some minor cosmetic repairs, no major system replacements are required at this time. The home is move-in ready.

Signature: Robert Williams

Date: July 22, 2022