ABC AUTO REPAIR

Claim ID: CLAIM-2025-001

123 Service Road

Boston, MA 02108

(617) 555-9876

License #: MA-AR-123456

REPAIR ESTIMATE

Date: September 03, 2025

Estimate#: EST-2025-0516-001

Vehicle Information:

Make: Toyota

Model: Camry Year: 2022

VIN: 1HGCM82633A123456

Mileage: 28,450

Insurance Information:

Policy #: AUTO-1234-5678

Claim #: Pending

ITEMIZED ESTIMATE:

Parts:

1. Rear Bumper Assembly......\$850.00

2. Left Tail Light Assembly......\$325.00

3. Right Tail Light Assembly......\$325.00

4. Trunk Alignment Hardware......\$150.00

5. Paint Materials.....\$200.00

<u>Labor:</u>

- 1. Bumper Replacement (2.5 hrs)....\$312.50
- 2. Tail Light Replace (1.0 hr).....\$125.00
- 3. Trunk Alignment (1.5 hrs)......\$187.50
- 4. Paint & Finish (4.0 hrs)......\$500.00

Additional:

- 1. Paint Blending.....\$250.00
- 2. Diagnostic Scan.....\$125.00

Subtotal.....\$3,350.00

Tax (6.25%)\$209.38

Total Estimate.....\$3,559.38

Estimator: Robert Johnson

ASE Certified #: ASE123456

Date: 09/03/2025