SBIG ECO

ECO#	ECO0280
Generated By:	Adam Robichaud
Date:	2015/11/27

Description:

Usability update to SBIG Driver Checker 64, and stability/speed updates to SBIGUDRV.DLL

Body: Removed "Download" button from SBIG Driver Checker 64,

and refactored its functionality into the "Update" button.

Removed "Current" column from driver status table to prevent

confusion about whether drivers are up to date. Added updated STF-8300 USB firmware (version to distribution.

Performance update to SBIGUDRV.DLL addressing speed

and stability concerns for all camera models via USB.

Updated redistributables are available in: \\OWEN\Shared\AdamR\ECO\ECO0280

SBIGUDRV.DLL 4.89 Build 1 changed to 4.90 Build 1.

Documents:

Action: Stock on hand: N/A

Update Sage 100: N/A

<u>Production</u>: Make sure all Production computers are running

latest software.

<u>Repair</u>: Make sure all Repair computers are running latest software.

Effective: Apply this ECO on all future production.

Fulfillment:

- Update SBIG FTP to include new installer/driver zip archive.
- Update SBIG CD-ROM to include new software