

The revolutionary project management tool is here and it's visual. Start Your Free Trial Now.

Custom Search

Suggest a Topic

Login

Write an Article

0

X

Flag register in 8085 microprocessor



Prerequisite - Registers of 8085 microprocessor

The **Flag register** is a Special Purpose Register. Depending upon the value of result after any arithmetic and logical operation the flag bits become set (1) or reset (0). In 8085 microprocessor, flag register consists of 8 bits and only 5 of them are useful.

The 5 flags are:





1. **Sign Flag (S)** – After any operation if the MSB (B(7)) of the result is 1, it in indicates the number is negative and the sign flag becomes set, i.e. 1. If the MSB is 0, it indicates the number is positive and the sign flag becomes reset i.e. 0.

from 00H to 7F, sign flag is 0 from 80H to FF, sign flag is 1

1- MSB is 1 (negative)

0- MSB is 0 (positive)



Example:

MVI A 30 (load 30H in register A)

MVI B 40 (load 40H in register B)

SUB B (A = A - B)

These set of instructions will set the sign flag to 1 as 30 – 40 is a negative number.



MVI A 40 (load 40H in register A)

MVI B 30 (load 30H in register B)

SUB B (A = A - B)

These set of instructions will reset the sign flag to 0 as 40 – 30 is a negative number.

2. **Zero Flag (Z)** – After any arithmetical or logical operation if the result is 0 (00)H, the zero flag becomes set i.e. 1, otherwise it becomes reset i.e. 0.

00H zero flag is 1.

from 01H to FFH zero flag is 0

1- zero result

0- non-zero result

Example:

MVI A 10 (load 10H in register A)

SUB A (A = A - A)

These set of instructions will set the zero flag to 1 as 10H – 10H is 00H

3. **Auxiliary Cary Flag (AC)** – This flag is used in BCD number system(0-9). If after any arithmetic or logical operation D(3) generates any carry and passes on to B(4) this flag becomes set i.e. 1, otherwise it becomes reset i.e. 0. This is the only flag register which is not accessible by the programmer

1-carry out from bit 3 on addition or borrow into bit 3 on subtraction 0-otherwise

Example:

MOV A 2B (load 2BH in register A)

MOV B 39 (load 39H in register B)

ADD B (A = A + B)

These set of instructions will set the auxiliary carry flag to 1, as on adding 2B and 39, addition of lower order nibbles B and 9 will generate a carry.

4. **Parity Flag (P)** – If after any arithmetic or logical operation the result has even parity, an even number of 1 bits, the parity register becomes set i.e. 1, otherwise it becomes

reset i.e. 0.

1-accumulator has even number of 1 bits

0-accumulator has odd parity

Example:

MVI A 05 (load 05H in register A)

This instruction will set the parity flag to 1 as the BCD code of 05H is 00000101, which contains even number of ones i.e. 2.

5. Carry Flag (CY) – Carry is generated when performing n bit operations and the result is more than n bits, then this flag becomes set i.e. 1, otherwise it becomes reset i.e. 0. During subtraction (A-B), if A>B it becomes reset and if (A<B) it becomes set. Carry flag is also called borrow flag.

1-carry out from MSB bit on addition or borrow into MSB bit on subtraction 0-no carry out or borrow into MSB bit

Example:

MVI A 30 (load 30H in register A)

MVI B 40 (load 40H in register B)

SUB B (A = A - B)

These set of instructions will set the carry flag to 1 as 30 – 40 generates a carry/borrow.

MVI A 40 (load 40H in register A)

MVI B 30 (load 30H in register B)

SUB B (A = A - B)

These set of instructions will reset the sign flag to 0 as 40 – 30 does not generate any carry/borrow.



Recommended Posts:

8085 program to access and exchange the content of Flag register with register B

Flag register of 8086 microprocessor

8085 program to find 2's complement of the contents of Flag Register

Register content and Flag status after Instructions

8085 program to exchange content of HL register pair with DE register pair

8085 program to count the number of ones in contents of register B

Bus organization of 8085 microprocessor



Interrupts in 8085 microprocessor

Pin diagram of 8085 microprocessor

Registers of 8085 microprocessor

Arithmetic instructions in 8085 microprocessor

Instruction cycle in 8085 microprocessor

Branching instructions in 8085 microprocessor

Addressing modes in 8085 microprocessor

Interface 8254 PIT with 8085 microprocessor



Check out this Author's contributed articles.

If you like GeeksforGeeks and would like to contribute, you can also write an article using contribute.geeksforgeeks.org or mail your article to contribute@geeksforgeeks.org. See your article appearing on the GeeksforGeeks main page and help other Geeks.

Please Improve this article if you find anything incorrect by clicking on the "Improve Article" button below.



Article Tags: Computer Organization & Architecture | microprocessor

Practice Tags: microprocessor



Be the First to upvote.

To-do Done

Based on 1 vote(s)





Please write to us at contribute@geeksforgeeks.org to report any issue with the above content.

×

Writing code in comment? Please use ide.geeksforgeeks.org, generate link and share the link here.

Load Comments

Share this post!

A computer science portal for geeks

710-B, Advant Navis Business Park, Sector-142, Noida, Uttar Pradesh - 201305 feedback@geeksforgeeks.org

COMPANY

About Us Careers Privacy Policy Contact Us

PRACTICE

Company-wise
Topic-wise
Contests
Subjective Questions

LEARN

Algorithms
Data Structures
Languages
CS Subjects
Video Tutorials

CONTRIBUTE

Write an Article
Write Interview Experience
Internships
Videos

@geeksforgeeks, Some rights reserved

