











Revision History A) Rev. 01 - (2012/03/08) B) Rev. 11 - (2012/06/13) 1) Swap pin MICRO USB FS DN and pin MICRO USB HS DP. 2) Modify reset circuit for U6 3) Add J267. (For manufacturing requirement) 4) Add J11. (2x9 Header for MCU GPIO signal test) 5) Change D7 for VDD 3V3 indication. 6) Change D8 for VDD 3V3 Module In indication. 7) Re-define pin definition for J10. 8) Remove C41,C42,R99,R84,R85,R86,R87. 9) Remove U2, U3. 10) Add JR5, JR6, JR7, JR8, JR9, J3, J25, J262, R96, R99, R100 11) Add U8 (SPI flash) 12) Add U11 (Slow CLK for BCM43362 failure analysis without MCU) 13) Change SW1 to another push button 14) Add J268 (2x3 Header) **Revision History** Document Number Size Rev WM-N-BM-09 EVB Tuesday, June 19, 2012