
Oveall Performance Cooler Accumulator Pump Valve


Overall Stability of Hydraulic System



Overall stability of the hydraulic system:

0: conditions were stable1: static conditions might not have been reached yet

Performance Valve Condition




Performance of valve condition:

100: optimal switching behavior

90: small lag

80: severe lag

73: close to total failure





Performance of Hydraulic Accumulator 130 Hydraulic accumulator / bar **Performance of hydraulic accumulator:** 130: optimal pressure 115: slightly reduced pressure 100: severely reduced pressure 90: close to total failure 31 Dec 12:00 31 Dec 18:00 01 Jan 00:00 31 Dec 06:00 01 Jan 06:00 01 Jan 12:00 Time

Oveall Performance Cooler Accumulator Pump Valve

