
E8: after the hazard moves (step 5000)
static
moved,
tuned decay
moved,
fast decay
Items delivered after the move
Robots lost after the move
C0
C1
C2
C4