
Canopy (moving)
Fuselage rim
Alert unit
Cockpit
Steel target
Bolt 1 tip
Bolt 2 tip
Bolt 3 tip
S0 seated
S1 lug 1
S2 lug 2
S3 lug 3
green only if
S0 and S1–S3
phase logic
self-test
event log
3-colour lamp
Chime / voice
Throttle shaker
Take-off gate
G1000 + log
throttle, IAS
14 V bus
split line:
nothing crosses