
Output Quality by Model and Complexity
Color-coded Performance Matrix
Model Type
Fine-tuned
Pre-trained
(with examples)
Pre-trained
(no examples)
0.0
1.0
1.0
1.0
0.0
1.0
0.5
0.5
0.5
0.5
0.0
0.0
0.0
0.0
0.0
1 zones
2 zones
4 zones
10 zones
20 zones
Building Complexity (Zone Count)
Quality Score
(1.0 = Perfect, 0.5 = Partial, 0.0 = Failed)
1.0
0.8
0.6
0.4
0.2
0.0