

AYE
TECH HUB

• AUTOCAD • LESSON 02

AutoCAD Interface

Ribbon · Command Line · Object Snap · Workspaces

Lesson 02 of 30 | AutoCAD Program

Awet G. Nway

Founder, AYE Tech Hub | CAD & BIM Design Specialist

- Every interface zone explained: Ribbon, Command Line, Status Bar
- The Command Line: why it is the fastest way to work in AutoCAD
- Object Snap (OSNAP): the settings every professional uses
- Function keys F1-F12 and their critical roles
- 20 essential keyboard shortcuts to work 3× faster

The AutoCAD Interface — 5 Zones to Know

The AutoCAD interface looks complex the first time. But it follows a simple logic: every zone has one clear purpose. Learn what each zone does and you will navigate any AutoCAD version — from 2014 to 2026 — confidently from day one.




Figure 1 — AutoCAD Interface: 5 Key Zones

Zone	Purpose	Key Tip
① Application Menu & Quick Access Toolbar	Application Menu (big "A" button): New, Open, Save, Print, Export, Options. Quick Access: customisable one-click buttons for most frequent commands.	Add LAYER, PLOT, UNDO to Quick Access — right-click any ribbon button → "Add to Quick Access Toolbar"
② Ribbon	All AutoCAD commands organised into tabs (Home, Insert, Annotate, etc.) and panels within each tab. Context-sensitive — changes when you select objects.	Ribbon is slower than typing commands. Use it to discover commands, then learn the keyboard shortcut. Collapse ribbon to gain drawing space.
③ Drawing Area (Model Space)	The infinite drawing canvas where you model at real-world size (1:1 scale). The crosshair cursor tracks your mouse position. ViewCube in top-right corner.	Model Space is always 1:1 scale. Scale is only applied in Paper Space layouts. ZOOM and PAN with scroll wheel and middle mouse button.
④ Command Line	The most important zone. Type any command here. AutoCAD shows prompts, options, and feedback in the command line.	Never click a ribbon button when you can type the shortcut. F2 opens the text window to see full command history.
⑤ Status Bar	Toggles for drawing aids: SNAP, GRID, ORTHO, POLAR, OSNAP, OTRACK, DYN. Also shows current scale, annotation scale, and workspace.	Right-click any status bar icon to access settings. Green = ON. Grey = OFF. OSNAP and ORTHO are the most important.

The Command Line is your best friend: Every AutoCAD professional types commands rather than clicking ribbon icons. Typing LINE is faster than finding it in the ribbon. AutoCAD also shows you the command options (in square brackets) and current coordinates in the command line. Reading the command line while working is the number one habit separating beginners from professionals.

Object Snap (OSNAP) and Drawing Aids

Object Snap (OSNAP) is the most important precision tool in AutoCAD. It snaps your cursor to exact geometric points on existing objects — endpoints, midpoints, centres, intersections. **Without OSNAP, precise technical drawing is impossible.** Every professional has OSNAP on at all times.





Figure 2 — Key Object Snap Modes and Their Keyboard Letters

Drawing Aid	Shortcut	What It Does	When to Use
ORTHO	F8	Constrains cursor to exactly horizontal or vertical movement only	Drawing walls, structural grids, any horizontal/vertical line
POLAR TRACKING	F10	Snap to angles at specified increments (e.g. every 15° or 45°)	Drawing angled elements; use 45° increment for isometric or angled walls
OBJECT SNAP (OSNAP)	F3	Snaps to geometric points on objects (endpoint, midpoint, centre, etc.)	ALL THE TIME — turn this off only when it is interfering with a specific task
OBJECT TRACKING (OTRACK)	F11	Tracks alignment paths extending from OSNAP points — draw in alignment	Aligning new objects to existing ones without drawing temporary lines
DYNAMIC INPUT (DYN)	F12	Shows coordinate input boxes at cursor — type distances directly in drawing area	Beginners find this helpful; professionals often disable it and use command line
SNAP TO GRID	F9	Locks cursor to regularly spaced grid points (not the visible grid)	Schematic drawings, electrical diagrams — disable for general technical drawing
GRID DISPLAY	F7	Shows a visual reference grid (does not affect cursor unless SNAP F9 is on)	Useful reference when starting — most professionals disable it for clean view

Function Keys — Master Reference

Figure 3 — F-Key Reference: Red/Coloured = Most Used in Daily Work



Recommended OSNAP settings for engineering work: Right-click the OSNAP button (F3) → OSNAP Settings → tick: Endpoint, Midpoint, Center, Intersection, Perpendicular, Nearest. Untick: Apparent Intersection, Extension, Parallel (these can interfere). These six snaps cover 95% of all engineering drawing needs.

Essential Keyboard Shortcuts and Workspaces

AutoCAD has hundreds of commands. These 30 shortcuts and aliases cover 90% of what you will do on any engineering drawing. Memorise these first — everything else you can look up as needed.

Shortcut / Alias	Command	Shortcut / Alias	Command
L	LINE	E	ERASE
PL	PLINE (polyline)	C	CIRCLE
A	ARC	REC	RECTANGLE
EL	ELLIPSE	SPL	SPLINE
CO	COPY	M	MOVE
MI	MIRROR	RO	ROTATE
SC	SCALE	S	STRETCH
TR	TRIM	EX	EXTEND
O	OFFSET	F	FILLET
CHA	CHAMFER	AR	ARRAY
LA	LAYER (dialog)	LT	LINETYPE
OP	OPTIONS (settings)	UN	UNITS
DI	DISTANCE (measure)	ID	ID POINT (coordinate)
Ctrl+Z	UNDO	Ctrl+Y	REDO
Ctrl+S	SAVE	Ctrl+P	PLOT (print)
Z+E	ZOOM EXTENTS	Z+A	ZOOM ALL
Esc	Cancel current command	Space	Repeat last command
Enter	Confirm / end command	Tab	Cycle OSNAP points
Shift+right-click	OSNAP menu	Scroll wheel	Zoom in/out

Workspace Configuration

Workspace	What It Shows	Best For
Drafting & Annotation	Full ribbon with 2D drafting tools. Most common workspace for 2D work.	Daily 2D technical drawing — floor plans, details, schematics
3D Modeling	Ribbon reorganised for 3D tools — solids, surfaces, mesh.	When creating 3D models in AutoCAD (rare for engineers, more for designers)
3D Basics	Simplified 3D workspace for learning 3D modelling.	Beginners learning AutoCAD 3D
AutoCAD Classic (custom)	Toolbars instead of Ribbon — older interface style.	Users migrating from AutoCAD 2008 and earlier who prefer toolbars

Interface Customisation	How to Do It	Why Bother
Collapse ribbon to tabs only	Click the small triangle at far right of ribbon → "Minimize to Tabs"	Doubles your drawing area — access panels by clicking tabs as needed

Add commands to QAT	Right-click any ribbon button → "Add to Quick Access Toolbar"	One-click access to your 5 most-used commands
Change crosshair size	Options → Display → Crosshair size → set 5-100 (100 = full screen)	Larger crosshair helps alignment. Most professionals use 5-10%.
Dark vs light background	Options → Display → Colors → change Drawing Window color	Dark background reduces eye strain for long drawing sessions
Command line height	Drag top edge of command line up to show more history lines	See more command feedback without using F2 text window

What comes next — CAD-003: Drawing Tools — mastering LINE, PLINE, ARC, CIRCLE, RECTANGLE, and SPLINE with precision input methods (absolute coordinates, relative coordinates, polar coordinates, and direct distance entry).