

Building patch cable:

For building cable, you need a crimping tool, a 5e network cable, and rj-45.

In the first step, you must use a crimping tool and cut the cable.



You must twist the cable ends with their pair in the second step. You will see matching colors.



Now you can plug rj-45 into the end of your cable, don't forget to cut plastic in the middle of the cable.



You can test your cable with a cable tester.