

Reserve Study (Draft for Board Review)

Sample document for the Willow Creek HOA demo. Not a real governing document.

Prepared by Hartwell Consulting. Draft; figures subject to revision.

Summary

Reserve balance after the pool resurfacing draw: \$18,200. Recommended fully funded balance: \$52,000. Percent funded: 35%.

Major Components

Pool surface and equipment: remaining life 12 years after resurfacing; replacement cost \$45,000.

Clubhouse roof: remaining life 6 years; replacement cost \$22,000.

Perimeter fencing: remaining life 4 years; replacement cost \$18,500.

Gate operators and keypads: remaining life 3 years; replacement cost \$9,000.

Recommendation

Increase the annual reserve contribution from \$6,000 to \$9,500 to reach full funding within ten years.