
(b) Mechanical numerical checks
Absolute mean-stress change (%)
0.0
0.1
0.2
0.3
0.4
0.07141
0.216
0.218
Ref. mesh
Open mesh
Open repair