DDAKE Charing Chart		Affiliated company	Shop :	
BPAKS Sharing Sheet		TOYOTA MOTOR THAILAND	Plant:  Ref. No.: In case ykt from other source (ex.shop jiku)	
I. Title:		(TMT)	Reg. No. : for MD only	
i. Title .			Safety Cost	
(W) BP Man power reduction : Deck ID Card Reader Machine				
(11) Di Man power readetion : Beek 15 cara		saaci iviaciiiic	Productivity (Smooth/Slim)	
II. Description :				
ii. Description .				
According of cost reduction and PEFF improvement activity, (W) try to reduce MUDA and KAIZEN process for minimize				
cost. So, we start from TPS basic knowledge and apply new equipment to KAIZEN our process.				
III. Yokoten Essence: Idea form :EASY BASS"				
Llow to edept this idea				
☐ Direct Yokoten ☐ Yokoten by Essence ☐ Yokoten by Essence ☐ The Maizen process ☐ The Maizen				
✓ New Initiative				
IV. Previous Status / Problem / Background :				
2 MP 2 Process				
Processs Lay-out Yamazumi (Be	fore		Piocess	
9 110ccs33 Lay Out   Sefore   120   MPEFF = 82.8	Τ/	T 90 sec		
(Cup Jig Repair Fitting T/G H/B H/S 80 90 95 97 94 97				
(S) (S) (A) (D) (S) (Waiting time MP-9 ID				
MP = 9 Au Σ CT = 709 Sec.		40 9	card process	
Σττ= 986 Sec. MPEFF = 71.90 %		29		
MP-1 MP-2 MP-3 MP-4 MP-5 MP-6 MP-7 MP-8 MP-9 MP-8 Cup Jig process				
Problem - MP-8 , MP-9 have a many waiting time.  only for safety				
- Ergonomic Problem from walk up-down the stairs.			Rank:	
			CONTROL LANGUAGE	
V. Kaizen or Improvement :				
Kaizen Idea  Trial Method  Trial Method				
- How to reduce job scan ID card?  - Study for auto scan ID				
- It possible to change method from manual to auto scan ID card?				
1 MP 2 process				
Processs Lay-out After Yamazumi (A	Afte	r)	2 process	
MPEFF = 88.5 T/T 90 sec				
(7) (3) (2) 100 MP Reduction (Cup Jig & Repair Fitting T/G H/ H/S 80 89 91 93 89 92				
8 6 5 4 1 60		29	Scan ID card	
MP = 8 αυ Σ CT= 689Sec.		40 9	By camera	
∑TT= 896 Sec. MPEFF = 76.89 %	Щ,	,	IP-8 Cup jig process	
MP-1 MP-2 MP-3 MP-4 MP-5		Trial conditio		
improvement V144	V086		by ED jig (Hood) Future Yokoten process expansion:	
- Balance Job from MP-9 to MP-8	Rody No. V011	EC Seavy House Color Rank :	process expansion .	
B12 B710 V227   Some	BAR_V011 eacial MSG. BW16	S12   S038   B487		
VI. Result Evaluation :		VII. Daily	Mgnt / How to maintain :	
(Result KPI / Process KPI impacted from improvement) (PDCA Concept for Genba)				
Reduce MP: 2 Person		No Need  Need		
			New Std. Review Std. sheet Control sheet for TM/TL/GL / MTN.	
MPEFF: 82.8%> 88.5% (+5.7%)  ☐ Control sheet for TM/TL/GL / MTN.  ☐ (Who/Method/Frequency/Abnormal Mgnt) ☐ Others				
Ergonomic : Reduce walk up-down the stair [Every cycle time]  Details (or Ref. Document) :				
			oval	
For safety: Rank Pank Investment Cost:	33	30,000 <b>Baht</b>		
Cost Saving/Reduction: 1.302 MB ROI:		Year GM (MD de	ot.) GM (PA) GM intiator	