



## Power

## Step-Down Convertor





Sheet: /Power/ File: Power.sch


Title:

 Size: A4
 Date:
 Rev:


 KiCad E.D.A. kicad (5.1.10-1-10\_14)
 Id: 2/5


**Sensors** Barometric Pressure Sensor +3.3V +3.3V +3.3V C300 C301 U301 BMP280 GND GND Inertial Measurement Unit +3.3V +3.3V +3.3V  $\frac{1}{100}$   $\frac{1}{100}$   $\frac{1}{100}$   $\frac{1}{100}$ GND GND Sheet: /Sensor/ File: Sensor.sch Title: Size: A4 Date: KiCad E.D.A. kicad (5.1.10-1-10\_14) **Rev:** Id: 3/5








**Decoupling Capacitors** 

















| Sheet: /MicroControlller/           |       |      |  |  |
|-------------------------------------|-------|------|--|--|
| File: MicroControlller.sch          |       |      |  |  |
| Title:                              |       |      |  |  |
| Size: A4                            | Date: | Rev: |  |  |
| KiCad E.D.A. kicad (5.1.10-1-10_14) |       |      |  |  |


## **Connectors**



## Peripherals







| Sheet: /Connectors/  |  |  |
|----------------------|--|--|
| File: Connectors.sch |  |  |
| Title:               |  |  |

| inte:           |                      |         |  |  |
|-----------------|----------------------|---------|--|--|
| Size: A4        | Date:                | Rev:    |  |  |
| KiCad E.D.A. ki | cad (5.1.10-1-10_14) | ld: 5/5 |  |  |