1) $Z(s)$ must be ratio of an even to add polynomial or odd even polynomial

$z(-s) = -z(s)$

2) All poles and zeros must be on jw axis but none in the left or right half of the plane.

3) Poles and zeros must be simple.

4) Poles and zeros must be alternate along jw axis

5) lowest degrees of $p(s)$ and $q(s)$ must differ by exactly one.

6) All coefficients of polynomial $p(s)$ & $q(s)$ must be real and positive.

Anika Sachan
2509500 8