
million CPU cycles
2.5
2.0
1.5
1.0
0.5
0
2.29
1.33
1.58
0.62
1.59
0.63
0.71
PIMony alone
MinorCPU
O3CPU
O3CPU*
CPU awake
CPU asleep in pim.wait (PIM busy)
PIM busy, no CPU
PIMony alone, same jobs