


Held-out H100 CAD edits: strict matches


mounting angle box x f130 | T1 | IoU 1.00000

Increase the box X dimension from 33.0 to 42.9.


SOURCE



RELEASED TARGET




H100 PREDICTION




locator block box y f130 | T1 | IoU 1.00000

Increase the box Y dimension from 82.2 to 106.86.


SOURCE



RELEASED TARGET




H100 PREDICTION




t3medplus stepped shaft rot diag60 | T2 | IoU 1.00000

Rotate the entire part by 60 degrees about the axis (1, 0, 1).

SOURCE



RELEASED TARGET



H100 PREDICTION

