



**GOVERNMENT OF TELANGANA
BOILERS DEPARTMENT**

Office of the Director of Boilers,
H.No.2-2-647/182/A, 3rd Floor,
Above State Bank of India,
Shivam Road, Bagh Amberpet,
Hyderabad – 500 013.

**RENEWAL AS MANUFACTURER OF BOILER & BOILER COMPONENTS
IN TELANGANA UNDER INDIAN BOILER REGULATIONS, 1950**

This is to certify that the capacity, capability, Inspection and Quality Management System of

**M/s. SAP ENGINEERING WORKS.,
Plot No/Sy.No. 42/5A/2,
Locality. MUDDAPUR CANAL,
Muddapur (Vi),
Kondapak (M),
Siddipet (Di),
502301 (Pin).**

Has been evaluated by the Directorate of Boilers and has been granted Renewal under Indian Boiler Regulations,1950 as Manufacturer of **Boiler Components.**

This certificate is valid for 2 years i.e upto **16/05/2027**

Validity is subject to the adherence to the quality control prescribed under the provision of the Indian Boiler Regulation,1950.

Certificate No. **TG/BM-06/2025**

Fee: **Rs. 3000/-**, Paid on **15/05/2025**
Challan No. **113766643025**

Date of issue. **19/05/2025**

**SREENIVAS
A RAO
MULLAPUDI**

Digitally signed by SREENIVASA RAO
MULLAPUDI
DN: c=IN, o=THE DIRECTOR OF BOILERS,
ou=THE DIRECTOR OF BOILERS, title=6dc3,
2.5.4.20=aad80da9735a24662f6c431cf4181
47bcd42822b4c89e0d7e6a0768aef55463,
postalCode=500013, st=TELANGANA,
serialNumber=f0863f2ba06cef66bc5e9c985
7025743ca6ecb2687d618d91a64ab097b69
7f6d, cn=SREENIVASA RAO MULLAPUDI
Date: 2025.05.19 14:48:33 +05'30'

**DIRECTOR OF BOILERS
TELANGANA, HYDERABAD**

INSTRUCTIONS

1. Any manufacturer of Boiler/Boiler Components shall be carried out manufacturing only after obtaining the approval of design drawings under the Boilers Act, 1923, and Indian Boiler Regulation 1950.
2. Stage inspections and quality shall be carried out strictly as per the Indian Boiler Regulation 1950.
3. Only approved electrodes shall be used in the welding work.
4. Clearance from the concerned Inspecting officer shall be obtained at every stage of erection, repairer, modification of Boiler/Economizer and erection of steam pipeline as stipulated under the Indian Boilers Regulation 1950 and its latest amendments.
5. All welding works shall be carried out through qualified welders. If any new qualified welders is proposed to be engaged, prior approval shall be obtained from the Director of Boilers.
6. A record of welding personnel engaged on welding should be maintained and produced to the inspecting authority, inspecting officer on demand.
7. Any changes in the address of workshop, shall be intimated to the Director of Boilers.
8. Application for renewal of Recognition shall be made at least two months before the expiry of the said period.
9. In case the repairer is found indulging in violating the provision of the Act/Regulations knowingly or unknowingly, the firm shall be blacklisted and renewal will not be done in any case.

* * *