

Problem Lifecycle

1. Citizen Report

Urgent

Submitter: Rajesh Karki

Timestamp: 2023-11-05 00:32

Evidence: 3 photos of crack and structural failure



3 photos of crack and structural failure

2. AI Assistance

AI categorization: Infrastructure/Bridge

Verified Location: Chitwan, Nepal (27.5°N, 84.4°E)

Confidence: 98%

Timestamp: 2023-11-05 08:33

3. Authority Verification

Verified

Role: Site Inspector Sharma - Chitwan Municipality

Status: Verified

Timestamp: 2023-11-05 14:15

Notes: Detailed structural assessment needed

4. Work Order

Approved

Role: Engineer Pradhan - MoPIT

Status: Approved

Timestamp: 2023-11-06 09:00

Budget allocated: \$12,500

Work Order ID: WO-9878

5. Builder Assigned

Assigned

Role: Project Manager BK - Lama Construction

Status: Assigned

Timestamp: 2023-11-06 16:30

☑️ Contract signed

6. Progress Updates

In Progress

Role: Field Engineer KC

Status: In Progress

Timestamp: Daily updates

Evidence:



55% complete

7. Inspection

Scheduled

Role: Senior Inspector Adhikari

Status: Scheduled

Timestamp: 2023-11-20

☑️ Pre-inspection checklist

8. Resolution

Closed

Role: Director Regmi

Status: Completion

Timestamp: 2023-11-21 17:00



☑️ Final sign-off

Map Ionim.



Evidence

