Safety Instructions

Kaveri Motion Components · Rev 2024

Safety

Never exceed the maximum operating pressure stated in the product manual; proof pressure is a factory test value only. Depressurise and lock out before maintenance; cylinders can move unexpectedly when air is applied. Machining, re-boring or welding products voids the warranty. Applications involving lifting of people or safety-critical functions (presses, guarding) require review by the customer's own safety engineer; KMC does not certify components for lifting people.