

✓ Congratulations! You passed!

TO PASS 80% or higher

False
True



grade 100%

Course assessment

LATEST SUBMISSION GRADE 100%				
1.	Which of the following is the correct representation of a 12mm user parameters after being linked to a dimension? #: 12.00. Up: 12.00. fx: 12.00. %: 12.00.	1/1 point		
	✓ Correct The answer can be found in Linking parameters and dimensions.			
2.	The symmetry constraints require 3 selections. First position, second position and a symmetry line. True False	1/1 point		
	Correct The answer can be found in Using symmetry and construction geometry.			
3.	What is the default operation type for an extrude when using a closed profile to create the first body in a design? New Component. Intersect. New Body. Join.	1/1 point		
	✓ Correct The answer can be found in Creating extruded features.			
4.	Closed profile sketches used for extrudes can't contain any additional sketch entities. • False • True	1/1 point		
	✓ Correct The answer can be found in Creating extruded features.			
5.	When projecting model edges that are not on the active sketch plane where are those projections created? On the active sketch plane. On the TOP plane. Projected edges must be on the active sketch plane. They are included in 3D.	1 / 1 point		
	✓ Correct The answer can be found in Projecting edges vs. including them.			
6.	A component is required to create mechanical motion in Fusion 360.	1/1 point		

Correct The answer can be found in The different ways to create components.	
 7. Which of the following is the best option to copy a component without retaining a link to the original? Copy/New. Copy/Paste Unique. Copy/Paste New. Copy/Paste. 	1/1 point
Correct The answer can be found in Copy paste and paste new.	
 8. A distributed design link can be broken. False True 	1/1 point
Correct The answer can be found in Distributed designs.	
 9. Which of the follow options allows you to manipulate the visual transparency of a component? Visual Control. Opacity Control. Display Control. Transparency Control. 	1/1 point
✓ Correct The answer can be found in Isolation and opacity control.	
 10. How do you minimize an expanded group in the timeline? Click the "-" button below it. Drag the timeline marker before it. Click the "+" button below it. Right click on the first feature and select "minimize". 	1/1 point
Correct The answer can be found in Creating groups and organizing a timeline.	
11. Ribs must have a closed profile sketch. False True	1/1 point
Correct The answer can be found in Adding ribs and plastic supports.	
 12. Which analysis type would be used to evaluate if a design contained an undercut that would restrict tool access? Section view. Minimum radius analysis. Draft analysis. Accessibility analysis. 	1/1 point
✓ Correct The product can be found in Applying deaft and design.	

13. What happens when a group of surfaces that form a closed region are stitched together?	1 / 1 point
They are converted to a solid body and the surface is removed.	
Nothing	
They create a closed set of surfaces.	
They are converted to a solid body and the surface body remains.	
✓ Correct	
The answer can be found in Surface creation for complex geometry.	
14. A surface used for replacing the face of a solid must extend out further than the solid face.	1/1 point
False True	
Correct The answer can be found in Using surfaces to replace faces.	
45. The self-feature are only be averated with a triangular area and in	
15. The coil feature can only be created with a triangular cross section. True	(1/1 point)
False	
Correct The answer can be found in Using a coil feature.	
16. What short-cut key is used to extrude faces during edit form?	1/1 point
CTRL.	
ALT.	
O SHIFT.	
○ TAB.	
✓ Correct	
The answer can be found in Creating holes and threads.	
17. Creased edged can't be undone.	1 / 1 point
O True	
False	
✓ Correct	
The answer can be found in Creasing or uncreasing an edge.	
18. Which utility can be used to repair star points on a form body?	1 / 1 point
Make Uniform.	
Repair Body.	
Repair Utility.	
Convert.	
✓ Correct	
The answer can be found in Repairs and modifications.	
19. Inserting edges must be done at existing intersection points.	1 / 1 point
○ True	
False	
✓ Correct	
The answer can be found in Inserting edges and subdivisions.	

20. After finishing a form body it can no longer be edited.	1/1 point
O True	
False	
✓ Correct	
The answer can be found in Working with a form as a BREP.	