



ISO-9650 liferaft — Spares : *Alternative painter activation label*

This Service Bulletin has been technically approved by Survitec Design Authority.

Signed: 

Dated: 04-Jun-2021

Richard Kerrigan
Marine Technical Manager
Survitec

BLANK PAGE

1. Introduction

A painter activation label (P/N E15500126) is attached to the fabric valise on ISO-9650 liferafts and gives instructions on how to use the painter line. This label is no longer available. However, Survitec has found an alternative.

The alternative, painter activation label (P/N E15500125) contains the same pictorial content as well as a multi-lingual service record section. When using this label, it must be trimmed so that it has the same finished dimensions as the old label.

From now on, when you need to order a new label, you must order P/N E15500125 (**Figure 2**). Existing stock of E15500126 (**Figure 1**) can still be used.

This Service Bulletin tells service stations how to replace a painter activation label on an ISO-9650 liferaft when required.



FIGURE 1
Painter activation label (old)
P/N E15500126




FIGURE 2
Painter activation label (new)
P/N E15500125

2. Equipment affected

ISO-9650 liferaft valises

3. Embodiment date

When required to replace valise label P/N E15500126 at service.

4. Necessary parts

Part Number	Description
E15500125	Painter activation label

5. Necessary equipment and tools

None required

6. Tasks

- A. Obey the correct service manual to service the liferaft.
- B. Remove the old painter activation label.
- C. Trim the new painter activation label so that you can only see the pictorial section. Make sure that the dimensions of the label are 155 × 47 mm.
Refer to **Figure 3**.
- D. Attach the new label to the fabric valise.



FIGURE 3
Trim the new painter activation label

7. Recording

None Required.

8. Reporting

None Required.

ISO-9650 liferaft — Spares : *Alternative painter activation label*

Service provider: _____

Associated Publications: *M 283 and M 307*

As part of Survitec Group procedures, each technician who is trained to service the equipment affected by this publication must read and fully understand this publication.

When each technician has read and fully understood the publication, they must complete and sign the table below.

Keep this table with this publication.

Each person named below has read and fully understood this publication:

BLANK PAGE