

Survitec

SURVIVAL TECHNOLOGY

Marine liferafts — Spare parts : *Consolidation of multiple branded part numbers*

This Service Bulletin affects products from the brands that follow:

	Survitec Dunmurry - Belfast Northern Ireland		Survitec Dunmurry - Belfast Northern Ireland
RFD Beaufort Inc	RFDB Inc Sharon Centre - Ohio USA		DBC Marine Safety Systems Ltd. Vancouver Canada
	SSPI Ohio USA		RFD Toyo Yokohama Japan
Survitec Safety Solutions	SSS		Survitec Zodiac Chevanceaux France
	Eurovinil S.p.A Grosseto Italy		
	DSB Deutsche Schlauchboot Eschershausen Germany		

This Service Bulletin has been technically approved by Survitec Design Authority.

Signed:



Dated: 27-May-2025

Simon Murray
Principal Engineer — MES
Survitec

12/24	Marine liferafts — Spare parts : <i>Consolidation of multiple branded part numbers</i>		
	Version 1:	May/25	Page 1 of 10

BLANK PAGE

1. Introduction

NOTE: This service bulletin was originally circulated as

*Marine liferafts — Spare parts :
Consolidation of multiple branded part numbers*

under the reference numbers which follow, which are now rescinded:

01/21 (RFD)	04/21 (SSS)	07/21 (Survitec)
02/21 (RFDB Inc)	05/21 (EV)	08/21 (DBC)
03/21 (SSPI)	06/21 (DSB)	09/21 (RFD Toyo)
		10/21 (Zodiac)

Within the range of Survitec liferaft components and spares items, several common parts have been identified and rationalised. These are:

- Anti-seasickness tablets
- First aid kits
- Lights and batteries

This service bulletin tells service stations about new part numbers and how to order them.

2. Equipment affected

All Marine liferafts equipped with the parts given in Paragraphs 4.A thru 4.C.

3. Embodiment date

You must do this service bulletin at each scheduled liferaft service.

An expected timetable for the introduction of each new part number is given at
6. Tasks.

4. Necessary parts

Each new part number can be purchased from Survitec.

A. Anti-seasickness tablets

The parts that follow have been replaced with Survitec-branded anti-sickness tablets.

Service Bulletin 01/21 thru 10/21 introduced Survitec-branded anti-sickness tablets. The table that follows shows the historic part number and current part number that you need to order.

You do not need to update your spares management system if you updated it in accordance with Version 2 of Service Bulletin 01/21 thru 10/21.

No changes have been made to the tablets or their containers.

Historic part number		Current part number	
Part number	Description	Part number	Description
DSB00940350	TABLET ANTI-SEASICK 60's DSB	01174009	TABLET ANTI-SEASICK 60'S (SURVITEC)
Z64514	TABLET ANTI-SEASICK 50'S SZ		

B. First aid kits

The parts that follow have been replaced with Survitec-branded SOLAS and CAT C first aid kits.

Service Bulletin 01/21 thru 10/21 introduced Survitec-branded SOLAS and CAT C first aid kits. The table that follows shows the historic part number and current part number that you need to order.

You do not need to update your spares management system if you updated it in accordance with Version 2 of Service Bulletin 01/21 thru 10/21.

No changes are being made to the contents of first aid kits.

Historic part number		Current part number	
Part number	Description	Part number	Description
15199001	KIT, FIRST AID *EN*	12865009	KIT FIRST AID SOLAS (SURVITEC)
DSB00940220	KIT, FIRST AID DSB UK		
05886009	KIT, FIRST AID *POLISH*		
11801009	KIT, FIRST AID CAT."C" EV	06484009	KIT FIRST AID CAT C (SURVITEC)
11802009	KIT, FIRST AID CAT."C" ZODIAC		
11803009	KIT, FIRST AID CAT."C" DSB		
11804009	KIT, FIRST AID CAT."C" RFD		
Z63703	KIT, FIRST AID CE	12874009	KIT FIRST AID CAT C EXT (SURVITEC)
06556009	KIT, FIRST AID EEC DIR/ SWEDISH		
12162009	KIT, FIRST AID EEC DIR/ DOT EXTENDED		

C. Lights and batteries

All current five-year life items have been replaced with Survitec-branded parts.

All Zodiac-branded lights and batteries have been replaced with Survitec-branded parts.

Service Bulletin 01/21 thru 10/21 introduced Survitec-branded five-year life items and lights. The tables that follows shows the historic part number and current part number that you need to order.

You do not need to update your spares management system if you updated it in accordance with Version 2 of Service Bulletin 01/21 thru 10/21.

The operation and performance of lights and batteries are not affected.

Historic part number		Current part number	
Part number	Description	Part number	Description
11785009	LIGHT READING RL6 RFD	12866009	LIGHT READING RL6 SURVITEC
11786009	LIGHT READING RL6 -DSB		
11787009	LIGHT READING RL6 -ZODIAC		
11796009	LIGHT READING RL6 EV		
11797009	LIGHT READING RL6 DBC		
12236009	LIGHT READING RL6 SURVITEC		

Historic part number		Current part number	
Part number	Description	Part number	Description
11788009	LIGHT P.I. RL6 RFD 650MM	12868009	LIGHT P.I. RL6 SURVITEC 650MM
11790009	LIGHT P.I. RL6 DSB 650MM		
11793009	LIGHT P.I. RL6 ZODIAC 650MM		
11798009	LIGHT P.I. RL6 EV 650MM		
11799009	LIGHT P.I. RL6 DBC 650MM		
12235009	LIGHT P.I. RL6 SURVITEC 650MM		
08279009	LAMP/INT+BATT D'MANT RL5 5YR	12869009	LAMP/INT+BATT D'MANT RL5 5YR SURVITEC
08402009	LAMP/INT+BATT D'MANT RL5 5YR		
11848009	LAMP/INT+BATT D'MANT RL5 5YR		
08280009	LAMP UNIT MARINE EXT. RL5 65	12870009	LAMP UNIT MARINE EXT. RL5 65 SURVITEC
08403009	LAMP UNIT MARINE EXT. RL5 65		
11847009	LAMP UNIT MARINE EXT. RL5 65		
08461009	LAMP UNIT MARINE EXT. RL5 950	12871009	LAMP UNIT MARINE EXT. RL5 950MM SURVITEC
06729009	POWER UNIT ASSY. MARINE RB2 RFD	12872009	POWER UNIT ASSY. MARINE RB2 SURVITEC
08195009	POWER UNIT ASSY. MARINE RB2 DSB		

Historic part number		Current part number	
Part number	Description	Part number	Description
11791009	LIGHT P.I. RL6 DSB 3500MM	12867009	LIGHT P.I. RL6 SURVITEC 3500MM
11800009	LIGHT P.I. RL6 DBC 3500MM		
11794009	LIGHT P.I. RL6 ZODIAC 4000MM	12875009	LIGHT P.I. RL6 SURVITEC 4000MM

The parts which follow will now be replaced with new part numbers:

Current part number		New part number	
Part number	Description	Part number	Description
Z64186	BATTERY RL6	12866009	LIGHT READING RL6 SURVITEC
Z64228	EXTERNAL LIGHT RL6 LR<25	12868009	LIGHT P.I. RL6 SURVITEC 650MM
Z64233	EXTERNAL LIGHT RL6 LR>25	12875009	LIGHT P.I. RL6 SURVITEC 4000MM
Z68106	BATTERY RL6 RIBO	80913820	BATTERY RL6 + LINE RIBO

5. Necessary equipment and tools

None required.

6. Tasks

- A. Obey the correct service manual to service, test and pack the liferaft.
- B. You can use existing stock of each current part number. It does not need to be removed from liferafts unless it is unserviceable (for instance, it is damaged or its date of expiry is before next scheduled liferaft service).
- C. If you need to replace anti-seasickness tablets, you must order the new part number (refer to 4.A.)
- D. If you need to replace a first aid kit, you must order the new part number (refer to 4.B.)
- E. If you need to replace a light or battery, you must order the new part number (refer to 4.C.)

7. Recording

- A. For each liferaft to which this service bulletin has been applied, complete the appropriate record card(s).
 - (1) Record details of the service onto the service record card. In the appropriate field, write "SB 12/24 Ver.1 APPLIED".

8. Reporting

- A. None required.

Marine liferafts — Spare parts : *Consolidation of multiple branded part numbers*

Service provider: _____

Associated Publications:

As part of Survitec procedures, each technician who is trained to service the equipment affected by this publication must read and fully understand this publication.

When each technician has read and fully understood the publication, they must complete and sign the table below.

Keep this table with this publication.

Each person named below has read and fully understood this publication: