

Rev0

Original Rev for Memco

Took T3-8I8O design rev14 and reworked it for PWM project

Rev5

Done:R56,R58丝印错误

Rev1

Done: fix mux select lines

Done: require a TXEN line for RS485 com, pin3.2

Done: remove 470 current limitting resistors

Done: flip D33

Done: output feedback to pic should come from 5V side of OPamp

Done: One pin of each "hand" potentiometer must be tied to GND.

Done: Each "hand" potentiometer must be tied to 12V not 5V

Done: Connect analog GND to INPUT page

Done: update footprint of packet resistors

Done: R18 and R22 to move for cpu socket

Done: Outputs out of order on PCB

Done: Make sure all thru-holes have thermal relief

Done: move D33 to make space for pic socket

Done: crystal footprint updated

Done: move IN_CPU2 to Port0 given the internal pull-ups may affect Analog input reads

Done: remove pull up on P0 lines

Rev2

Done: added diode to decrease 5V line for 485 module, it would overheat otherwise

Done: timing cap for power chip changed to 120pF to reduce noise

Done: changed jumper select to switches

Done: changed the resistance for power to 1.89 and 5.96 for the 5V supply

Rev3

Done: rectify connection with Input Con. Was mis-labelled

Done: change cap by op-amp to 10uF. 100uF too slow

Done: fix footprint of switches

TBD: rectify footprint names of 2N2222, Q1, Q2 for BOM purposes

Slick Screen on Board was mislabelled. Still reads Rev2

note: make sure muxes are phillips brand. Does not

work with Texas chips

Tiel -						
Title	<title></th><th></th><th></th><th></th><th></th><th></th></tr><tr><th>Size</th><th>Document Number</th><th></th><th></th><th></th><th></th><th>Rev</th></tr><tr><td>В</td><td><Doc></td><td></td><td></td><td></td><td></td><td><R</td></tr><tr><td>Date:</td><td>Monday April 13 2015</td><td>Sheet</td><td>-1</td><td>of</td><td>-1</td><td>-</td></tr></tbody></table></title>					





