


Metrics for Rectangular Region

- Confidence area
- Rectangular Confidence Region
- ε_A
- ε_B
- True Parameters θ
- + Estimate $\hat{\theta}_{rect}$



Parameter a