


Metrics for Rectangular Region

- Rectangular Confidence Region
- $\Delta A_{\max} = \varepsilon_A$
- $\Delta B_{\max} = \varepsilon_B$
- d_{\max}
- True Parameters θ
- Estimate $\hat{\theta}_{rect}$



Parameter a