Zero Detection

O Created	@October 29, 2024 3:08 PM
<u>≔</u> Tags	
Status	Not started

Input Vector (31 bits)	Expected zero_flag
"0000000000000000000000000000000000" (all zeros)	1
"0000000000000000000000000000000000000	0
"111111111111111111111111111" (all ones)	0
"0000000000000000000000000000000000000	0
"0000000000000000000000000000000000" (all zeros)	1

e.g. whenever input vector is not 0, output 1 to zero flag. else, output 0 to output flag.

Zero Detection 1