

Assembly drawing, top (F.Cu, face side)

ODD JOBS

design-as-code: hardware/mao/design