	 									 		 		 		i I I I I	Heatsink Drill Template All tap for M3 or 4-40 Remove drill and tap burrs using fine sandpaper to prevent contact with transistor				
	 	 	-		 		Bias S	 	 	 	 	 	TO-22 Bias S (Split	0/126 ervo Block)		 		 		 	
		 4/247 	TO-26	4/247	TO-26	 64/247)	TO-26	TO:	+ -220/ (Con	- - + /12β nmq (Bia Bia n Bla	S Serv	TO-2	64/247	TO-26	— — - 4/247 — — -	TO-2	64/247	TO-26	64/247 6	+
	 		, 		7 			TO-2: Drive		26 26 - 	TO _t I I	220/1 Driv							\ - 		
PCB hole	Mounting	 	 - - -		 - 		- — — 		 	 	 		- — — —		 	 			 - 	PCB Mo	unting
DCB /	l 		 		 				 	 	 				 		 		 		I
hole	1ounting	 	i I I I		i I L I I		 		 	. <u> </u> - - -	 - - 		 		 <u>-</u> 		i 		 <u> </u> 	hole	punting