

33 plans/s, every arm with 6 seeds
1.0
0.5
0.0
Success rate
falls backward
at the lean onset
falls in the stand
3
5
10
20
50
Executed step per plan in the lean rung (mrad RMS over 27 joints)
elite mean
softmax
argmin