

Table 66. WLCSP15 - Mechanical data

Symbol	millimeters			inches ⁽¹⁾		
	Min	Typ	Max	Min	Typ	Max
A ⁽²⁾	-	-	0.60	-	-	0.0236
A1 ⁽³⁾	0.12	-	-	0.0047	-	-
A2	-	0.38	-	-	0.0150	-
A3	-	0.025	-	-	0.0010	-
b ⁽⁴⁾	0.19	0.23	0.26	0.0075	0.0091	0.0102
D ⁽⁵⁾	2.25 BSC			0.0886 BSC		
D1 ⁽⁵⁾	1.58 BSC			0.0622 BSC		
E ⁽⁵⁾	1.40 BSC			0.0551 BSC		
E1 ⁽⁵⁾	0.61 BSC			0.0240 BSC		
eD ⁽⁵⁾⁽⁶⁾	0.35 BSC			0.0138 BSC		
eE ⁽⁵⁾⁽⁶⁾	0.61 BSC			0.0240 BSC		
eS ⁽⁵⁾⁽⁶⁾	0.35 BSC			0.0138 BSC		
N ⁽⁷⁾	15					
SD ⁽⁵⁾⁽⁸⁾	0.26 BSC			0.0102 BSC		
SE ⁽⁵⁾⁽⁸⁾	0.30 BSC			0.0118 BSC		
aaa ⁽⁹⁾	0.02			0.0008		
bbb ⁽⁹⁾	0.06			0.0024		
ccc ⁽⁹⁾	0.03			0.0012		
ddd ⁽⁹⁾	0.015			0.0006		

1. Values in inches are converted from mm and rounded to 4 decimal digits.
2. The profile height A is the distance from the seating plane to the highest point on the package. It is measured perpendicular to the seating plane.
3. A1 is defined as the distance from the seating plane to the lowest point on the package body.
4. Dimension b is measured at the maximum diameter of the terminal (ball) in a plane parallel to Datum C.
5. BSC stands for BASIC dimensions. It corresponds to the nominal value and has no tolerance. For tolerances, refer to form and position table. On the drawing, these dimensions are framed. For the tolerances, refer to form and position values.
6. e represents the solder balls grid pitch(es).
7. N represents the total number of balls.
8. Basic dimensions SD & SE are defining the ball matrix position with respect to datums A and B.
9. Tolerance of form and position drawing.