



[illegible]



Missing Data Rate Heatmap (Actual Column Names)



The step plot illustrates the cumulative effect of adding variables to a model. The x-axis, labeled 'Variables', lists the variables in the order they were added: FM, MeanV, Density, Blain, HG, AG, DG, Gyp_per, and WC_per. The y-axis represents a metric, ranging from 0.00 to 0.10. The plot shows a step-wise increase in the metric as variables are added, with a significant jump between DG and Gyp_per.

Variables	Value
FM	0.01
MeanV	0.02
Density	0.03
Blain	0.04
HG	0.05
AG	0.05
DG	0.05
Gyp_per	0.07
WC_per	0.08

FALSE

☒ TRUE

Missing Data Summary Statistics (Actual Column Names)

