Device Tag	Pin	Signal Name / Function	PLC Address	Wire Number
security button	x1	24 V input (from power)	—	W13
	x2	PLC.I0.0	I0.0	W15
maintenance switc	x1	24 V input (from power)	—	W14
	x2	PLC.I0.1	I0.1	W16
maintenance buttc	x1	24 V input (from power)	—	W22
	x2	PLC.I0.2	I0.2	W23
maintenance buttc	x1	24 V input (from power)	—	W24
	x2	PLC.I0.3	I0.3	W25
maintenance buttc	x1	24 V input (from power)	—	W26
	x2	PLC.I0.4	I0.4	W27
maintenance buttc	x1	24 V input (from power)	—	W28
	x2	PLC.I0.5	I0.5	W29
maintenance buttc	x1	24 V input (from power)	—	W30
	x2	PLC.I0.6	I0.6	W31
B1 (Balance1)	x1	Sensor +24 V supply	—	W7
	x2	Sensor 0 V (return)	—	W8
	x3	Weight Output Signal → PLC	AI0.0	W9
B2 (Balance2)	x1	Sensor +24 V supply	—	W10
	x2	Sensor 0 V (return)	—	W11
	x3	Weight Output Signal → PLC	AI0.1	W12
LCD (Afficheur)	x1	24 V supply	—	W23
	x2	0 V return	—	W24
	COM	PLC MODBUS COM	COM	W22
	D+	PLC MODBUS D+	D+	W20
	D-	PLC MODBUS D-	D-	W21
H1 (Alarme)	x1	24 V supply	—	W2
	x2	Alarm Output → PLC control	Q0.0	W5
	x3	0V RETURN	__	W1
H2(alarme)	x1	24v suppy	__	W4
	x2	Alarm Output → PLC control	Q0.1	W6
	x3	0v return	__	W3
PLC	L	24 V input	—	W17
	N	0 V return	—	W18
	I0.0	security button	—	W16
	I0.1	maintenance switch	—	W15
	I0.2	maintenance button1	—	W23
	I0.3	maintenance button2	—	W25
	I0.4	maintenance button3	—	W27
	I0.5	maintenance button4	—	W29
	I0.6	maintenance button5	—	W31
	AI0.0	Balance1 weight input	—	W12
	AI0.1	Balance2 weight input	—	W9
	Q0.0	Alarm1 output control	—	W6
	Q0.1	Alarm2 output control	—	W5
	COM	LCD COM	—	W22
	D+	LCD D+	—	W20
	D-	LCD D-	—	W21