Innovative Embedded Systems
Halt Report : AP 02 UD 8791 -Route patrol 3 (862170010565487)-Interval:15 mins

| SNo   | Place  | ArrivalTime         | DepartureTime       | Duration of Halt (hr.min) | Latitude/Longitude |
|-------|--|---------------------|---------------------|---------------------------|--------------------|
| 1     | 0.2 km from Kanyakumari Road<br>Sirivaram Andhra Pradesh<br>515731 India                             | 2015-08-08 01:01:31 | 2015-08-08 01:18:46 | 00:17:15                  | 14.86135/77.59298  |
| 2     | 0.03 km from Bangalore-<br>Hyderabad Highway Neeluru<br>Andhra Pradesh 515775 India                  | 2015-08-08 02:20:09 | 2015-08-08 02:39:33 | 00:19:24                  | 14.9686/77.60108   |
| 3     | 0.08 km from Bangalore-<br>Hyderabad Highway Pamidi<br>Andhra Pradesh 515775 India                   | 2015-08-08 02:41:33 | 2015-08-08 02:57:17 | 00:15:44                  | 14.96193/77.5982   |
| 4     | 0.01 km from Bangalore-<br>Hyderabad Highway Andhra<br>Pradesh 515775 India                          | 2015-08-08 05:37:41 | 2015-08-08 06:04:24 | 00:26:43                  | 14.98634/77.60861  |
| 5     | 0.28 km from Bangalore-<br>Hyderabad Highway<br>Ramarajupalle Andhra Pradesh<br>515405 India         | 2015-08-08 06:23:26 | 2015-08-08 06:59:55 | 00:36:29                  | 15.06187/77.63005  |
| 6     | 0.03 km from Kanyakumari<br>Road Neeluru Andhra Pradesh<br>515775 India                              | 2015-08-08 09:49:03 | 2015-08-08 10:07:27 | 00:18:24                  | 14.96863/77.60102  |
| 7     | 0.01 km from Kanyakumari<br>Road Priyanka Nagar<br>Anantapur Andhra Pradesh<br>515001 India          | 2015-08-08 12:46:58 | 2015-08-08 13:11:33 | 00:24:35                  | 14.70269/77.59165  |
| 8     | 0.13 km from Kanyakumari<br>Road Govindapalle Andhra<br>Pradesh 515001 India                         | 2015-08-08 13:28:59 | 2015-08-08 14:01:04 | 00:32:05                  | 14.73251/77.6061   |
| 9     | 0.12 km from Kanyakumari<br>Road Andhra Pradesh 515731<br>India                                      | 2015-08-08 15:47:29 | 2015-08-08 16:04:25 | 00:16:56                  | 14.76871/77.59971  |
| 10    | 0.27 km from Service Road<br>Srinagar Colony Anantapur<br>Andhra Pradesh 515002 India                | 2015-08-08 18:17:56 | 2015-08-08 18:33:38 | 00:15:42                  | 14.66328/77.58334  |
| 11    | 0.25 km from 10 Subash Road<br>Adimurthy Nagar Gulzarpet<br>Anantapur Andhra Pradesh<br>515001 India | 2015-08-08 18:51:40 | 2015-08-08 19:09:18 | 00:17:38                  | 14.67928/77.59966  |
| 12    | 0.01 km from Service Road<br>Anantapur Andhra Pradesh<br>515002 India                                | 2015-08-08 19:38:06 | 2015-08-08 19:55:35 | 00:17:29                  | 14.65091/77.58171  |
| 13    | 0.07 km from Bangalore-<br>Hyderabad Highway Garladinne<br>Andhra Pradesh 515731 India               | 2015-08-08 21:17:40 | 2015-08-08 21:48:39 | 00:30:59                  | 14.81153/77.59852  |
| 14    | 0 km from Kanyakumari Road<br>Lolur Andhra Pradesh 515731<br>India                                   | 2015-08-08 21:52:56 | 2015-08-08 22:39:30 | 00:46:34                  | 14.80574/77.59837  |
| 15    | 0.15 km from Kanyakumari<br>Road Andhra Pradesh 515731<br>India                                      | 2015-08-08 23:51:46 | 2015-08-08 23:59:58 | 00:08:12                  | 14.89582/77.58576  |
| Total | 2015-08-08 00:00:00  |                     | 2015-08-08 11:59:00 | 05:44:09                  |                    |