### **USB4 1.0 ENGINEERING CHANGE NOTICE FORM**

**Title: CL0s Exit Latency Change** 

**Applied to: USB4 Specification Version 1.0** Brief description of the functional changes: Updates the CL0s exit latency to account for a change to the Re-timer timing requirement in the USB4 Re-Timer Specification. Benefits as a result of the changes: Matches the Re-timer specification. An assessment of the impact to the existing revision and systems that currently conform to the USB specification: None An analysis of the hardware implications: None An analysis of the software implications: None An analysis of the compliance testing implications: None

## **USB4 1.0 ENGINEERING CHANGE NOTICE FORM**

# **Actual Change**

# (a). 4.2.1.6.5.1Exit flow from CL0s state, Page 160

#### **From Text:**

In order to limit the CL0s exit time to  $230\mu s$ , a Router shall comply with the following equation:

### To Text:

In order to limit the CL0s exit time to  $\frac{230245}{\mu}\mu$ s, a Router shall comply with the following equation: